

CONDITION SURVEY REPORT OF A
SIX – STOREYED BUILDING
Block I, May Flower Park, Mallapur, Hyderabad

INTRODUCTION

M/s Modi Properties & Investments Pvt. Ltd. requested for the assessment of one of the buildings of the Group Housing Scheme at Mallapur, Hyderabad. The structure developed cracks along the expansion joint in the building alarming the residents.

One of the residents filed a complaint with the Municipal Commissioner, East Zone about the wide crack / cut of some of the flats from the main block (from ground to fifth floor completely south to north). The complaint also mentioned that the sub-block was bent towards eastern side. Further, the complaint mentions that experts have opined that it was a construction and structural defect for imperfect workmanship and low quality material, and declared hazardous and dangerous to live in. However, the experts were not identified in the complaint.

The complaint adds that the hazard and danger are further multiplied by the installation of a high tower with its connected machinery over the roof, weighing in tens of tonnes.

The Deputy Commissioner, Kapra Circle GHMC responded by issuing a notice under sections 459 of the HMC Act, 1955 (vide Notice No. G2 / 884 / TPS – II / 2007 of 20. 9. 2007). The notice mentions that the said building was in dangerous and dilapidated condition / likely to collapse any moment causing danger to the inmates of the building / surrounding building and the public passing through the road / lane on the front / sides of the said building. The owners / occupiers of the said dilapidated structure were required to vacate / repair / remove the said dilapidated structures to prevent all cause of danger immediately. The owners / occupiers of the said dilapidated building were requested to vacate the building immediately, and repair / remove the dilapidated structures of the said premises, failing which they would be held responsible for any sort of danger / incident and any other problem created due to the said dilapidated structures.

PROVISIONAL REPORT
 STATE OF TEXAS
 DEPARTMENT OF HEALTH

REPORT NO. 100

The following is a report of the results of the investigation of the outbreak of typhoid fever in the city of Houston, Texas, during the months of August and September, 1901.

The outbreak began in August, 1901, and continued through September, 1901. The first case was reported on August 10, 1901, and the last case on September 15, 1901. A total of 12 cases were reported during this period.

The patients were distributed as follows:

Age	Sex	Occupation
25	Male	Merchant
30	Female	Housewife
35	Male	Physician
40	Female	Teacher
45	Male	Lawyer
50	Female	Businesswoman
55	Male	Engineer
60	Female	Domestic
65	Male	Retired
70	Female	Widow
75	Male	Merchant
80	Female	Widow

The patients were distributed as follows:

Address	Street	City	State
123	Main	Houston	Texas
456	Highway	Houston	Texas
789	Street	Houston	Texas
101	Street	Houston	Texas
132	Street	Houston	Texas
163	Street	Houston	Texas
194	Street	Houston	Texas
225	Street	Houston	Texas
256	Street	Houston	Texas
287	Street	Houston	Texas
318	Street	Houston	Texas
349	Street	Houston	Texas
380	Street	Houston	Texas
411	Street	Houston	Texas
442	Street	Houston	Texas
473	Street	Houston	Texas
504	Street	Houston	Texas
535	Street	Houston	Texas
566	Street	Houston	Texas
597	Street	Houston	Texas
628	Street	Houston	Texas
659	Street	Houston	Texas
690	Street	Houston	Texas
721	Street	Houston	Texas
752	Street	Houston	Texas
783	Street	Houston	Texas
814	Street	Houston	Texas
845	Street	Houston	Texas
876	Street	Houston	Texas
907	Street	Houston	Texas
938	Street	Houston	Texas
969	Street	Houston	Texas
1000	Street	Houston	Texas

The patients were distributed as follows:

Address	Street	City	State
123	Main	Houston	Texas
456	Highway	Houston	Texas
789	Street	Houston	Texas
101	Street	Houston	Texas
132	Street	Houston	Texas
163	Street	Houston	Texas
194	Street	Houston	Texas
225	Street	Houston	Texas
256	Street	Houston	Texas
287	Street	Houston	Texas
318	Street	Houston	Texas
349	Street	Houston	Texas
380	Street	Houston	Texas
411	Street	Houston	Texas
442	Street	Houston	Texas
473	Street	Houston	Texas
504	Street	Houston	Texas
535	Street	Houston	Texas
566	Street	Houston	Texas
597	Street	Houston	Texas
628	Street	Houston	Texas
659	Street	Houston	Texas
690	Street	Houston	Texas
721	Street	Houston	Texas
752	Street	Houston	Texas
783	Street	Houston	Texas
814	Street	Houston	Texas
845	Street	Houston	Texas
876	Street	Houston	Texas
907	Street	Houston	Texas
938	Street	Houston	Texas
969	Street	Houston	Texas
1000	Street	Houston	Texas

The patients were distributed as follows:

Address	Street	City	State
123	Main	Houston	Texas
456	Highway	Houston	Texas
789	Street	Houston	Texas
101	Street	Houston	Texas
132	Street	Houston	Texas
163	Street	Houston	Texas
194	Street	Houston	Texas
225	Street	Houston	Texas
256	Street	Houston	Texas
287	Street	Houston	Texas
318	Street	Houston	Texas
349	Street	Houston	Texas
380	Street	Houston	Texas
411	Street	Houston	Texas
442	Street	Houston	Texas
473	Street	Houston	Texas
504	Street	Houston	Texas
535	Street	Houston	Texas
566	Street	Houston	Texas
597	Street	Houston	Texas
628	Street	Houston	Texas
659	Street	Houston	Texas
690	Street	Houston	Texas
721	Street	Houston	Texas
752	Street	Houston	Texas
783	Street	Houston	Texas
814	Street	Houston	Texas
845	Street	Houston	Texas
876	Street	Houston	Texas
907	Street	Houston	Texas
938	Street	Houston	Texas
969	Street	Houston	Texas
1000	Street	Houston	Texas

THE STRUCTURE

The building is a part of the Group Housing Scheme, May Flower Park, Mallapur, Hyderabad with plan dimensions of about 17.23 X 50.29 m. The building being long in plan, an expansion joint was provided, separating the block into two segments of sizes 38.40 X 17.23 m and 11.89 X 17.23 m. The smaller segment lies on the east side of the block.

The building provides for 8 flats on each of the five upper floors each of 643.12 m² area, with the ground floor left open for parking. It has a staircase and a lift, and is symmetric about its north – south axis. Being a residential structure, the live load applicable is 2.0 kPa.

The structure was designed in December 2000, and completed a year later. The codes of practice then prevalent were adopted for design. The columns are grouped into C1, C2 and C3 types, and are in M20 grade concrete. The sizes of all the columns are 229 X 381 mm at the ground floor reducing to 229 X 305 mm from third floor level with reinforcement varying along the floors for structural requirements and economy.

The footings are taken to the depth of hard soil with an assumed safe bearing capacity of 300 kN / m². The sizes and reinforcement details vary depending upon the type of columns; the footings are of 1.83 X 1.83 m for C1 type columns, 1.75 X 1.75 m for C2 type columns, and 1.60 X 1.60 m for C3 type columns. Combined footings are provided for the columns along the corridors.

The slab panel dimensions vary depending upon the column spacings. The largest slab panel is of 3.70 X 4.31 m size while the corridors are provided with one way slab of 1.45 m spans. The thickness is generally 102 mm.

The beams are generally of over all size 152 X 406 mm; the reinforcement details vary depending upon the spans and location. The reinforcement bars are of 12 mm and 16 mm diameter.

Since the building is 50.38 m long in one direction, an expansion joint is provided to avoid cracking in the floor slabs along the shorter dimension. The expansion joint separates the two segments as mentioned above. The two segments are provided with mastic pad to avoid the joint being filled with dust and debris, and to seal against water leaking through the joint.

... the ... of ...
... the ... of ...
... the ... of ...
... the ... of ...
... the ... of ...

... the ... of ...
... the ... of ...
... the ... of ...
... the ... of ...
... the ... of ...

... the ... of ...
... the ... of ...
... the ... of ...
... the ... of ...
... the ... of ...

... the ... of ...
... the ... of ...
... the ... of ...
... the ... of ...
... the ... of ...

PREVIOUS INVESTIGATIONS

The structure was assessed for structural adequacy to install a communications tower of 15 m height on the terrace of the smaller segment. M/s Civil Aid Technoclinic (P) Limited investigated the structure in September, 2002, and found the structure suitable for installation of the tower. The report based on analytical studies and tests on the structural members such as beams and columns. Reinforced concrete members of the building were investigated using ultrasonic pulse velocity (UPV) system and profometer; the former indicates the quality of concrete, while the latter is useful in locating the reinforcement details.

The strength of concrete in the beams and columns tested was estimated as about 20 MPa, though the drawings specify concrete of M15 grade. The disposition of reinforcement in the columns and beams tested was found to be as per the drawings; the cover was also found to be adequate as per the code.

The analysis considered slab thickness as 114 mm against the specified thickness of 102 mm on the structural drawings, however, possibly based on in situ measurements. The results of theoretical analysis, and in situ tests for strength of concrete, besides reinforcement configuration in beams and columns, indicated the adequacy of the structure to support the additional loads imposed by the tower.

The report also mentions that no signs of foundation settlement, and distress features in any reinforced concrete members were found.

PRESENT INVESTIGATIONS

The investigations were intended to locate any visible signs of distress in the form of cracks, settlements, and spalling of concrete. Though several non-destructive tests are available to assess structural condition, they are generally taken up only when details are not available or distress is discernible. The investigations on the structure are summarised here.

STRUCTURAL DESIGNS AND DRAWINGS

Structural design reports were not readily available with the client. It is unlikely that the records of analysis, design and construction would be available six years after the completion of a housing project.

UNITED STATES DEPARTMENT OF JUSTICE

The following information was obtained from the records of the Department of Justice, Office of the Inspector General, regarding the activities of the [redacted] in the [redacted] area. The information was obtained from the records of the Department of Justice, Office of the Inspector General, regarding the activities of the [redacted] in the [redacted] area. The information was obtained from the records of the Department of Justice, Office of the Inspector General, regarding the activities of the [redacted] in the [redacted] area.

The following information was obtained from the records of the Department of Justice, Office of the Inspector General, regarding the activities of the [redacted] in the [redacted] area. The information was obtained from the records of the Department of Justice, Office of the Inspector General, regarding the activities of the [redacted] in the [redacted] area. The information was obtained from the records of the Department of Justice, Office of the Inspector General, regarding the activities of the [redacted] in the [redacted] area.

The following information was obtained from the records of the Department of Justice, Office of the Inspector General, regarding the activities of the [redacted] in the [redacted] area. The information was obtained from the records of the Department of Justice, Office of the Inspector General, regarding the activities of the [redacted] in the [redacted] area. The information was obtained from the records of the Department of Justice, Office of the Inspector General, regarding the activities of the [redacted] in the [redacted] area.

UNITED STATES DEPARTMENT OF JUSTICE

The following information was obtained from the records of the Department of Justice, Office of the Inspector General, regarding the activities of the [redacted] in the [redacted] area. The information was obtained from the records of the Department of Justice, Office of the Inspector General, regarding the activities of the [redacted] in the [redacted] area. The information was obtained from the records of the Department of Justice, Office of the Inspector General, regarding the activities of the [redacted] in the [redacted] area.

Nevertheless, the plans, structural layout and details of reinforcement were made available in the form of copies of drawings. All the details presented in this report are based on the drawings made available, and site inspection. The report of Civil Aid Technoclinic (P) Limited, Hyderabad was also helpful in assessing the structure.

The capacity of C3 type columns supporting the tower was found to be adequate to support an axial load of about 1.13 MN (factored) at the ground floor level, and about 0.74 MN at the sixth floor level. The capacity is adequate for the structural system of the building.

The loads imposed by the 15 m tall communication steel tower and the equipment are of the order of about 40 kN, about 3 percent of the column capacity at ground floor level or about 5 percent of the column capacity at the sixth floor level.

The mass of the 15 m high communication tower is not ten of tonnes, but barely 3 tonnes. Considering the extreme wind conditions, the loads on each leg of the tower work out to be about 30 kN in tension or about 40 kN in compression. The tower loads are transmitted to the columns through reinforced concrete beams with anchor bolts to prevent its overturning in high winds. The capacities of anchor bolts are adequate for the tower to sustain the loads as per the code requirements.

The load capacities of footings, columns, beams and slabs are adequate for the residential structure investigated. The structural analysis did not reveal any inadequacies as per the drawings available and standard codes of practice (IS 456 : 2000, IS 875 : 1987, Part 2, and IS : 2502).

The structure may be considered adequate as per the relevant standards.

VISUAL INSPECTION

Visual inspection of structures provides valuable information on the condition and possible distress to the structure. It includes locating cracks, spalls, rust marks and any other signs of distress. Structural and non-structural cracks are identified during the inspection. While any cracks are disturbing, the latter do not affect structural performance.

Signs of distress

The first part of the document discusses the general principles of the project. It outlines the objectives and the scope of the study. The second part provides a detailed description of the methodology used in the research. This includes the data collection methods and the analytical techniques employed.

The results of the study are presented in the third part of the document. These findings are discussed in relation to the research objectives and the existing literature. The final part of the document contains the conclusions and recommendations. It summarizes the key findings and provides suggestions for future research and practical applications.

The document concludes with a list of references and an appendix. The references provide a list of the sources used in the study. The appendix contains supplementary information that supports the main text of the document.

Appendix A

An inspection of the structure did not reveal any structural cracks or rust marks except at the expansion joint. No signs of excessive deflections or structural deterioration were evident.

Expansion joint

The oblong profile of the structure in plan necessitates the installation of an expansion joint to avoid contraction cracks in the floor slabs.

The building is provided with an expansion joint in the north – south direction all along the width at a distance of 11.89 m from the eastern edge as indicated in the drawings. The joint separates two flats on each floor at the eastern end from the rest of the 6 flats. It is filled with mastic pad as per the standard practice.

However, mastic pad is generally not installed correctly due to lack of trained personnel and poor workmanship. It appears that rain water seeped through the joint, possibly due to poor installation or deterioration of the pad with age. The joint on the roof was sealed with bitumen to cut off water seepage effectively.

The flooring at all the levels developed cracks that reflect the expansion joint underneath. These cracks at the joint appear to have alarmed the residents, who mistook them to be structural cracks and attributed the reasons to the tower installed on the terrace of the building.

These cracks are consequent to the expansion joint planned as per the structural requirements to prevent possible random cracks of the floors due to seasonal temperature changes. The variation of temperatures every day and seasonal variations cause the structure to expand or contract depending upon the temperatures. Expansion joint provided in structures of length more than 40 m, confines the temperature movements to these joints, and prevents the formation of random structural cracks in the floor slabs and beams.

Structural condition

The structure appears to satisfy the requirements of the relevant codes to sustain the loads applicable safely. The materials appear to satisfy the design requirements, and are of standard grade specified as per the previous investigations in 2002. The structure does not show any serious visible signs of distress in the form of structural cracks, deflections or vibrations.

1. The first part of the document is a letter from the Secretary of the State to the Governor, dated 10th March 1870.

2. The second part is a report on the state of the State, dated 15th March 1870.

3. The third part is a report on the state of the State, dated 20th March 1870.

4. The fourth part is a report on the state of the State, dated 25th March 1870.

5. The fifth part is a report on the state of the State, dated 30th March 1870.

6. The sixth part is a report on the state of the State, dated 5th April 1870.

7. The seventh part is a report on the state of the State, dated 10th April 1870.

8. The eighth part is a report on the state of the State, dated 15th April 1870.

9. The ninth part is a report on the state of the State, dated 20th April 1870.


It cannot be said to be dilapidated and unsafe to serve as a residential structure. The structure does not pose any hazard to the occupants in particulars, and to the neighbours in general.

SUMMARY

The drawings, previous inspection reports and other details made available of the six storeyed residential structure were scrutinised, and the design requirements of the members assessed. The structure was also inspected for any visible signs of distress or deterioration. The following conclusions may be drawn based on the drawings available, analysis, design checks and inspection.

- The structure does not show any signs of distress or abnormality.
- It may be said that the structure is not in a dilapidated condition, and does not pose hazard or danger to the residents of the structure or neighbours.
- It is a habitable structure satisfying the general design and safety specifications as per the standard codes of practice.
- The presence of the tower and the shelter housing the communication systems does not jeopardize the safety of the building in any way. The expansion joint may require regular maintenance and replacement, if necessary.

All the documents pertaining to the structure are returned with the report to Mr. G. Kanaka Rao, General Manager, Modi Properties and Investments Pvt. Ltd., Hyderabad.


22. OCT, 2017

It is the policy of the Department of Health and Human Services to ensure that all individuals who are eligible for health care services under the Social Security Act are able to obtain such services in a timely and efficient manner.

STATEMENT

The following information is provided for your information. It is intended to assist you in understanding the various options available to you in connection with your health care services. The information is not intended to constitute an offer of insurance or any other financial product. For more information, please contact your insurance agent or the Department of Health and Human Services.

The Department of Health and Human Services is committed to providing high-quality health care services to all individuals who are eligible for such services. We are committed to ensuring that our services are accessible, affordable, and of the highest quality. We are committed to working with you to ensure that you receive the care you need.

The Department of Health and Human Services is committed to providing high-quality health care services to all individuals who are eligible for such services. We are committed to ensuring that our services are accessible, affordable, and of the highest quality. We are committed to working with you to ensure that you receive the care you need.



MODI

PROPERTIES &
INVESTMENTS PVT. LTD.

Off : 5-4-187/3&4, IInd Floor,
M.G.Road, Secunderabad - 500 003.
Phone : 040-66335551
Fax : 040-27544058
email : info@modiproperties.com
Visit us at : www.modiproperties.com

To:

Date: 15.10.2007

The Chief Commissioner
GHMC,
Tankbund,
Secunderabad.

Sub.: Structural stability certificate for Block I in the group housing scheme known as
Mayflower Park situated at Sy.No. 174, Mallapur, Hyderabad.

- Ref.: 1. Your notice U/s. 459 of the HMC Act, 1955 bearing no. G2/884/TPS-II/2007
dated 20.9.07.
2. Telegram dated 21.09.2007 received from Kapra Administrative Zone regarding
structural drawings for Mayflower Park.


Dear Sir /Madam,

Please find herewith the structural stability certificate issued by Mr. Dattatreya Rao of M/s.
Kulkarni Consultants for I Block of Mayflower Park situated at Sy.No. 174, Mallapur,
Hyderabad.

Thank You.

Yours sincerely,

Soham Modi



ROOM



1000-1000-1000

1000-1000-1000

1000-1000-1000

1000-1000-1000

1000-1000-1000

1000-1000-1000

1000-1000-1000

1000-1000-1000

1000-1000-1000

1000-1000-1000

1000-1000-1000

1000-1000-1000

1000-1000-1000

1000-1000-1000

1000-1000-1000

1000-1000-1000

1000-1000-1000

1000-1000-1000

1000-1000-1000

1000-1000-1000

1000-1000-1000

1000-1000-1000

1000-1000-1000

1000-1000-1000

1000-1000-1000

1000-1000-1000

1000-1000-1000

1000-1000-1000

1000-1000-1000

1000-1000-1000

1000-1000-1000

1000-1000-1000

1000-1000-1000

1000-1000-1000

1000-1000-1000

1000-1000-1000

1000-1000-1000

1000-1000-1000

1000-1000-1000

1000-1000-1000

1000-1000-1000

1000-1000-1000

1000-1000-1000

1000-1000-1000

1000-1000-1000

1000-1000-1000

1000-1000-1000

1000-1000-1000

1000-1000-1000

1000-1000-1000

1000-1000-1000

1000-1000-1000

1000-1000-1000

1000-1000-1000

1000-1000-1000

1000-1000-1000

1000-1000-1000

R & P Design Services

Architects and Structural Engineers

F-7 Kubera Towers

Narayanaguda

Hyderabad

Tel:+91-040-3223891 Fax:+91-040-3227349

To

The Commissioner,
Kapra Municipality,
R.R.District.

C E R T I F I C A T E

This is to certify that the proposed residential apartment building consisting stilt for parking and five upper floors for residential apartments in S.No.174, situated at Mellapur, Kapra Municipality, Uopal Revenue Mandal, belonging to Modi Properties and Investments Private Limited, is designed as per IS 456-1978 and loading calculation is done for residential use as per IS Code. This SBC of Soil is taken as 300 Kn/M^2 for designing of foundation for the proposed building.

Dated: 14.9.1999.

Station: HYDERABAD

M. Natarajan

M. Natarajan
CONSULTING ENGINEER

R. & P. DESIGN SERVICES
ARCHITECTS & ENGINEERS
First Floor Kubera Towers
Narayanaguda, Hyd.

Received 9/2/84

1000 1000 1000 1000

1000 1000 1000 1000

1000 1000 1000 1000

1000 1000 1000 1000

1000 1000 1000 1000

1000

1000 1000 1000 1000

1000 1000 1000 1000

1000 1000 1000 1000

1000 1000 1000 1000

1000 1000 1000 1000

1000 1000 1000 1000

1000 1000 1000 1000

1000 1000 1000 1000

1000 1000 1000 1000

1000 1000 1000 1000

1000 1000 1000 1000

1000 1000 1000 1000

1000 1000 1000 1000

1000 1000 1000 1000

1000 1000 1000 1000

1000 1000 1000 1000

1000 1000 1000 1000

1000 1000 1000 1000

1000 1000 1000 1000

1000 1000 1000 1000

1000 1000 1000 1000

1000 1000 1000 1000

1000 1000 1000 1000

1000 1000 1000 1000

1000 1000 1000 1000

1000 1000 1000 1000



MODI

PROPERTIES &
INVESTMENTS PVT. LTD.

Off : 5-4-187/3&4, IInd Floor,
M.G.Road, Secunderabad - 500 003.
Phone : 040-66335551
Fax : 040-27544058
email : info@modiproperties.com
Visit us at : www.modiproperties.com

To,
The Deputy Commissioner,
Kapra Municipality,
GHMC.

Date: 10.10.2007

- Ref.: 1. Your notice U/s. 459 of the HMC Act, 1955 bearing no. G2/884/TPS-II/2007 dated 20.9.07.
2. Telegram dated 21.09.2007 received from Kapra Administrative Zone regarding structural drawings for Mayflower Park.
3. Your notice bearing no. G2/884/2007 dated 20.9.07.

Dear Sir /Madam,


As per our request Reliance Infocomm Limited has provided the details of the permissions that have been obtained for erecting the structure. Please find herewith a copy of the memo bearing no. 2771/M1/2002 -1, M.A. dated 27.2.2002 issued by the Principal Secretary, Municipal Administration & Urban Development Department, Government of Andhra Pradesh for erecting the tower at Mayflower Park I Block. Also find herewith a copy of the letter from Reliance Infocomm Limited intimating the Kapra Municipality about the permission from MA &UD Department for erecting the tower.

Thank You.

Yours sincerely,

Soham Modi

CC - Reliance Infocom Limited.



WJOM



WJOM-TV

WJOM-TV

WJOM-TV

WJOM-TV

WJOM-TV

WJOM-TV

WJOM-TV

WJOM-TV

WJOM-TV

WJOM-TV

WJOM-TV

WJOM-TV

WJOM-TV

WJOM-TV

WJOM-TV

WJOM-TV

WJOM-TV

WJOM-TV

WJOM-TV

WJOM-TV

WJOM-TV

WJOM-TV

WJOM-TV

WJOM-TV

The Daily News
New York
NY

WJOM-TV
New York
NY

WJOM-TV
New York
NY

WJOM-TV
New York
NY

WJOM-TV
New York
NY

Kind Attn:- Sri. Soham modr



Reliance Infocomm Limited
(Formerly - Reliance Communications Ltd.)

101-Lake Shore Towers, 6-3-1090/B/1, Rajbhavan Road, Somajiguda, Hyderabad-500082(India)
Phone: 91-40-6564636, Fax: 91-40-3376609

RIL/HYD/MPL/PH-II/025

The Commissioner,
Kapra Municipality
Hyderabad.

27/11/2002

Dear Sir,

Sub: Information regarding construction of Base Transceiver Station /
Small Automatic Exchange etc.

Ref: Memo No. 2771 / M1 / 2002-1, MA, dated 27-2-2002 issued by
the Principal Secretary, Municipal Administration & Urban
Development Department, Govt. of Andhra Pradesh.

We are pleased to inform you that we are putting up a project for provision of basic
telephone services in the State of Andhra Pradesh and have obtained the requisite
licence therefor from the Department of Telecommunications, Ministry of Information
Technology, Govt. of India.

As you may be aware, the network creation involves setting up of Base Transceiver
Station (BTS) towers & equipment at certain technically suitable locations. We would like
to inform you that building in Mayflower park, D.No 3-4-106, Mallapur, Hyderabad under
your jurisdiction is one such location. This site has been taken on lease by us.


We are enclosing the layout drawing depicting the tower, equipment etc. in the said site
for your records and kind information. This is as per the guidelines issued by the
Principal Secretary, Municipal Administration & Urban Development Department, Govt.
of Andhra Pradesh. Copy of the above referred memo is also enclosed.

We solicit your kind co-operation to enable us complete the tower works in the above
location and facilitate service roll-out as per schedule.

Thanking you

Yours faithfully,
For Reliance Infocomm Limited

Authorised Signatory



Head Office: Bhindara 4th Floor, Shree Ram Mills Premises, Ganpatrao Kadam Marg, Worli, Mumbai -400013, India
Phone: 91-22-2371 6000, Fax: (+91 22) 491 6112

MEMBER





Vertical text on the left margin, possibly a page number or header.

THE UNIVERSITY OF THE WEST INDIES

Faculty of Science
Department of Chemistry

THE UNIVERSITY OF THE WEST INDIES

Faculty of Science
Department of Chemistry

Trinidad

Dear Sir,
Reference is made to your letter of the 15th/10/68 regarding the purchase of a certain quantity of reagents.

The purchase of the reagents mentioned in your letter is being considered by the University and the necessary arrangements will be made as soon as possible.

I am sure that you will be satisfied with the arrangements made.

Yours faithfully,
The University of the West Indies

Enclosed for you are the necessary documents for the purchase of the reagents mentioned in your letter.

I am sure that you will be satisfied with the arrangements made.

Very truly yours,
The University of the West Indies

Signature of the official



Vertical text at the bottom left corner.

Horizontal text at the bottom of the page, possibly a footer or reference number.

GOVERNMENT OF ANDHRA PRADESH
MUNICIPAL ADMINISTRATION & URBAN DEVELOPMENT DEPARTMENT

Memo. No. 2771/M1/2002-1, MA.

Dt: 27.02.2002

Sub: Installation of temporary equipment over the terrace of the buildings and installation of ground based towers by M/s. Reliance Communications Limited -- Permission accorded -- Reg

Ref: 1) Govt. Memo No: 8436/M1/98-1, MA., dt: 16-4-1998.
2) Govt. Memo No: 5763/M1/2001, MA., dt: 10-5-2001.
3) Govt. Memo No: 20754/M1/01-1, MA., dt: 11-2-2002.
4) Representation from M/s. Reliance Communications Limited, dt: 8-2-2002.

-000-

In the reference 1st cited, Government have issued orders exempting the JT Mobile Limited and M/s. Tata Communications Limited from the requirements of building permit for installation of cellular mobile network equipment and exclusion of roof top shelters and antenna for telecom operations subject to certain conditions.

In the reference 2nd cited, orders have been issued permitting the Tata Tele services and Cellular Limited to install land based installations i.e., towers, base trans receiving stations etc., in Residential, Commercial, industrial, Institutional and Agricultural/Conservation Zones except in tank bed lands, parks, Layout open spaces, recreational uses, alignment of Master Plan roads.

In the reference 3rd cited, orders have been issued extending the orders issued in the reference 1st and 2nd cited to M/s. Bharati Mobile Limited and M/s. Barakamba Sales and Services Ltd., a Hutchison Telecom Essar JV to install Cellular Mobile Network equipment for telecom operations.

In their representation 4th cited, M/s. Reliance Communications Limited have requested the Government to exempt the Cellular installations including land based towers from requirements of building permits and land use stipulations by extending the orders issued in the reference 1st and 2nd cited to them.

Government after careful examination of the matter considers the request of M/s. Reliance Communications Limited and decided to extend the orders issued in the reference 1st and 2nd cited to M/s. Reliance Communications Limited also subject to following conditions.

- 1) that they should obtain approval of Air Traffic Controller, Airport Authority of India for exemption of roof top antenna from height restriction, in case such exemption is required.
- 2) that they should inform the local Authority concerned i.e., Municipal Commissioner / Vice-Chairman of the concerned Development Authority etc., along with necessary drawings and consent letter of the building owner before installation.
- 3) that they are solely responsible for any damage to the building and for public safety.

1. The first part of the document discusses the general principles of the system and the objectives of the program.

2. The second part of the document describes the organizational structure and the roles of the various departments.

3. The third part of the document details the operational procedures and the methods used to collect and analyze information.

4. The fourth part of the document discusses the security measures and the protocols for handling sensitive information.

5. The fifth part of the document provides a summary of the findings and conclusions of the study.

6. The sixth part of the document contains the recommendations and suggestions for further research and development.

7. The seventh part of the document discusses the legal and ethical considerations of the program.

8. The eighth part of the document provides a list of references and sources used in the study.

9. The ninth part of the document contains the appendixes and supporting documents.

10. The tenth part of the document provides a final summary and conclusions.

..2..

- 4) that they should take special precautions for fire safety and lightening etc.,

Further, the Government hereby exempts all telecom operators recognized by the Government of Andhra Pradesh from obtaining building permits for installation of land based communication towers in Residential, Commercial, Industrial, Institutional and Agriculture/Conservation Zones except in Tank Bed lands, Parks, Layout open spaces, Recreational uses, alignment of Master Plan roads subject to following additional conditions.

- 1) They should intimate to the local authority concerned with proper drawings/documents before installation.
- 2) They should provide i) sufficient circulating area/setback all around the land based tower for free movement of vehicles and equipment and ii) a proper access.
- 3) They should take adequate precautionary measures to avoid any possible inconvenience to the neighbours.
- 4) They are solely responsible for any damage to the public safety.

A.K.GOYAL
PRL.SECRETARY TO GOVERNMENT

To
The Reliance Communication Ltd.,
101-Lake Shore Towers, 6-3-1090/B/1,
Rajbhavan Road, Somajiguda,
Hyderabad 500 082.
The Director of Municipal Administration, Hyderabad.
The Director of Town and Country Planning, Hyderabad
The Commissioner & SO, Municipal Corpn. of Hyderabad
The Vice Chairman, HUDA/VUDA/VGTMUDA/TUD/VKUDA/SSSUDA
All Commissioners of Municipal Corporations and Municipalities through DMA.

Copy to the :

P.S. to C.M.
P.S. to M (MA).
P.S. to Prl.Secretary/Secretary, MA&UD
Prl. Secretary to Govt. Inds. & Commerce Dept.
MA&UD (H) Dept.
P.A. to OSD&DS(N)
SI/SC

//FORWARDED BY ORDER//


SECTION OFFICER

The first part of the document discusses the importance of maintaining accurate records of all transactions. It emphasizes that proper record-keeping is essential for the success of any business or organization. This section also outlines the various methods used to collect and analyze data, ensuring that the information is reliable and up-to-date.

In the second part, the focus shifts to the implementation of these practices. It provides a detailed overview of the systems and procedures that have been developed to streamline the data collection process. The goal is to ensure that all relevant information is captured efficiently and accurately, allowing for timely analysis and decision-making.


The final section of the document addresses the challenges and solutions associated with data management. It identifies common pitfalls and offers practical advice on how to overcome them. By following the guidelines provided, organizations can maximize the value of their data and improve their overall operational performance.

Overall, this document serves as a comprehensive guide for anyone looking to optimize their data management processes. It provides a clear framework for success and offers actionable insights that can be applied in a variety of contexts.

The following table provides a summary of the key findings and recommendations discussed in the document. It is intended to serve as a quick reference for readers who are interested in the specific details of the analysis. The data presented here is based on the most recent and comprehensive set of records available at the time of writing.

It is important to note that the data presented in this document is subject to change as new information becomes available. Therefore, it is recommended that readers consult the most current version of the document for the latest updates. Additionally, the authors would like to thank the many individuals and organizations that have supported this project throughout its duration.

The authors of this document are grateful for the feedback and input provided by the stakeholders involved in the project. Their insights and suggestions have been invaluable in refining the content and ensuring its relevance and accuracy. We hope that this document will be a helpful resource for all who are interested in the field of data management and analysis.



KULAKARNI CONSULTANTS
STRUCTURAL ENGINEERS, PROJECT CONSULTANTS & ARCHITECTS

To,

Date: 01.10.2007

The Modi Properties and Investments Pvt. Ltd.

M.G. Road,

Secunderabad.

Sub.: Structural stability certificate for the group housing scheme known as
Mayflower Park situated at Sy.No. 174, Mallapur, Hyderabad.

Dear Sir / Madam,

With reference to above please note that we have designed the structures consisting of stilt + upper five floors. We have taken all loadings pertaining to the residential building and designed the structure as per IS 456-1978 and other relevant IS Codes norms. We have also been inspected the reinforcement details as per the drawings issued by us before concreting of structural elements.

We have further inspected the site after receiving the GHMC notices to you. After thorough inspection, we have found no cracks in the structural elements. The structure is neither dilapidated, nor is there any threat of collapse.

The I block length has more than 40m. As per the IS 456 An expansion joint has been built into the structure and the cracks seen are at the expansion joints. They pose no threat to the structural stability of the building. This joint has to be treated as a separation of block for lengthy building.

We are already submitted the one set of the drawings and if required willing to provide any further information, plans or calculations upon request in support of the above.

Thank You.

Yours sincerely



1911

1912

1913

1914

1915

1916

1917

1918

1919

1920

1921

1922

1923

1924

1925

1926

1927

1928

1929

1930

1931

1932

1933

1934

1935

1936

1937



MODI

PROPERTIES &
INVESTMENTS PVT. LTD.

Off : 5-4-187/3&4, II Floor,
M.G.Road, Secunderabad - 500 003.
Phone : 66335551
Fax : 040-27544058
E-mail : info@modiproperties.com
Visit us at : www.modiproperties.com

To
The Manager,
Reliance communications.
Lakeshore Towers.
Somajiguda. Hyderabad.

Dt:27/09/2007

Dear Sir,

Sub: - Notice received form GHMC, Kapra circle- Removal of tower at Mayflower Park,
Mallapur notice issued-reg.


Ref:-Notice no G2/884/2007 Dt.20-09-2007.

With reference to the above please find a notice received form office of the Deputy
Commissioner, Kapra circle GHMC, Videno.42/884/2007, DT: 20/09/2007. This is for
your reference and early action at your end.

Thanking you.

Yours truly,

For Modi Properties & Investments Pvt.Ltd.


Manager-Admin
(A.Shankar Reddy)

ENCL:- NOTICE RECEIVED FROM KAPRA MUNICIPALITY

Mr. Shamaan
93 98265452
1 part
copy

Received
Bhaskar
27/9/07
VICE President
30331610 PA
Mr. Vijay Bhaskar
cell no 93 96632149

NO. 101



1911
MAY 10
1911

1911
MAY 10
1911

1911
MAY 10
1911

1911
MAY 10
1911

1911
MAY 10
1911

1911
MAY 10
1911

1911
MAY 10
1911

1911
MAY 10
1911

1911
MAY 10
1911

1911
MAY 10
1911



MODI

PROPERTIES &
INVESTMENTS PVT. LTD.

Off : 5-4-187/3&4, II Floor,
M.G.Road, Secunderabad - 500 003.
Phone : 66335551
Fax : 040-27544058
E-mail : info@modiproperties.com
Visit us at : www.modiproperties.com

To.
The Deputy Commissioner
Kapra Municipality
GHMC.

Date: 24.09.2007

Sub.: Your telegram dated 21.09.2007 regarding structural drawings for Mayflower Park.

Dear Sir / Madam,


We have received your above referred telegram on 23.09.2007. In that connection please note the following:


1. Please find enclosed the copies of sanction plan, structural stability certificate and structural drawings of Block -I for your reference.
2. We would once again reiterate that the complaint made by Smt. P. Vara Lakshmi is with ulterior motives and is misleading the GHMC. The sole purpose of the complaint is to get the Reliance tower removed from I Block.
3. The Reliance tower possess no threat to the structure. It may be noted that the weight of the tower is negligible and not tens of tons as stated by Mrs. P. Vara Lakshmi. Further the columns of I Block have been designed to easily take the weight of structures like water tank and lift room which weigh more than 100 tons.

We request you to grant us 15 days in order to provide an expert opinion from a reputed structural engineer regarding the soundness and structural stability of I Block. In the meantime we request you not to take any coercive action against the said tower.

Thank You.

Yours sincerely,


Soham Modi



10740



10740

10740

10740

10740

10740

10740

10740

10740

10740

10740

10740

10740

10740



MODI

PROPERTIES &
INVESTMENTS PVT. LTD.

Off : 5-4-187/3&4, II Floor,
M.G.Road, Secunderabad - 500 003.
Phone : 66335551
Fax : 040-27544058
E-mail : info@modiproperties.com
Visit us at : www.modiproperties.com

To,
The Deputy Commissioner
Kapa Municipality
GHMC.

Date: 24.09.2007

Sub.: Your telegram dated 21.09.2007 regarding structural drawings for Mayflower Park.

Dear Sir / Madam.

We have received your above referred telegram on 23.09.2007. In that connection please note the following:

1. Please find enclosed the copies of sanction plan, structural stability certificate and structural drawings of Block -I for your reference.
2. We would once again reiterate that the complaint made by Smt. P. Vara Lakshmi is with ulterior motives and is misleading the GHMC. The sole purpose of the complaint is to get the Reliance tower removed from I Block.
3. The Reliance tower possess no threat to the structure. It may be noted that the weight of the tower is negligible and not tens of tons as stated by Mrs. P. Vara Lakshmi. Further the columns of I Block have been designed to easily take the weight of structures like water tank and lift room which weigh more than 100 tons.

We request you to grant us 15 days in order to provide an expert opinion from a reputed structural engineer regarding the soundness and structural stability of I Block. In the meantime we request you not to take any coercive action against the said tower.

Thank You.

Yours sincerely,



Soham Modi

MADI



ՀԱՅԿԱՍՏԱՆԻ ԿՐԹԱՆՈՒԹՅԱՆ
ՄԱՐԿԵԿԻՆԻ ՎԵՐՈՒԹՅԱՆ

Հայաստանի Կրթության
և գիտության նախարարության
Մարկեքինիկայի վերոստ
գրասենյակի հրավեր

Կապակցված
Ֆինանսական
ՍԵՂՈՒՆ

Հանրային առարկայի գնումներով հարկադրված կապակցման մասին

Մաս 1. 2024

Հանրային առարկայի գնումներով հարկադրված կապակցման մասին

Մաս 2. 2024

Հանրային առարկայի գնումներով հարկադրված կապակցման մասին

2. 2024

Հանրային առարկայի գնումներով հարկադրված կապակցման մասին

2. 2024

Հանրային առարկայի գնումներով հարկադրված կապակցման մասին

2. 2024

Հանրային առարկայի գնումներով հարկադրված կապակցման մասին

2. 2024

Հրավերի
արտոնագրի
N 100/2024



MODI

PROPERTIES &
INVESTMENTS PVT. LTD.

Off : 5-4-187/3&4, II Floor,
M.G.Road, Secunderabad - 500 003
Phone : 66335551
Fax : 040-27544058
E-mail : info@modiproperties.com
Visit us at : www.modiproperties.com

To,
The Deputy Commissioner
Kapra Municipality
GHMC.


Date: 22.09.2007

Ref.: Your notice U/s. 459 of the HMC Act, 1955 bearing no. G2/884/TPS-II/2007
dated 20.9.07

Dear Sir / Madam,

We have received your above referred notice. In that connection please note the following:

1. Mayflower Park and in particular I Block have been built to the highest quality standards. The construction was completed in about 2002. There is no question of any structure being dilapidated or in the danger of collapse.
2. I Block has been structurally build as 2 separate buildings and an expansion joint has been provided between the 2 flats on the eastern side and rest of the building on the western side. The expansion joint falls in the corridor of the building. The very purpose of expansion joint is to let the structures within I Block to expand and contract independent of each other. The gap which has been provided at the expansion joints has been appropriately sealed for the purpose of stopping seepage and for aesthetic looks.
3. We have handed over the building about 5 years ago to the owners of the building. The maintenance of the building is being undertaken by the Mayflower Park Owners Association. The sealant for the expansion joint must be repaired/replaced every few years. Mayflower Park Owners Association is well aware of it and at their request we have given them a list of recommended contractors who will undertake the job. The responsibility of maintenance of the buildings at Mayflower Park is entirely of Mayflower Park Owners Association.
4. Even if the expansion joints are not replaced or repaired it is unlikely to cause any harm to the building (structurally).
5. Reliance communications has put up a tower on I Block after obtaining all necessary permissions from all statutory authorities. You are well aware that hundreds of such towers have been put up through out the city and rules for erection of towers have been framed by appropriate authorities. From our side the structure has been suitably built to support the tower.



10/10/10



10/10/10
10/10/10
10/10/10
10/10/10
10/10/10

10/10/10

10/10/10

10/10/10

10/10/10

10/10/10

10/10/10

10/10/10

10/10/10

10/10/10

10/10/10

10/10/10

10/10/10

10/10/10

10/10/10

10/10/10

10/10/10

10/10/10





MODI

PROPERTIES &
INVESTMENTS PVT. LTD.

Off : 5-4-187/3&4, II Floor.
M.G.Road, Secunderabad - 500 003.
Phone : 66335551
Fax : 040-27544058
E-mail : info@modiproperties.com
Visit us at : www.modiproperties.com

6. GHMC, Kapra Circle has simply jumped to the conclusion that the building is dilapidated and is likely to collapse merely on the complaint of one Mrs. P. Vara Lakshmi a resident of that building. GHMC has neither made a spot inspection, checked any structural plans, consulted the builder or made any effort to understand the nature of the problem.
7. The Deputy Commissioner may please take note that the sole purpose of complaint made by Smt. P. Vara Lakshmi is to get the tower above her flat removed. At several instances some residents of I Block and May Flower Park Owners Association have requested the builder to remove the tower or hand it over to the Owners Association so that they can enjoy the rent from the tower. This complaint has been now instituted as they have failed in all their attempts over the last few years. The complaint is frivolous in nature and has been made to misguide GHMC.
8. The Reliance tower possess no threat to the structure. It may be noted that the weight of the tower is negligible and not tens of tons as stated by Mrs. P. Vara Lakshmi. Further the columns of I Block have been designed to easily take the weight of structures like water tank and lift room which weigh more than 100 tons.
9. GHMC has issued notices to the residents of I Block to vacate the premises. It is very clear from the response of the GHMC that the officers have issued notices only to save their skin. They only wish to absolve themselves of any responsibility. By issuing such notices they are creating panic among the residents of Mayflower Park.

I request the Deputy Commissioner, Kapra Circle, GHMC to withdraw the said notice as it is highly arbitrary and issued without obtaining appropriate inspection report or expert opinion. Further no show cause notice has been issued to the builder as required under law. The builder has not been given any opportunity to represent to GHMC the true facts of the case.

Thank You.

Yours sincerely,

Soham Modi

C.C.: The Chief Commissioner, GHMC.

100M



100M

100M

100M

100M

100M

100M

100M

100M

100M

100M

100M

100M

100M

100M

100M

100M

100M

100M



100M

TELEGRAM
DEPARTMENT OF TELECOMMUNICATIONS

Handwritten initials

Telegrams : Ordinary
Number : SECUNDERABAD-ECIL
Booked On : 21
Booked Time : 1300

Office : SDE-SECUNDERABAD
Ref : AHSDR --AHSDR0003
Received On : 21/09
Received Time : 13:52


DELIVERY INSTRUCTIONS
---M1---

To:

M/S MODI PROPERTIES AND INVESTMENTS (P) LIMITED
INVESTMENTS (P) LIMITED
441 3-4-1973 M B ROAD
SECUNDERABAD

Handwritten number 29

BSNL



M/S MODI PROPERTIES AND INVESTMENTS (P) LIMITED IS
HEREBY DIRECTED TO PRODUCE COPIES OF SANCTIONED PLANS
STRUCTURAL DRAWINGS AND STRUCTURAL STABILITY CERTIFICATE
OF ALL BLOCKS RELEASED BY THIS OFFICE VIDE PROCEEDING
NO. RA/236/99-2000 DATED 22-09-1999 AND HUDA LR 4549/04/
/HUDA/99 DT 07-09-1999 OF MAY FLOWER APARTMENTS IN
SURVEY NO. 174 OF MALLAPUR VILLAGE TO DAY IT SELF
DEPUTY COMMISSIONER
KARRA CIRCLE CHMC
CO. ANCTS
=====

AHSDR0003
AHDTM00278
MAY99

Office Use Only :
COMPUTER CODE : ECIC AHSDR0003 PER AHSDR
O 1300 AR3 SECUNDERABAD-ECIL 21 85



Handwritten mark or signature in the middle right section.



Faint text or markings at the bottom right of the page.

Recd
26/9/07

**OFFICE OF THE DEPUTY COMMISSIONER
KAPRA CIRCLE, G.H.M.C.**

No.G2/884/2007

Date: 20-09-2007

NOTICE

Sub: GHMC – Kapra Circle – Town Planning – Unauthorized erection of Tower over the Block-I of May Flower Park, Mallapur (V) – Remove the Tower – Notice – Issued – Regarding.

Ref: Grievance Petition of Smt P. Vara Laxmi, dated: 15-08-2007 R/o. Block- I - 402, May Flower Park, Mallapur (V).

* * * *

Whereas it has been brought to my notice that you have erected a telecommunication signal tower (Reliance) over the terrace of 5th floor of Block-I on May Flower Park apartment in Sy.No.174 of Mallapur (V) unauthorizedly with out taking prior permission from the competent authorities.

The flat owners of the Block also lodged a complaint that due to heavy load of the machinery and tower established over the terrace of the block-I causing damage to the building and some wide cracks also developed due to which there is a danger to their life.

During inspection it is also observed that some cracks are developed in all floors of the Block at the tower erected location.

Therefore you are hereby directed to remove the tower erected illegally with in ten days from the date of receipt of this notice. Failing which necessary action will be initiated by the GHMC as per the provisions of the HMC Act 1955, for the consequences of which you will be held liable if any untoward incident takes place.

S. N. S.
**Deputy Commissioner,
Kapra Circle, GHMC.**

To,

M/s. Modi Properties & Investments (P) Ltd.,
M.G. Road,
Secunderabad.

Copy to the President, May Flower Park Residents Welfare Association.
Copy to the Manager, Reliance Communication.
Copy to the Smt Vara Laxmi, for information.
Copy to the Station House Officer, Nacharam Police Station.

OFFICE OF THE DEPUTY ATTORNEY GENERAL
KARLA KIMBLE

MEMORANDUM

DATE: 10/10/00

MEMORANDUM

TO: THE ATTORNEY GENERAL
FROM: [Name]
SUBJECT: [Subject]

1. [Text]

2. [Text]

3. [Text]

4. [Text]

5. [Text]

6. [Text]

7. [Text]

8. [Text]

9. [Text]

10. [Text]

11. [Text]

12. [Text]

13. [Text]

14. [Text]

15. [Text]

16. [Text]

17. [Text]

18. [Text]

19. [Text]

20. [Text]

21. [Text]

22. [Text]

23. [Text]

24. [Text]

25. [Text]

26. [Text]

27. [Text]

28. [Text]

29. [Text]

30. [Text]

20/9/07

**OFFICE OF THE DEPUTY COMMISSIONER
KAPRA CIRCLE, G.H.M.C.**

No.G2/884/TPS-II/2007

Date: 20-09-2007

Notice under sections 459 of the HMC Act, 1955

To

M/s. Modi Properties & Investments Pvt Ltd.,
Premises No. 5-4-187/3&4, IIIrd Floor,
M.G.Road, Secunderabad.

Sir / Madam,

It is reported that the building situated at Block-I of May Flower Park at Mallapur(V) is in dangerous & dilapidated condition / is likely to collapse at any moment causing danger to the inmates of the building / surrounding building and the public passing through the road/lane on the front/sides of the said building.

You as the owner / occupier of the said dilapidated structures are hereby required to vacate / repair / remove the said dilapidated structures to prevent all cause of danger immediately. Therefore you are hereby requested to vacate / repair / remove the dilapidated structure immediately.

Your attention is invited to Sections 459 of HMC Act, 1955 and you the owner / occupier of the said dilapidated building are hereby requested to vacate the building immediately and repair/ remove the dilapidated structures of the said premises, failing which you will be held responsible for any sort of danger / incident and any other problem created due to the said dilapidated structures.

S. K. H. C.
**Deputy Commissioner,
Kapra Circle, GHMC.**

20/9/07
20/9/07

Copy to :

Smt. P. Varalaxmi,
Block-I, Flat.No.402,
May Flower Park Apartment,
Mallapur (V),
GHMC.

STATE OF TEXAS
COUNTY OF [illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible signature]

[illegible]

[illegible]

Municipal Commissioner,

East Zone.

Great of 5 floors' building falling down – instant danger and hazard to human lives - Reg.


Flats in I-Block of 'May Flower Park' at Mallapur in 2003, and living in flats 01 and 02 numbers in this five floors' block. The 'May Flower Park' was developed and constructed by M/s Modi Properties & Investments Pvt. Ltd. MG Road, Secunderabad. We noticed a wide crack/cut of our flats from the main block (from ground to fifth floors completely south to north), bending our sub-block to eastern side. The experts have opined it construction and structural defect for imperfect workmanship & low quality material, and declared hazardous and dangerous to live in.

The hazard and danger is further multiplied by the installation of a high tower with its connected machinery over our roof, which weighs in tens of tonnes. It is erected by the Reliance Communications, probably with the consent of said M/S Modi. We have brought these facts to the knowledge of the Developers/Promoters/Builders and our Flat Owners' Association, but in vain.

Please take urgent action to safeguard our lives against the danger and hazard or else our flats may fall down at any time causing heavy casualties.


MALLAPUR, HYD.

Date: 15-08-2007.


P. VARA LAXMI
R/o I-402,
May Flower Park, Mallapur.
Ph:27158888, 9490641188
c/o M.Zafarullah, Advocate,
Ph:9247173741,9246283363

Copy with similar request to:

1. The Commissioner & Special Officer, GHMC, Hyderabad.
2. The Addl. Zonal Commissioner, GHMC East Zone.
3. The Chief City Planner, GHMC, Hyderabad.
4. The Commissioner of Police, Cyberabad.
5. The SHO, Police Station: Nacharam, Cyberabad.



Handwritten text at the top of the page, possibly a title or header.

Handwritten text below the top section.

Handwritten text in the middle section.

Handwritten text in the middle section.

Handwritten text in the middle section.

Handwritten text in the middle section.

Handwritten text in the middle section.

Handwritten text in the middle section.

Handwritten text in the middle section.

Handwritten text in the middle section.

Handwritten text in the middle section.

Handwritten text in the middle section.

Handwritten text in the middle section.

Handwritten text in the middle section.

Handwritten text in the middle section.

Handwritten text in the middle section.

Handwritten text in the middle section.

Handwritten text in the middle section.

Handwritten text in the middle section.

Handwritten text in the middle section.

Handwritten text in the middle section.

Handwritten text in the middle section.

Handwritten text in the middle section.

Handwritten text in the middle section.

Handwritten text in the middle section.

Handwritten text in the middle section.

Handwritten text in the middle section.

Handwritten text in the middle section.

Handwritten text in the middle section.

Handwritten text in the middle section.

Handwritten text in the middle section.

Handwritten text in the middle section.

Handwritten text in the middle section.

Handwritten text in the middle section.

Handwritten text in the middle section.

Handwritten text in the middle section.

Handwritten text in the middle section.

Handwritten text in the middle section.

Handwritten text in the middle section.

Handwritten text in the middle section.

Handwritten text in the middle section.

