

CONSULTANT INSPECTION REPORT

MODI REALTY MALLAPUR LLP

5-4-187/3&4, II Floor, M.G. Road,
Secunderabad - 500 003.
Phone : +91 - 40 - 66335551

GULMOHAR RESIDENCY

Sy. No. 19, Mallapur,
Hyderabad - 500 076.
Phone : +91 91210 21818

Sl. No. 1001

Date : 08.08.2019

Physical Soil Investigation

- ① Soil Profile
Top layer - Soft red soil
Second layer - Red soil - Gravel
Third layer - Red to yellowish Gravel
(Mudam)
Deteriorated rock
- ② Hard soil strata reached 1-8'0" from NGL
- ③ Soil is deteriorated rock (Mudam)
- ④ Foundation work can be started by checking the exact value of SBC.
- ⑤ Remove all loose particles from pits. Drive uniformly until hard soil strata is reached and then proceed further with concrete work
- ⑥ for exact values of SBC check soil testing report.

Engineer Sign.

• P. Sci. Kunst

Date : _____

8/8/19.

Consultant Sign.

Date : _____

08/08/2019,