

Mr. Dile

Task List	NE-II
Company Name:	NE
Date	27.05.17
Prepared by	M.Mahesh

Sl.no	Site	Depth	Capacity of pump		Loacation	Status
1	NE	200'	1 HP	Single Phase	Main gate entrance	Working
2	NE	150'			No motor	Not working
3	NE	350'	3 HP	3 phase	Villa no 21	Working
4	NE	380'	3 HP	3 phase	Villa no 72	Working
5	NE	300'	1 HP	Single phase	South east corner	working
6	NE	300'	3 HP	3 phase	Villa no 1	Starter problem

Sir, Actually I have enquired starting new pump 3 hp capacity. Pump is having pressure problem it seems so they have sent for repair / replacement , later on again they have faced same problem , in this regard again they have ordered new one that is working . default is laying in stores at club house first floor.

And one more 1.5 hp pump is gone to MNM site .