

aruna@modiproperties.com

From: <sohammodi@modiproperties.com>
Date: 02-11-2017 10:41 AM
To: <aruna@modiproperties.com>
Attach: IMG_20171031_162309.jpg; IMG_20171031_162052.jpg; IMG_20171031_145850.jpg;
IMG_20171031_162003.jpg
Subject: FW: Water Seepage along retaining wall and at Expansion join of E-Block.

Print

From: BnC estates [mailto:bnc@modiproperties.com]
Sent: 01 11 2017 02:43 PM
To: sohammodi@modiproperties.com
Cc: Subbareddy BNC <subbareddy@modiproperties.com>; BnC Estates <bnc@modiproperties.com>
Subject: Reg:Water Seepage along retaining wall and at Expansion join of E-Block.

Respected Sir,

This is regarding seepage in E-Block sub Cellar floor. Sir, after close observation we have found that there is continuous seeping of water in to sub cellar along E-Block retaining wall at 2 locations of 30 feet length. Seepage is through minute pores along the flooring and retaining wall joint. This continuous seepage is the reason for water in sub cellar floor.

There is continuous water coming out from expansion joint at column joint.

Attached to the mail are the photos of seepage areas and expansion joint seepage.

Brick work and plastering of joint has no effect on seepage.

Please advise Sir.

Regards,
K. Kiran Kumar,
BNC Estates.

Sent from Yahoo Mail on Android

02-11-2017

