Recommendation: Stop further work. Stop further work. Proceed with furth Proceed with furth	Checked By MD on	Previous stage report no.	Project Manager	Prepared by	Company	Flat No
Stop further work. Submit ATR on QC report Stop further work. Proceed with work after some Proceed with further work only after making of Proceed with further work. ATR not required.		no.	Zak:y	G.RAJESH	AGH	و بر
eport to QC team. Proc ter submitting ATR on sing corrections pointed ired.	MD Sign	35655	Sign	Sign	Project	Other
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required. Proceed with further work. ATR not required.		Report filed and signed	Todas \	la	AVR Gulmohar	1
by QC. ATR not required.	For filling	ed by PM	Date	Date	Phase	SI. No.
	☐ Yes ☐ No	GYes □No	26 109 120	26 109 20	1	36104

Scanned with CamScanner

Inspection should be done after:

- Completing stage II works.
- Complete works like windows, grills, electrical wiring, switches, french door glass, etc.
- In case of modular kitchen provide platform, granite and dado and modular kitchen in this stage.
- Provide video door phone in this stage.
- Possession for wood work cannot be given until QC check for stage III is completed and all corrections mentioned in the report are made.

Stage III check notes:

- Window grills must be fitted at the depth of 1/4" from the wall.
- Switchboards must be fitted to plum
- Cover junction boxes with cement covers and not PVC covers. Use pin head type sheet metal screws (not MS).

Miscellaneous check:

Modular kitchen to be provided	☐ Yes ☐ No (Modular kitchen provided	☐ Yes ☐ No ☐
Modular kitchen workman ship	☐ Good ☐ Avg ☐ Poor Modular kitchen granite	Modular kitchen granite & dado	☐ Good ☐ Avg ☐ Poor
	١	workman ship & finishing	-
Video door phone to be provided	☑Yes □No	Video door phone provided	☐ Yes ☑No

	Ren	15	14	13	12	=	10	9	∞	7	6	2	4	ω	2	-	S No	
2	Remarks Note : 1. 3	Other	Portico	Toilet 3	Toilet 2	Toilet 1 M. T	Kitchen	Utility / balcony 3	Utility / balcony 2	Utility / baleony 1	Lobby T Pooja	Dining	Drawing	Bedroom 3	Bedroom 2 M. B	Bedroom 1 M.B	Room	
Edevation	In Two				7	7	1	1	I	1	1	١	1	1	<	7	Door, door knob & door stopper fitting	
tion					7	7	1	1	1	1	((1	1	<	<	Door, door knob & door stopper cleaning	R
Window	Toilet's				7	7	7	1)	1	(<	7	1	1	<	Window grills & quality	Rate the quality of (Good
1	nic.				<	7	1	()	1	(<	7	1	<	7	Window grills fitting & finishing	ality of (G
	window (7	1	<	١	J	1	<	<	7	1	<	<	Windows quality	ood ✓, Avg.
not	Alymunium				7	7	<	(J	١	(<	7	1	<	<	Window fitting & finishing	×
Provided.	7 unium				ĺ	1	1	1)	l	1	(١	1	١	1	Balcony railing quality & finishing	Poor – need
ed.	som (\	1	1	1	,	<	((1	(1	١	CP jali quality and fitting	ls correction
	not				ζ	\	×	1)	1	(<	×	1	×	×	Edge building	needs correction XX, NA)
	Provided.				\	7	7	l)	1	(7	7	1	ζ		Switch boards fitting & covering with plastic covers	VA)
	led.					۲	<	1	1	\	(<)	<	<	Junction box covers painting	

Quality Control Check Repot. Stage: After Finishing Stage III (Villas)

Miscellaneous check – after finishing stage III	
Quality and workmanship of gate	Good Avg. Poor
Quality and workmanship of railings	Good Avg. Poor
Painting of gates & railings	Good Avg. Poor
Cleaning/painting of external cladding/texture	Good Avg. Poor
Quality and workmanship of lawn	Good Avg. Poor —
Remarks: Note 31. Jawn was not Provided.	
2. For Villa At Coulle of Places Civil	8 Civil work's painting was
pending.	