Quality Control Check Report.   Stage: After Column Casting (villas)

Block No.	26	Column No.	01	Sl. No.		33734
Company	Serene Construction	Project Sign	Serene Poms	Phase		-
Prepared by	S.Sunil Kumar	Sign		Date		06/06/19
Project Manager	Siva Prasad	Sign		Date		06/06/19
Previous stage report no.			38827	Report filed and signed by PM?		☐Yes ☐No
				G.Siva Prasad		
Checked By MD on		MD Sign		For filling		☐Yes ☐No

Recommendation:
☐ Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.
☐ Stop further work. Proceed with work after submitting ATR on QC report to QC team.
☑ Proceed with further work only after making corrections pointed out in the QC report. ATR not required.
☐ Proceed with further work. ATR not required.

Columns Position Check.
Notes:
1. Inspection should be done after casting of columns at each stage and before starting centering works for each slab.
2. Prepare Columns Position Check Plan as follows:
    a.   Divide blocks into smaller sub-blocks.
    b.   Show size and orientation of columns. (Tolerance 0.5")
    c.   Show inner – inner space between columns. (Tolerance 1")
    d.   Show diagonals for 20% of bays. (Tolerance 1.5")
    e.   Print an A3 size plan.
3. Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension next to it.

Columns Position Check Plan enclosed?	☑Yes ☐No

Slab Dimensions Check.
Notes:
1. Prepare Slab (or plinth beams) Dimensions Check Plan as follows:
    a.   Show outer dimensions of slab. (Tolerance 2")
    b.   Show length and width of balconies (Tolerance 1")
    c.   Show inner dimensions of ducts and lift well. (Tolerance 1")
    d.   Show location of sunken slab.
    e.   Print an A3 size plan.
2. Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension next to it

Slab Dimensions Check Plan enclosed?	NA	☐Yes ☐No
Specified thickness of slab?	NA	Actual thickness of slab?	NA