

- 1. Column correction cc should be a monolith with plinth beam.
- 2. Table bricks / blocks to be joined with cement mortor.

FIG.NO.96	CHIPPED BROKEN COLUMN FIG.NO.96	STANDARD DRAWING FOR	Description
Z			Direction
	Project Name & Phase:		Direction Owners & Developers:
Scale:	Approved By:	Prepared By:	Date:
N.T.S	Soham Modi	Nagalaxmi	16.05.2022
Phone:+91-40-66335551	Modi Properties Pvt Ltd Phone:+91-40-66335551		Promoted by