



CASE - A



**APPROVED BY**  
**16 MAY 2022**  
**SOHAM MODI**  
**MANAGING DIRECTOR**

1. Column correction cc should be a monolith with plinth beam.
2. Table bricks / blocks to be joined with cement mortar.

CASE - B



<p>Description</p> <p style="text-align: center;">STANDARD DRAWING FOR CHIPPED BROKEN COLUMN</p>	<p>Direction</p> <p style="text-align: center;">N </p>	<p>Owners &amp; Developers :</p> <p style="text-align: center;">Project Name &amp; Phase :</p>	<p>Date :</p> <p>Prepared By :</p> <p>Approved By :</p> <p>Scale :</p>	<p>16.05.2022</p> <p>Nagalaxmi</p> <p>Soham Modi</p> <p>N.T.S</p>	<p>Promoted by</p> <p style="text-align: center;">Modi Properties Pvt Ltd Phone: +91-40-66335551</p>
--	--	--	--	---	--