uality
Control
uality Control Check Repot.
Stage
:: After
Finishing
Stage II
Stage: After Finishing Stage II (Apartments)

Tilat NIA		Out.		C1 11	
FIAL INO	C-005	Other	1	St. No.	30107
Company	VISTA HOMES	Project	VISTA HOMES	Phase	Ì
Prepared by	M. Tya Sindhur	Sign	FR	Date	24/04/18
Project Manager	Madhu.	Sign	Youlv	Date	81/20/18
Previous stage report no.	no.	26203	Report filed and signed by PM	d by PM	WYes □No
Checked By MD on		MD Sign		For filling	☐Yes ☐No
Recommendation: Stop further work. Stop further work. Proceed with furth Proceed with furth	Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not proceed with further work. ATR not required.	port to QC team. Proce ter submitting ATR on ing corrections pointed ired.	sed only after recheck l QC report to QC team. l out in the QC report. 1	y QC. ATR not required.	
Inspection should be done after:	after:				

- Completion of flooring, bathroom /utility tiles, doors & beading, first coat of paint. Completion of windows, grills, electrical wiring, switches must be done in next stage False ceiling must be completed before flooring.
- Kitchen platform, granite and dado must be completed where modular kitchen is not provided.
- Provide granite soffit for main door and balconies in this stage.

Miscellaneous check:

Good Navg Poor	False ceiling workmanship	√Yes □No	False ceiling to be provided?
	polishing		
☐ Good ☑ Avg ☐ Poor	Main door granite soffit edge	☐Good ☐Avg ☐ Poor	Main door granite soffit workmanship Good Avg Poor Main door granite soffit edge
ŊYes □No	Granite soffit for main door provided $ \nabla Y$ es $ \nabla Y$	that the management of	Granite soffit for main door required ☐Yes ☐ No
oolishing Good Avg Poor	Balcony granite soffit edge polishing	☐ Good ☑ Avg ☐ Poor	Balcony granite soffit workmanship Good Navg Poor Balcony granite soffit edge p
NYes □ No	Granite soffit for balcony provided	¥es □No	Granite soffit for balcony required
\		√Yes □No	Main door fixed with lock & stopper \ \New Yes \ \No

Ren	9	∞	7	6		S	4	ω	2	-	S No	
Remarks	Other	Other	Utility	Kitchen	dining-area	Wash basin in	Feilet4	Teilet-3	Toilet 2 (CT)	Toilet I (MT)	Room	Tiling & granite work
			<	1	1		-	-	<	<	Workmanship of tiling	
			<	<	1		1	1	<	<	White cement filling around CPVC lines	
			<	1	J	(1	1	<	<	Corners finishing	Rate th
			<				1	1	<	<	Finishing near doors	Rate the quality of (Good , Avg. X, Poor - needs correction XX, NA)
			<	1		(1	1	<	<	Finishing on top of tiles	of (Goo
			*Companies**	1			1		<,	X	Finishing near ventilators	d •, A
			<	[(1	1	<	<	Step at bathroom entrance / utility	vg. ×, I
				(I	1	<		Step for shower / pot wash	oor – ne
		k	<	([1	<	<	Tile joint grouting	eds corr
		1		1	[]		ĺ	ζ.	Granite platform finishing and edge polishing	ection X
		-			Į			1	•	<	Granite platform slope	X, NA)
				1	1		1			<	Granite platform height	
					Į			1		<	Finishing under granite platform	

12 0	S No	E
Other Remarks	Bedroom 1 (MB) Bedroom 2 (KB) Bedroom 3 Bedroom 3 Drawing Dining Lobby-1 Lobby-1 Lobby-1 Utility/balcony 1 Utility/balcony 3 Kitchen Other	Flooring & painting
3	Color variation of floor tiles	
K. Bedroom	Flooring workman ship & grouting	
hoom	Skirting size (3")	Rate
groutine	Skirting workmanship	the qualit
Not I	Plastering above skirting	Rate the quality of (Good
	Plastering & finishing of walls	d v, Avg.
den	Crack filling	g. X, Poor
Roperty	Loft Finishing	1
	General quality of painting & finishing	ıg Circ
	Door & frame paint quality	ing am
	Door beading, lupp and painting qualit	am y.
	Edge building	