Quality Control Check Repot. Stage: After Finishing Stage III (Apartments)

Company Dave II Project Proj	Flat No	0-725	Other		SI. No.	32430
Sign Sign Report filed and signed by PM MD Sign MD Sign Report filed and signed by PM Bimit ATR on QC report to QC team. Proceed only after recheck by QC. roceed with work after submitting ATR on QC report to QC team. Work only after making corrections pointed out in the QC report. ATR not required. Nate Report filed and signed by PM For filling	Company	1200 - II	Project	Par-A	Phase	
Sign 32292 Report filed and signed by PM MD Sign MD Sign For filling For filling work only after submitting ATR on QC report to QC team. Proceed only after recheck by QC. work only after making corrections pointed out in the QC report. ATR not required.	Prepared by	P. Cas Munar	Sign	PLA	Date	22/12/8
MD Sign MD Sign Report filed and signed by PM MD Sign For filling bmit ATR on QC report to QC team. Proceed only after recheck by QC. roceed with work after submitting ATR on QC report to QC team. work only after making corrections pointed out in the QC report. ATR not required. work, ATR not required.	Project Manager	k showing know	Sign		Date	21/12
on MD Sign For filling Cork. Submit ATR on QC report to QC team. Proceed only after recheck by QC. ork. Proceed with work after submitting ATR on QC report to QC team. urther work only after making corrections pointed out in the QC report. ATR not required. urther work. ATR not required.	Previous stage report	no.	32292	Report filed and signe	d by PM	MYes No
ork. Submit ATR on QC report to QC team. Proceed only after recheck by Q ork. Proceed with work after submitting ATR on QC report to QC team. urther work only after making corrections pointed out in the QC report. ATR urther work. ATR not required.	Checked By MD on		MD Sign		For filling	☐Yes ☐No
Inspection chould be done offer.	Recommendation: Stop further work. Stop further work. Proceed with furth Proceed with furth	Submit ATR on QC re Proceed with work aft ter work only after mak er work. ATR not requi	port to QC team. Procler submitting ATR on ing corrections pointedired.	eed only after recheck l QC report to QC team I out in the QC report.	oy Q ATR	

- Completing stage II works.
- Complete works like windows, grills, electrical wiring, switches, french door glass, etc.
- In case of modular kitchen provide platform, granite and dado and modular kitchen in this stage.
- Provide video door phone in this stage.
- Possession for wood work cannot be given until QC check for stage III is completed and all corrections mentioned in the report are made.

- Stage III check notes:

 1. Window grills must be fitted at the depth of '4" from the wall.

 2. Switchboards must be fitted to plum.
- Cover junction boxes with cement covers and not PVC covers. Use pin head type sheet metal screws (not MS).

Miscellaneous check:

Video door phone to be provided	And the state of t	Modular kitchen workman ship	Modular kitchen to be provided
Yes No		Good Avg Poor	Yes No
Video door phone provided	workman ship & finishing	☐ Good [V Avg ☐ Poor Modular kitchen granite & dado	Modular kitchen provided
Yes No		Good YAvg Poor	Yes No