	Quality Control Check Repot.		Stage: After Finishing Stage III (Apa	e III (Apartments)	
Flat No	E-10)	Other		Sl. No.	31076
Company	BNC	Project	3	Phase	× × × × × × × × × × × × × × × × × × ×
Prepared by	2000	Sign		Date	
Project Manager		3	Much	No. of the last of	23/62/19
r roject Maidage	book Reddy	Sign	1 2	Date	22/02/19
Previous stage report no.	no.	32802	Report filed and signed by PM	d by PM	LYcs No
Checked By MD on		MD Sign		For filling	Yes No
Recommendation:					
Stop further work. Stop further work. Proceed with furth	Submit ATR on QC rep Proceed with work after work only	port to QC team. Proer submitting ATR c	Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after reclaims and the proceed with further work only after reclaims.	у QС.	
Proceed with furth Proceed with furth	Proceed with further work only after making or Proceed with further work. ATR not required.	ng corrections point red.	Proceed with further work only after making corrections pointed out in the QC report. ATR not req	VTR not required.	
Inspection should be done after:	after:				

the said in the case

- Completing stage II works.
- In case of modular kitchen provide platform, granite and dado and modular kitchen in this stage. Complete works like doors, windows, grills, electrical wiring, switches, french door glass, etc.
- Provide video door phone in this stage.
- Possession for wood work cannot be given until QC check for stage III is completed and all corrections mentioned in the report are made.

- Stage III check notes:

 1. Window grills must be fitted at the depth of 1/4" from the wall.

 2. Switchboards must be fitted to plum.
- Cover junction boxes with cement covers and not PVC covers. Use pin head type sheet metal screws (not MS).

Miscellaneous check:

video door phone to be provided	Vidoo document	Modular kitchen workman ship			Modular kitchen to be provided	
LYes UNo		Good Avg Poor		Yes No		
Video door phone provided	workman ship & finishing	Good Avg Poor Modular kitchen granite & dado	7.00	Modular kitchen provided		
Yes No	[]	Good Avg Poor		TVes TVes		