Qua	Quality Control Check Repot.	eck Repot.	Stage: After Finishing Stage III (A)	age III (Apartments)	
Flat No C	C-603	Other		SI. No.	17/046
Company	BNC	Project	ンナン	Phase	(<i>=</i>
	P. Sai Kemar Sign	Sign	Poly	Date	7 0 7
Project Manager Sivi	Sign Coldy Sign	Sign	7.82	Date	410/4
Previous stage report no.		965tr	Report filed and signed by PM	ned by PM	Yes No
Checked By MD on	Auto la r	MD Sign		For filling	Yes No
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not Inspection should be done after:	ATR on QC reled with work after only after making.	oort to QC team er submitting A'ng corrections pred.	Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck I Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. Proceed with further work. ATR not required.	n. ATR not required.	
mapacitan ac done after .				Control Contro	

Quality Control Check Repot.

- Completing stage II works.
- Complete works like doors, windows, grills, electrical wiring, switches, french door glass, etc.
- In case of modular kitchen provide platform, granite and dado and modular kitchen in this stage.
- Provide video door phone in this stage.
- Pessession for wood work cannot be given until QC check for stage III is completed and all corrections mentioned in the report are made.

Stage III check notes:

- Window grills must be fitted at the depth of '," from the wall.
- Switchboards must be fitted to plum.
- Cover junction boxes with cement covers and not PVC covers. Use pin head type sheet metal screws (not MS).

Miscellaneous check:

Video door phone to be provided Yes No Video door phone provided Yes		Arodular kitchen workman ship Good Avg Poor Modular kitchen granite & dado Good	Windular Richen to be provided Yes Who Modular Ritchen provided	
Yes No) [Good Avg Poor	T Vac T Na	

S No

0

Page 2 of 2