Flat No	0-103	Other		SI. No.	33148
Company	Vista loves	Project	Vista homo	Phase	)
Prepared by	Prosen Know	Sign	Rod	Date	13/3/19
Project Manager	7. Madhu	Sign	4	Date	13/3/19
Previous stage report no.	no.	31015	Report filed and signed by PM		Yes No
Checked By MD on		MD Sign		For filling	☐Yes ☐No
Recommendation:  Stop further work. Sub Stop further work. Pro Proceed with further w Proceed with further w	Recommendation:  Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. ATR not required.  Proceed with further work. ATR not required.	port to QC team. Proces reasonable and ATR on ing corrections pointed ired.	eed only after recheck l QC report to QC team l out in the QC report.	by QC. ATR not required.	

- Inspection should be done after:
  Completion of flooring, bathroom /utility tiles, doors & beading, first coat of paint.
  Completion of windows, grills, electrical wiring, switches must be done in next stage
- False ceiling must be completed before flooring.
- Kitchen platform, granite and dado must be completed where modular kitchen is not provided.
- Provide granite soffit for main door and balconies in this stage.

## Miscellaneous check:

Good Avg Poor	False ceiling workmanship	☐Yes ☐No	False ceiling to be provided?
	polishing		
☐Good Mayg ☐Poor	Main door granite soffit edge	☐ Good Mavg ☐ Poor	Main door granite soffit workmanship Good Mavg Poor Main door granite
Yes [	Granite soffit for main door provided Yes No	Yes No	Granite soffit for main door required Yes No
☐ Good [V	Balcony granite soffit edge polishing	Good Avg Poor	Balcony granite soffit workmanship Good Avg Poor Balcony granite soffit edge polishing Good Avg Poor
YYes No	Granite soffit for balcony provided	☐Yes ☐No	Granite soffit for balcony required
		✓Yes □No	Main door fixed with lock & stopper Yes No

platform

4

S No