55	p
	uality
	Contro
	Quality Control Check Repot.
	r Finishing
	Stage III
	Stage: After Finishing Stage III (Apartments)

Flat No	ha1- G	Other		SI. No.	35476
Company	BNS	Project	W FG	Phase	7
Prepared by	S. Sunil Xumas	Sign		Date	08/6/18
Project Manager	Subba Reoldy, Sign	Sign	181	Date	08/6/18
Previous stage report no.	no.	3087 <b>8</b>	Report filed and signed by PM		Yes No
Checked By MD on		MD Sign		For filling	☐Yes ☐No
Recommendation:  Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by Q Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. ATR proceed with further work. ATR not required.	Recommendation:  Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. ATR not required.  Proceed with further work. ATR not required.	port to QC team. Proceed ter submitting ATR on ing corrections pointed ired.	eed only after recheck l QC report to QC team l out in the QC report.	by QC.  ATR not required.	

- Completing stage II works.

  Complete works like windows, grills, electrical wiring, switches, french door glass, etc.

  In case of modular kitchen provide platform, granite and dado and modular kitchen in this stage.
- Provide video door phone in this stage.
- Possession for wood work cannot be given until QC check for stage III is completed and all corrections mentioned in the report are made.

- Stage III check notes:

  1. Window grills must be litted at the depth of 'a' from the wall.
- Cover junction boxes with cement covers and not PVC covers. Use pin head type sheet metal screws (not MS).

## Miscellaneous check:

Video door phone to be provided		Modular kitchen workman ship	Modular kitchen to be provided
☐Yes ☐ No		Good Avg Poor	Yes No
Video door phone provided	workman ship & finishing	☐ Good ☑Avg ☐ Poor   Modular kitchen granite & dado	Modular kitchen provided
Yes No		Good Avg Poor	□Yes □No

	Ren	15	4	13	12	=	10	9	×	7	6	יטי	4	ω	10		S No	
*	Remarks Sufflick	Other	Other	Toilet 3	Toilet 2 C, Toi	Toilet 1 M, To1	Kitchen	Utility/balcony-3-	Utility / balcony-2-	Utility/balcony 1	Lobby-1	Dining	Drawing	Bedroom 3 (71-BCd	Bedroom 2 K. Bed	1 3	Room	
	Grails				ζ	<	}	1	ς	1	]	]	Κ	ζ	7	<	Door, door knob & door stopper fitting	
					ζ	ζ	)	1	<	}	1	1	<	ς	5	(	Door, door knob & door stopper cleaning	
	not fitted				<	ς	<	<b>`</b>	1	1	1	1	1	(	ζ	(	Window grills quality	Rate the
	fited.				ς	ς	~	9	ý	4	1	1		ζ	<	ζ	Window grills fitting & finishing	Rate the quality of (Good
					ζ	<	<	1	9	-	1	1	1	ς.	ζ	ς .	Windows quality	***
					ζ	~	ζ	1	]	- Company		1	1	<	<	<	Window fitting & finishing	V, Avg.
						9	1	١	j		1		1	4	1	j	Balcony railing quality & finishing	X, Poor-
					١	1	1	١	١	<	1	1	3	<	<	ζ	French door quality & fitting	- needs co
,					(	۲	١	1	ζ	ζ	1	1	1	<	<	<	CP jali quality and fitting	eeds correction XX, NA)
					ς	(	<	١	``		Chart	1	-	A	ζ	•	Edge building	X X
				(	`	۲	4	<b>N</b>	ζ	<	1	1	<	<	<	<b>\</b>	Switch boards fitting & covering with plastic covers	NA)
						7	<	Ì	<	<	)	)		<	<	ζ	Junction box covers painting	