Recommendation: Checked By MD on Previous stage report no. Project Manager Prepared by Company Flat No Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Proceed with further work. ATR not required. Proceed with further work only after making corrections pointed out in the QC report. ATR not required Stop further work. Proceed with work after submitting ATR on QC report to QC team. K-Shinh P. Sai しいる Quality Control Check Repot. 0-512 5 Sign Sign Other MD Sign Project 748H6 Stage: After Finishing Stage II (Apartments) Report filed and signed by PM Pmr-g For filling Date Sl. No. Date Phase 8115/2 20/9/13 Yes [=] Yes 31514 ∟ No \square No

Inspection should be done after:

- Completion of flooring, bathroom /utility tiles, doors & beading, first coat of paint.
- Completion of windows, grills, electrical wiring, switches must be done in next stage
- False ceiling must be completed before flooring.
- Kitchen platform, granite and dado must be completed where modular kitchen is not provided.
- Provide granite soffit for main door and balconies in this stage.

Miscellaneous check:

			·			
raise ceiling to be provided?		Main door granite soffit workmanship Good Avg Poor Main door granite soffit edge	Oranite soffit for main door required Yes No	Balcony granite soffit workmanship - Good Avg Poor Balcony granite soffit edge	Granite solfit for balcony required	1 4
∐Yes JNo	\	☐ Good ☐ Avg ☐ Poor	∐Yes NNo	Good Avg Poor	L Yes WNo	LYYes [] No
ng workmanship	polishing	Main door granite soffit edge	Granite soffit for main door provided	Balcony granite soffit edge polishing	Granite soffit for balcony provided	
Good Avg Poor		Good Ave Poor	provided Yes No	polishing Good Avg Poor	☐Yes ☐No —	
				1		