The state of the s	Treated to be a few of the state of the	Comment of the contract of the
--	---	--

Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR n Proceed with further work. ATR not required.	Checked By MD on	Previous stage report no.	Project Manager	Prepared by	Company	Flat No
ubmit ATR on QC re roceed with work af work only after mak work. ATR not requ		•	Subject Ready.	S.Swilzuma!	PNC.	D-604
eport to QC team. Proter submitting ATR oring corrections point ired.	MD Sign	28889	Sign	Sign	Project	Other
scommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck 1 Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. Proceed with further work. ATR not required.		Report filed and signed by	2.81	Ac	M(0)	
by QC. ATR not required.	For filling	ed by PM	Date	Date	Phase	SI. No.
	☐Ycs ☐No	L-Ycs No	क्षपा जी। ह	27 3 18	山	29826

Inspection should be done after:

- Completing stage II works.

 Complete works like windows, grills, electrical wiring, switches, french door glass, etc.

 In case of modular kitchen provide platform, granite and dado and modular kitchen in this stage.
- Provide video door phone in this stage.

 Possession for wood work cannot be given until QC check for stage III is completed and all corrections mentioned in the report are made.

Stage III check notes:

- Window grills must be fitted at the depth of 1/4" from the wall.

 Switchboards must be fitted to plum.

 Cover junction boxes with cement covers and not PVC covers. Use pin head type sheet metal screws (not MS).

Miscellaneous check:

	Video door phone to be provided		Modular kitchen workman ship	Modular kitchen to be provided
	⊡Yes □No		☐Good ☐Avg ☐Poor	☐Yes □No
The state of the s	Video door phone provided	workman ship & finishing	☐ Good ☐ Avg ☐ Poor Modular kitchen granite & dado	Modular kitchen provided
	□Yes □No		Good Avg Poor	✓Yes □No

	(14)	Rer	15	14	13	12	11	10	9	∞	7	6	Ŋ	4	w	2	Н	S No	
	SOMO	Remarks () Line	Other	Other	Foilet-3-	Toilet 2 C, Toi	Toilet 1 M. Toi	Kitchen	-Utility/balcony-3-	Utility / balcony-2.	-Utility-/ balcony 1	Lobby-1-	Dining	Drawing	Bedroom 3 Graged	Bedroom 2 K-Bed	Bedroom 1 M. Bec	Room	
		8			4	ζ	(1	1	<	!	1	1	ς	ς.	ς	ς	Door, door knob & door stopper fitting	
	大子	Y Y			}	(<	1	١	(1	1	1	ζ	<	ς	(Door, door knob & door stopper cleaning	
	NGK.	took of		anny.	1	(((1),,(J	ſ	1	}	1	ς	ς	(Window grills quality	Rate the quality of (Good
	15 P	5 Alea			-	<	ζ	7	-	١	1	١	-	l	(ζ	(Window grills fitting & finishing	quality of
	Rendin					<	ς	(1	1	1	١	١		ς	ς	(Windows quality	
(d ,					(ζ	<	١	1			•	1	ζ	<	<	Window fitting & finishing	V, Avg.
						1	1	-	-	١		1	•	1	1	1	1	Balcony railing quality & finishing	X, Poor
					-	9	-	1	1	ş	V	8	•	ı	١	1	-	French door quality & fitting	needs co
		3			•	<	<	4	•	<	V	1	•	Ť	1	ī	Á	CP jali quality and fitting	correction XX, NA)
					1	ς	ζ	<	C	ς	<	1	-	(5	5	<	Edge building	XX
					}	<	<	<		<	<	1	co	۲	<	5		Switch boards fitting & covering with plastic covers	VA)
	.40)	〈	<	<	-	<	<	١	ነ	ڒ	<	<	<	Junction box covers painting	