ľ	Juant	:
	Juality Control Check Repot.	
ı		
The second secon	Stage: After rimshing stage in (Apartments)	Line Ctore III (A)
	uai uiicii(s)	no reference for

		- 1	-	Т		
Recommendation: Stop further work. Subrementation: Stop further work. Proceed with further work. Proceed with further work.	Checked By MD on	Previous stage report no.	Project Manager	Prepared by	Company	Flat No
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required.		no.	Swys Redy Sign	Sismil-tunes	3 2 2	0-801
port to QC team. Proceder submitting ATR on sing corrections pointed ired.	MD Sign	114		Sign	Project	Other
eed only after recheck QC report to QC team		Report filed and signed by PM	7.81	2 10	MFG	
by QC. ATR not required.	For filling	d by PM	Date	Date	Phase	SI. No.
	Yes No	Yes No	10/4/18	10/4/18	H	49996

Inspection should be done after:

- Completing stage II works.
- Complete works like windows, grills, electrical wiring, switches, french door glass, etc.
- In case of modular kitchen provide platform, granite and dado and modular kitchen in this stage.
- Provide video door phone in this stage.
- Possession for wood work cannot be given until QC check for stage III is completed and all corrections mentioned in the report are made.

- Stage III check notes:

 1. Window grills must be fitted at the depth of 1/4" from the wall.

 2. Switchboards must be fitted to plum.
- Cover junction boxes with cement covers and not PVC covers. Use pin head type sheet metal screws (not MS).

Miscellaneous check:

☐ Yes ► No	Video door phone provided	⊠Yes □No	Video door phone to be provided
	workman ship & finishing		
☐ Good ☐ Avg ☐ Poor	☐ Good ☐ Avg ☐ Poor Modular kitchen granite & dado	Good Avg Poor	Modular kitchen workman ship
Yes No	Modular kitchen provided	☑Yes □No	Modular kitchen to be provided
			11.000