	Quality Control Check Repot.		Stage: After Finishing Stage III	ge III (Apartments)	
Flat No	208-0	Other		SI. No.	40002
Company	BNC	Project	MEG	Phase	2100
Prepared by	V. Ten Coll.	Sign	7.	Date	91/2/10
Project Manager	0110	Sign	7.4		81/03/18
Droman	COBPA RECOULTY	740	7	Date	21/50/18
revious stage report no.	no.	30003	Report filed and signed by PM		Yes No
Checked By MD on		MD Sign		For filling	Yes No
Recommendation:					
Stop further work. Stop further work.	Submit ATR on QC rep Proceed with work after	port to QC team. Prer submitting ATR	Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team.	by QC.	
Proceed with furth Proceed with furth	Proceed with further work only after making Proceed with further work. ATR not required	ng corrections poin red.	Proceed with further work only after making corrections pointed out in the QC report. ATR not required. Proceed with further work. ATR not required.	ATR not required.	
inspection should be done after:	after:				

- Completing stage II works.
- Complete works like windows, grills, electrical wiring, switches, french door glass, etc.
- In case of modular kitchen provide platform, granite and dado and modular kitchen in this stage.
- Provide video door phone in this stage.
- Possession for wood work cannot be given until QC check for stage III is completed and all corrections mentioned in the report are made.

Stage III check notes:

- Window grills must be fitted at the depth of 1/4" from the wall. Switchboards must be fitted to plum.
- Cover junction boxes with cement covers and not PVC covers. Use pin head type sheet metal screws (not MS).

Miscellaneous check:

video door phone to be provided	Tride de la constante de la co	induction workman ship	Modular kitchen to be provided
'MYes ∐No		Good Avg Poor	√Yes □No
Video door phone provided	workman ship & finishing	Good Avg Poor Modular kitchen granite & dado	Modular kitchen provided
□Yes \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\		Good VAvg Poor	NYes □No

	13	5	Remarks	15		L.	+-			1 9	×		10	١٠	n -	4	w	2	-	S No	
	commy your		arks yay Door	Other	Other	Tollet 3	Toilet 2 (CT)	Tollet I (MT)	Kitchen	Utility/-baleony-3	Utility Abaleony 2	Utility/ balcony 1	±obby I	Dining	Diawing	,	Bedroom 3 (6号)	Bedroom 2 (KB)		1	
	a grap		Madis			1	メメ		1	I	1	(1	1	<	\{\}	文	〈	·<	Door, door knob & door stopper fitting	
	35	1	est est				1	1	(1	1	{	((<		\	<u> </u>	<	Door, door knob & door stopper cleaning	
	2 fr	r	tica	•		1	<	<	<	1	<	 	[(1	<		<	<	Window grills quality	Rate the quality of (Good
	Ž.					}	<	<	<	1	<		1	1	1	k	,	メ	<	Window grills fitting & finishing	luality of
						1	۷.	<	<	1	<		(1	(K	×		5	Windows quality	1 1
ļ			ļ			1	<	<	<		<	1	[1	ſ	K		<	<	Window fitting & finishing	·, Avg. >
						}	1	ţ	-	-	١	<	!	1	ſ	1	١	,	1	Balcony railing quality & finishing	X, Poor-
						\ 	1	(ſ	1	1	<	-	1	1	(1	1	French door quality & fitting	needs ce
	ļ		-			(\	<	[1	2	<	Ţ	l	ſ	1		1	(CP jali quality and fitting	needs correction XX, NA)
		1				1	<u> </u>	{	1	F	<u>ر</u> ا		-	<	<	<	<	(,		Edge building	X X
						1	<	<	<		<	۲	(<	<	<	K	\ \	\ c	Switch boards fitting & covering with plastic covers	(A)
							<	<	1		\	×	1		5	<	<			Junction box covers painting	