Quality
Control
Quality Control Check Repot.
Stage: Al
ter Finishing
hing Stage III
Stage: After Finishing Stage III (Apartments

Flat No Project Pro)		21 71	
Project RAC Sign Red Sign Afg Phase Project Phase Project Phase Afg Phase Project Phase Project Phase Project Phase Project Phase Phase	Flat No	7 - 806	Other		SI. No.	30252
Sign Construct Sign Sign Construct Sign Sign Date Sign MD on MD Sign MD Sign And Sign Report filed and signed by PM ation: ation: her work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. her work only after making corrections pointed out in the QC report. ATR not required. with further work ATR not required.	Company	BNC	Project	MFG	Phase	13
ort no. Sign 2997 Report filed and signed by PM MD Sign MD Sign MD Sign Report filed and signed by PM For filling For filling rk. Submit ATR on QC report to QC team. Proceed only after recheck by QC. ork. Proceed with work after submitting ATR on QC report to QC team. urther work only after making corrections pointed out in the QC report. ATR not required.	Prepared by		Sign	Pray	Date	14/5/18
ort no. 29977 Report filed and signed by PM MD Sign MD Sign For filling rk. Submit ATR on QC report to QC team. Proceed only after recheck by QC. ork. Proceed with work after submitting ATR on QC report to QC team. urther work only after making corrections pointed out in the QC report. ATR not required.	Project Manager	2000000	Sign	roll-	Date	14/5/18
m MD Sign For filling rk. Submit ATR on QC report to QC team. Proceed only after recheck by QC. ork. Proceed with work after submitting ATR on QC report to QC team. urther work only after making corrections pointed out in the QC report. ATR not required. urther work. ATR not required.	Previous stage report	no.	29977	Report filed and signe	d by PM	∏Yes □No
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required. Proceed with further work. ATR not required.	Checked By MD on		MD Sign		For filling	Yes No
	Recommendation: Stop further work. Stop further work Proceed with furtl Proceed with furtl	Submit ATR on QC re Proceed with work aft her work only after mak her work. ATR not requ	port to QC team. Proces reasonable to QC team. Proces reasonable to QC team. Process reasonable to QC team.	eed only after recheck! QC report to QC team! I out in the QC report.	by QC. ATR not required.	

- Completing stage II works.

 Complete works like doors, windows, grills, electrical wiring, switches, french door glass, etc.

 In case of modular kitchen provide platform, granite and dado and modular kitchen in this stage.

 Provide video door phone in this stage.

 Possession for wood work cannot be given until QC check for stage III is completed and all corrections mentioned in the report are made.

- Stage III check notes:

 1. Window grills must be fitted at the depth of ¼" from the wall.

 2. Switchboards must be fitted to plum.
- Cover junction boxes with cement covers and not PVC covers. Use pin head type sheet metal screws (not MS).

Miscellaneous check:

☐ Yes ☐ No	Video door phone provided	No □No	Video door phone to be provided
	workman ship & finishing	•	
Good Avg Poor	☐ Good ☐ Avg ☐ Poor Modular kitchen granite & dado	☐ Good ☐ Avg ☐ Poor	Modular kitchen workman ship
□Yes □No)	Modular kitchen provided	Yes No	Modular kitchen to be provided
		, , , , , , , , , , , , , , , , , , ,	MISCELIANCOUS CHECK.

4. 30

7.2

Dining

Lobby-1-

Drawing

Bedroom 3 Bedroom 2 Bedroom 1

S No

Room

covers

painting

人

人

Junction box covers

15 Other

2

Other

Toilet 3 Toilet 2 Toilet 1 Kitchen