<u>0</u>
alit
Cor
trol
rol Check Repot.
ck Rep
epot
ľ
Sta
ge:/
fter
· Fin
ishii
1g S1
age
III (
Apa
rtme
ents)

Flat No		()+h			
	E-803	OHEL		SI. No.	32233
Company	BNC	Project	mF6	Phase	≈)
Prepared by	Sikuldup	Sign	Aludero	Date	29/11/18
Project Manager	Subba Riddys.v	Sign	Date Date	Date	8/11/16
Previous stage report no.	no.	32158	Report filed and signed by PM	d by PM	Yes No
Checked By MD on	, ,	MD Sign		For filling	☐Yes ☐No
Recommendation:					
Stop further work.	Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team.	port to QC team. Proce er submitting ATR on	eed only after recheck b	y QC.	
Proceed with furth	Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	ing corrections pointed	out in the QC report. /	VTR not required.	
Proceed with furth	Proceed with further work. ATR not required.	red.	,	>	
the state of the s	•				

- Inspection should be done after:
 Completing stage II works.
 Complete works like windows, grills, electrical wiring, switches, french door glass, etc.
 In case of modular kitchen provide platform, granite and dado and modular kitchen in this stage.
- Provide video door phone in this stage.

 Possession for wood work cannot be given until QC check for stage III is completed and all corrections mentioned in the report are made.

- Stage III check notes:

 1. Window grills must be fitted at the depth of 1/4" from the wall.
- Switchboards must be fitted to plum.

 Cover junction boxes with cement covers and not PVC covers. Use pin head type sheet metal screws (not MS).

Miscellaneous check:

Video door phone to be provided		Modular kitchen workman ship	Modular kitchen to be provided
MYes □No		Good Avg Poor	☐Yes ☐No
Video door phone provided	workman ship & finishing	Good Avg Poor Modular kitchen granite & dado	Modular kitchen provided
☐Yes ☐No	1	Good Avg Poor	☐Yes ☐No ~