	Quality Control Check Repot.		Stage: After Finishing Stage III (Apartments)	e III (Apartments)	
Flat No	F - 603	Other		SI. No.	
Company		Project	3	Phase	29403
Prepared by		2	TIKES .		<u> </u>
	B SUNC ACCORDING	Sign	7	Date	201010
Project Manager	Sabbo Ro Laty. Sign	Sign		Date	8119180
Previous stage report no.	10.		Report filed and signed by DM		8119180
Checked By MD on		CURTH	C		I cs No
Cilculation by MID on		MD Sign		For filling	Yes No
Recommendation:					
Stop further work. Stop further work. Proceed with furthe	Stop further work. Submit ATR on QC report Stop further work. Proceed with work after some proceed with further work only after making of the proceed with further work. ATR not required.	oort to QC team. Pro or submitting ATR on ng corrections point	Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	y QC. .TR not required.	
Inspection should be done after:	ifter:	led.			

Quality Control Check Repot.

- Completing stage II works.

 Complete works like windows, grills, electrical wiring, switches, french door glass, etc.
- In case of modular kitchen provide platform, granite and dado and modular kitchen in this stage.
- Provide video door phone in this stage.
- Possession for wood work cannot be given until QC check for stage III is completed and all corrections mentioned in the report are made.

- Stage III check notes:

 1. Window grills must be fitted at the depth of 1/4" from the wall.

 2. Switchboards must be fitted to plum.
- Cover junction boxes with cement covers and not PVC covers. Use pin head type sheet metal screws (not MS).

Miscellaneous check:

viaco don phone to be provided	Video door should	mosaia Michell Workhian Ship	Modular bitchen workman aki	Modular kitchen to be provided
Yes No		Good Avg Poor		Yes No
Video door phone provided	workman ship & finishing	Modular kitchen granite & dado	The state of the s	Modular kitchen provided
Yes No	[] o	Good Avo Poor	Xes No	

7.0	15	14	13	12	=	10	9	∞	7	6	S	4	w	2	<u> </u>	S No	
 Remarks X Wallig	Other	Other	Toilet 3	<u> </u>	Toilet 1 MATON		Utility-balcony 3	Utility / balcony 2-	Utility-/ balcony 1	Lobby-1	Dining	Drawing	Bedroom 3 Gr. Bed	Bedroom 2 K. Bed	Bedroom 1 M. Bed	Room	
Grail				<	ς.	1	j	ς	ı	1	1	<	<	ς	ζ	Door, door knob & door stopper fitting	
Gaill mit				ζ	ζ	1	i	<	1	1	t	ζ.	(<	(Door, door knob & door stopper cleaning	
Pito co				<	ς	ς	1	10	1	1	1	١	<	<	ζ,	Window grills quality	Rate the quality of (Good
ed.				(<	<	-	J	(1	-	(((<	Window grills fitting & finishing	quality of
				ζ	<	<	١	1	(1	1	1	(ζ	(Windows quality	1
				ζ	<	ζ	-	1	1	1	1	١	<	(۷	Window fitting & finishing	V, Avg.
				1	1	Į.	1	1	<		-	1	1	1	1	Balcony railing quality & finishing	X, Poor-
				4	1	-	*	1	<	1	•	*	١	1	1	French door quality & fitting	– needs c
				ζ	<	١	gram.	(<	•	1	1	1	•	3	CP jali quality and fitting	ceds correction XX, NA)
8				<	ζ.	×		<	<	1	-	((ζ	<	Edge building	× ×,
				<	<	<	١	ς	ζ	١)	<	ς.	<		Switch boards fitting & covering with plastic covers	VA)
				<	<	<	١	<	ζ.	١	\	ζ	(<u></u>	ζ.	Junction box covers painting	

Quality Control Check Repot. Stage: After Finishing Stage III (Apartments)