Quality Control Check Repot. Stage: After Finishing Stage III (Apartments)

Flat No	D-204	Other		SI. No.	32040
Company	Vista Holmes	Project	Nista Homes	Phase	1
Prepared by	_	Sign		Date	12/11/18
Project Manager	T. Machic	Sign	Maylun	Date	18/11/18
Previous stage report no.	no.	31989	Report filed and signed by PM	d by PM	Yes No
Checked By MD on		MD Sign		For filling	☐Yes ☐No
Recommendation: Stop further work. Subnestion should be done after a few or the commendation: Recommendation: Proceed with further works. Proceed with further works.	Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	port to QC team. Proceer submitting ATR on ng corrections pointed red.	eed only after recheck b QC report to QC team. I out in the QC report. !	y QC. VTR not required.	

- Completing stage II works.
- Complete works like windows, grills, electrical wiring, switches, french door glass, etc. In case of modular kitchen provide platform, granite and dado and modular kitchen in this stage.
- Provide video door phone in this stage.
- Possession for wood work cannot be given until QC check for stage III is completed and all corrections mentioned in the report are made.

- Stage III check notes:
 Window grills must be fitted at the depth of ½" from the wall.
 Switchboards must be fitted to plum.
- Cover junction boxes with cement covers and not PVC covers. Use pin head type sheet metal screws (not MS).

Miscellaneous check:

	_		
Video door phone to be provided		Modular kitchen workman ship	Modular kitchen to be provided
Yes No		Good Avg Poor	☐Yes ☐No
Video door phone provided	workman ship & finishing	Good Mayg Poor Modular kitchen granite & dado	Modular kitchen provided
□Yes □No		☐ Good ☐ Avg ☐ Poor	☐Yes ☐No

1

Ren	15	14	13	12	11	10	9	8	7	6	5	4	ß	2	_	S No	
Remarks @ windows	Other	Other	Toilet 3	Toilet 2 Cてめ	Toilet 1 M. To	Kitchen	-Utility/balcony-3-	Utility / balcony-2	Hility/balcony 1	Lobby-1	Dining	Drawing	ယ (Bedroom 2 K-Be	Bedroom 1 M.Bed	Room	(B)
				(`	1	1	<	1	1	1	<	ς.	ζ	7	Door, door knob & door stopper fitting	
blunder				(ζ.	1	B	ζ	1	ſ	ſ	ς	ς.	ζ	;	Door, door knob & door stopper cleaning	
pe 0				ζ	ς	<		ς	ſ	-	1	1	ζ	<	ς	Window grills quality	Rate the quality of (Good
cleaned				<	(ζ	ļ	5		1	١	1	ζ	(5	Window grills fitting & finishing	quality of
9				ζ	(4	1	1	ſ		1	1	ς,	5	ς	Windows quality	(Good ✓
				4	ζ	۲		1	1	ţ	1	1	(ζ	<	Window fitting & finishing	, Avg.
				١	j	1	1	1	ζ.		})	1			Balcony railing quality & finishing	X, Poor-
				1	}	tow-	-	-	ς	1		3	1	1	1	French door quality & fitting	– needs co
				(ζ	١	•	ζ	3	1	1	1	1	1	1	CP jali quality and fitting	needs correction
				(<	3	1	X	×	1		ζ	ζ	ζ	<	Edge building	XX, NA)
				ζ	<	ζ	١	ζ	ζ	1		<	ς	<	ζ	Switch boards fitting & covering with plastic covers	VA)
				<	<	Ç)	٤	<	١)	<	ζ	(<	Junction box covers painting	