I	0
	uality
	Quality Control Check Repot.
	Check 1
	Repot.
	Stage:
	After
	Stage: After Finishing Stage II (Apartments)
	Stage II
	(Apartm

Flat No	G-006	Other	1	SI. No.	28801
Company	VISTA HOMES Project	Project	VISTA HOMES	Phase	1
Prepared by	M. Tela Sinder Sign	Sign	4	Date	41/21/48
Project Manager	- Medhu	Sign	7mly	Date	4) 21/48
Previous stage report no.	no.	28449	Report filed and signed by PM	d by PM	⊠Yes □No
Checked By MD on		MD Sign		For filling	Yes No
Recommendation: Stop further work. Sub Stop further work. Pro Proceed with further w	Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR n. Proceed with further work. ATR not required.	port to QC team. Procer submitting ATR on ing corrections pointedired.	eed only after recheck be QC report to QC team. I out in the QC report.	y QC. ATR not required.	

- Inspection should be done after:
 Completion of flooring, bathroom /utility tiles, doors & beading, first coat of paint.
 Completion of windows, grills, electrical wiring, switches must be done in next stage
- False ceiling must be completed before flooring.
- Kitchen platform, granite and dado must be completed where modular kitchen is not provided.
- Provide granite soffit for main door and balconies in this stage.

Miscellaneous check:

False ceiling to be provided? MYes No False ceiling workmanship	polishing	Main door granite soffit workmanship ☐ Good ☒ Avg ☐ Poor Main door granite soffit edge	Granite soffit for main door required Yes No Granite soffit for main door provided	Balcony granite soffit workmanship Good Avg Poor Balcony granite soffit edge polishing Good Avg Poor	Granite soffit for balcony required Yes No Granite soffit for balcony provided	
	oolishing		Granite soffit for main door provided \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	Balcony granite soffit edge polishing		
☐ Good ☐ Avg ☐ Poor		☐Good ☑Avg ☐ Poor	JYes No]Good [Avg ∏Po	NYes □No	1

Ren	9	∞		9		S	4	w	1	~	S No	
Remarks	Other .	Other	Utility	Kitchen	dining area	Wash-basin in	Teilet-4	Foilet 3	1011et 7 (CL)	Tollet 1 (M)	Room	Tiling & granite
			<	3		(١	-	<	, <	Workmanship of tiling	
e e			<	1			•	ļ	<	<	White cement filling around CPVC lines	
			<	1	50.01	1	}	;	<	<	Corners finishing	Rate th
			<	1		1	1		<	<	Finishing near doors	Rate the quality of (Good , Avg. X, Poor
			<	1		1		1	<u>ر</u>	<	Finishing on top of tiles	of (Goo
			1	1		1			<	<	Finishing near ventilators	d •, A
-			<	[ſ] }		<	<	Step at bathroom entrance / utility	vg. ×, I
			<	-	ě	1	1	1	<	5	wash	1
			<	ţ]]		<u> </u>	<u> </u>	Tile joint grouting	eds corr
			1	<		1		-		j	Granite platform finishing and edge polishing	ection X
			1	<	1]	1		1	J	Granite platform slope	needs correction XX. NA)
			/		ĺ				-	j	Granite platform height	
			G C		1		1				Finishing under granite platform	