Recommendation: Checked By MD on Previous stage report no. Prepared by Project Manager Company Flat No Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work. ATR not required. Proceed with further work only after making corrections pointed out in the QC report. ATR not required. VISTA HOMES M-Tigasindher Quality Control Check Repot. 1. Madhu 501-105 Sign MD Sign Sign Project Other: 30483 Stage: After Finishing Stage III (Apartments) Report filed and signed by PM VISTA 工型了 1 HOY D Date SI. No. For filling Date Phase Yes 12/06/18 20 Yes 30513 90 No No  $\infty$ 

Inspection should be done after:

- Completing stage II works.
- Complete works like windows, grills, electrical wiring, switches, french door glass, etc
- In case of modular kitchen provide platform, granite and dado and modular kitchen in this stage.
- Provide video door phone in this stage.
- Possession for wood work cannot be given until QC check for stage III is completed and all corrections mentioned in the report are made.

## Stage III check notes:

- Window grills must be fitted at the depth of 1/4" from the wall
- Switchboards must be fitted to plum.
- Cover junction boxes with cement covers and not PVC covers. Use pin head type sheet metal screws (not MS).

## Miscellaneous check:

Video door phone to be provided		Modular kitchen workman ship	Modular kitchen to be provided	
Yes No		Good Avg Poor Modular kitchen granite	Nes □No	
Video door phone provided	workman ship & finishing	Modular kitchen granite & dado	Modular kitchen provided	
☐ Yes ☑No		Good NAvg Poor	\\ Yes □No	