Ouality Control
ity Control Check Repot.
Stage: Aft
er Finishing Sı
Stage: After Finishing Stage II (Apartments)
ents)

Flat No	R-206	Other		SI. No.	28903·
Company	Rayon Utsta	Project	Visita Homes	Phase	٦
Prepared by	3	Sign	M	Date	06/01/18
Project Manager		Sign	Peullin	Date	96)01/18
Previous stage report no.	no.	98558	Report filed and signed by PM	d by PM	☐Yes
Checked By MD on		MD Sign		For filling	Yes No
Recommendation: Stop further work.	ecommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck	port to QC team. Proc	eed only after recheck l	c by QC.	
Stop further work. Proceed with furth	Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report.	er submitting ATR on ing corrections pointed		ATR not required.	
Proceed with furth	Proceed with further work. ATR not required	ired.			

Inspection should be done after:

- Completion of flooring, bathroom /utility tiles, doors & beading, first coat of paint. Completion of windows, grills, electrical wiring, switches must be done in next stage
- False ceiling must be completed before flooring.
- Kitchen platform, granite and dado must be completed where modular kitchen is not provided.
- Provide granite soffit for main door and balconies in this stage.

Miscellaneous check:

Good Avg Poor	False ceiling workmanship	☐ Yes ☐ No	False ceiling to be provided?
	polishing		
☐ Good ☐ Avg ☐ Poor	Main door granite soffit edge	☐Good ☑Avg☐Poor	Main door granite soffit workmanship Good Avg Poor Main door granite soffit edge
door provided Yes No	Granite soffit for main door provided	∐Yes □No	Granite soffit for main door required Yes No
Good Avg Poor	Balcony granite soffit edge polishing	☐ Good ☐ Avg ☐ Poor Balcony granite soffit	Balcony granite soffit workmanship
Yes No	Granite soffit for balcony provided	□Yes □No	Granite soffit for balcony required
		☑Yes ☐No	Main door fixed with lock & stopper Yes No

Ren	9	8	7	6	5	4	3	2	1	S No	
Remarks	Other	Other	Utility	Kitchen	Wash basin dining area	- Teilet-4	Toilet 3	Toilet 2	Toilet 1	Room	Tiling & granite work
				100 Marian Coly	in in			CLO	MITO		granite
.			ς	ζ	1	1	-	۲	ς	Workmanship of tiling	
			ς	(1	١	1	7	(White cement filling around CPVC lines	
			<	<	1	1	1	۲	(Corners finishing	Rate the
			<	1	1	1	1	ζ	(Finishing near doors	Rate the quality of (Good , Avg. X, Poor
			((1	1	1	(ζ	Finishing on top of tiles	of (Good
			١	3	1	1	1	(٢	Finishing near ventilators	·, Av
			ς	(1	1	٩	(5	Step at bathroom entrance / utility	g. X, Pa
			<	ς	1	1		\	7	Step for shower / pot wash	00r – nee
	1		×	1.		٩	e	Y).	Tile joint grouting	ds corre
			1	5	1	1	1	1	1	Granite platform finishing and edge polishing	- needs correction XX. NA)
				(1	1	1	1	1	Granite platform slope	X, NA)
(2)			1	<		}	f	1	1	Granite platform height	
			1	<	Ì)	,	١	1	Finishing under granite platform	