Quality Co
Control (
Quality Control Check Repot.
Stage: After Finishing Stage III (Villas)
Finishing Stage III (
e III (Villas

Sov (LLP)  A by  Manager  Mana	[]		)			
Sov(LLP) Project Sov Phase  T. Vivlod Kurnax Sign T. Van B. Kurnas Date  W. Pusus hotkam Sign Report filed and signed by PM  ort no. 32762 Report filed and signed by PM  rk. Submit ATR on QC report to QC team. Proceed only after recheck by QC. ork. Proceed with work after submitting ATR on QC report to QC team. urther work only after making corrections pointed out in the QC report. ATR not required.	Flat No	70	Other		Sl. No.	22658
To Vividad Kurnay  Sign  Report filed and signed by PM  The Report filed and signed by	Company		Project	200	Phase	X
ort no.  Sign  Ort no.  Report filed and signed by PM  MD Sign  MD Sign  Report filed and signed by PM  For filling  rk. Submit ATR on QC report to QC team. Proceed only after recheck by QC. ork. Proceed with work after submitting ATR on QC report to QC team. urther work only after making corrections pointed out in the QC report. ATR not required. urther work. ATR not required.	Prepared by			T. Vin Adhima	Date	27/05/19
ort no.    32762   Report filed and signed by PM     m	Project Manager			X.	Date	27/05/19
MD Sign  For filling  rk. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  ork. Proceed with work after submitting ATR on QC report to QC team.  urther work only after making corrections pointed out in the QC report. ATR not required.  urther work. ATR not required.	Previous stage report		32762	Report filed and signe	d by PM	Yes No
Recommendation:  Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	Checked By MD on		MD Sign		For filling	☐Yes ☐No
Inspection should be done offer.	Recommendation:  Stop further work.  Stop further work.  Proceed with furth Proceed with furth	Submit ATR on QC re Proceed with work aft per work only after making work. ATR not requi	port to QC team. Proceer submitting ATR on ing corrections pointedired.	eed only after recheck l QC report to QC team. I out in the QC report.	by QC.  ATR not required.	

- Completing stage II works.
- Complete works like windows, grills, electrical wiring, switches, french door glass, etc.
- In case of modular kitchen provide platform, granite and dado and modular kitchen in this stage.
- Provide video door phone in this stage.

  Possession for wood work cannot be given until QC check for stage III is completed and all corrections mentioned in the report are made.

- Stage III check notes:

  1. Window grills must be fitted at the depth of 1/2" from the wall.
- Switchboards must be fitted to plum.
- Cover junction boxes with cement covers and not PVC covers. Use pin head type sheet metal screws (not MS).

## Miscellaneous check:

Video door phone to be provided	1771	Modular kitchen workman ship	Modular kitchen to be provided
✓ Yes ☐ No		Good Avg Poor	☐Yes ☑No
Video door phone provided	workman ship & finishing	Good Avg Poor Modular kitchen granite & dado	Modular kitchen provided
☐Yes ☐No		Good Avg Poor	□Yes □No —

## Quality Control Check Repot. Stage: After Finishing Stage III (Villas)

2. Without doing self-check	Demode	Quality and workmanship of lawn	Cleaning/painting of external cladding/texture	Painting of gates & railings	Quality and workmanship of railings	Quality and workmanship of gate	Miscellaneous check - after finishing stage III
Site Enginees (Suman) A raising by check,		Good Avg. Poor	Good Navg. Poor	Good NAvg. Poor	☐ Good ☑ Avg. ☐ Poor	Good Avg. Poor	