

Quality Control Check Report. Stage: After Finishing Stage II (Villas)

| | | | | | |
|---------------------------|------------|---------|--|-------------------------------|---------------------------------------------------------------------|
| Flat No | 200 | Other | | Sl. No. | 33016 |
| Company | Vec CLIP) | Project | | Phase | - |
| Prepared by | V. Sanketh | Sign | | Date | 26/2/19 |
| Project Manager | A. Suresh | Sign | | Date | 26/2/19 |
| Previous stage report no. | | 31834 | | Report filed and signed by PM | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No |
| Checked By MD on | | MD Sign | | For filling | <input type="checkbox"/> Yes <input type="checkbox"/> No |

Recommendation:

- Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.
- Stop further work. Proceed with work after submitting ATR on QC report to QC team.
- Proceed with further work only after making corrections pointed out in the QC report. ATR not required.
- Proceed with further work. ATR not required.

Inspection should be done after:

- Completion of flooring, bathroom /utility tiles, doors & beading, first coat of paint.
- Completion of windows, grills, electrical wiring, switches must be done in next stage
- False ceiling must be completed before flooring.
- Kitchen platform, granite and dado must be completed where modular kitchen is not provided.
- Provide granite soffit for main door in this stage.

Miscellaneous check:

| | | | |
|---------------------------------------|------------------------------------------------------------------------------------------|-----------------------------------------|------------------------------------------------------------------------------------------|
| Main door fixed with lock & stopper | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | | |
| Granite soffit for main door required | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | Granite soffit for main door provided | <input type="checkbox"/> Yes <input type="checkbox"/> No |
| Main door granite soffit workmanship | <input type="checkbox"/> Good <input type="checkbox"/> Avg <input type="checkbox"/> Poor | Main door granite soffit edge polishing | <input type="checkbox"/> Good <input type="checkbox"/> Avg <input type="checkbox"/> Poor |

Quality Control Check Report. Stage: After Finishing Stage II (Villas)

| Tiling & granite work | | Rate the quality of (Good ✓, Avg. X, Poor – needs correction XX, NA) | | | | | | | | | | | | |
|-----------------------|---------------------------|----------------------------------------------------------------------|----------------------------------------|-------------------|----------------------|---------------------------|----------------------------|-------------------------------------|----------------------------|---------------------|-----------------------------------------------|------------------------|-------------------------|----------------------------------|
| S No | Room | Workmanship of tiling | White cement filling around CPVC lines | Corners finishing | Finishing near doors | Finishing on top of tiles | Finishing near ventilators | Step at bathroom entrance / utility | Step for shower / pot wash | Tile joint grouting | Granite platform finishing and edge polishing | Granite platform slope | Granite platform height | Finishing under granite platform |
| 1 | Toilet 1 G-Toi | ✓ | ✓ | ✓ | X | ✓ | X | ✓ | ✓ | ✓ | - | - | - | - |
| 2 | Toilet 2 M-Toi | ✓ | ✓ | ✓ | ✓ | ✓ | X | ✓ | ✓ | ✓ | - | - | - | - |
| 3 | Toilet 3 K-Toi | ✓ | ✓ | ✓ | ✓ | X | X | ✓ | ✓ | ✓ | - | - | - | - |
| 4 | Toilet 4 | - | - | - | ✓ | - | X | - | ✓ | ✓ | - | - | - | - |
| 5 | Wash basin in dining area | - | - | - | - | - | - | - | - | - | - | - | - | - |
| 6 | Kitchen | ✓ | ✓ | ✓ | - | - | X | - | - | ✓ | ✓ | ✓ | ✓ | - |
| 7 | Utility | ✓ | ✓ | ✓ | ✓ | ✓ | X | - | - | ✓ | ✓ | ✓ | ✓ | X |
| 8 | Portico | | | | | | | | | | | | | |
| 9 | Other | | | | | | | | | | | | | |
| Remarks | | | | | | | | | | | | | | |

| S No | Room | Rate the quality of (Good ✓, Avg. ✕, Poor – needs correction ✕✕, NA) | | | | | | | | | | | | |
|---------|---------------------|--------------------------------------------------------------------------------------------------------------------------------------|---------------------------------|--------------------|----------------------|---------------------------|---------------------------------|---------------|----------------|-----------------------------------------|-------------------------------|--------------------------------------------|---------------|--|
| | | Color variation of floor tiles | Flooring workmanship & grouting | Skirting size (3") | Skirting workmanship | Plastering above skirting | Plastering & finishing of walls | Crack filling | Loft Finishing | General quality of painting & finishing | Door & frame painting quality | Door beading, luppam and painting quality. | Edge building | |
| 1. | Bedroom 1 G.B | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | |
| 2. | Bedroom 2 M.B | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | |
| 3. | Bedroom 3 K.B | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | |
| 4. | Bedroom 4 | - | - | - | - | - | - | - | - | - | - | - | - | |
| 5. | Drawing | ✓ | ✕✕ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | |
| 6. | Dining | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | |
| 7. | Lobby 1 Lounge | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | |
| 8. | Lobby 2 Ruja | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | |
| 9. | Terrace/ balcony 1 | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | |
| 10. | Terrace-/ balcony 2 | - | - | - | - | - | - | - | - | - | - | - | - | |
| 11. | Head room | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | |
| 12. | Portico | - | - | - | - | - | - | - | - | - | - | - | - | |
| 13. | Kitchen | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | |
| 14. | Utility | ✓ | - | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | |
| 15. | Other | ✓ | - | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | |
| Remarks | | <p>✕✕ Instead of full Tiles they laid cut piece Tiles in Drawing.</p> <p>✕✕ No. of skirting piece not provided in family lounge.</p> | | | | | | | | | | | | |

Quality Control Check Report. Stage: After Finishing Stage II (Villas)

| | | | |
|-------------------------------------------------------|-----------------------------------------------|------------------------------------------|-------------------------------|
| Miscellaneous check after finishing stage II | <input type="checkbox"/> Good | <input checked="" type="checkbox"/> Avg. | <input type="checkbox"/> Poor |
| Quality and workmanship of portico tiles | <input type="checkbox"/> Good | <input checked="" type="checkbox"/> Avg. | <input type="checkbox"/> Poor |
| Quality and workmanship of flooring & setbacks | <input type="checkbox"/> Good | <input checked="" type="checkbox"/> Avg. | <input type="checkbox"/> Poor |
| Quality and workmanship of external cladding/ texture | <input type="checkbox"/> Good | <input checked="" type="checkbox"/> Avg. | <input type="checkbox"/> Poor |
| Remarks: | all Screws not fixed by villa external walls. | | |