Quality Control Check Repot. Stage: After Finishing Stage II (Villas)

Flat No	2.8	Other		Sl. No.	32688
Company	トルン	Project	Blogmadale	Phase	1
Prepared by	S. Kuldeep	Sign	Duldung-	Date	18/10/19
Project Manager	Bala musali Rushna Sign	Sign	(pand	Date	18/01/17
Previous stage report no.	no.	31707	Report filed and signed by PM	d by PM	LYes □No
Checked By MD on		MD Sign		For filling	☐ Yes ☐ No
Recommendation: Stop further work. Submi Stop further work. Proce Proceed with further worl Proceed with further worl	Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required Proceed with further work. ATR not required.	port to QC team. Proceer submitting ATR on ing corrections pointedired.	eed only after recheck be QC report to QC team. I out in the QC report.	y QC. ATR not required.	

Inspection should be done after:

- Completion of flooring, bathroom /utility tiles, doors & beading, first coat of paint. Completion of windows, grills, electrical wiring, switches must be done in next stage
- False ceiling must be completed before flooring.
- Kitchen platform, granite and dado must be completed where modular kitchen is not provided.
- Provide granite soffit for main door in this stage.

Miscellaneous check:

	polishing	1	
Good Avg Poor	Main door granite soffit edge	Good Avg Poor	Main door granite soffit workmanship Good Avg Poor Main door granite
☐Yes ☐No -	Granite soffit for main door provided	☐Yes ZÑo	Granite soffit for main door required
	the second statement	Yes No	Main door fixed with lock & stopper

N

S No

7 0

 ∞

Quality Control Check Repot. Stage: After Finishing Stage II (Villas)

	Miscellaneous check after finishing stage II	
	Quality and workmanship of portico tiles	☐ Good A Avg. ☐ Poor
	Quality and workmanship of flooring & setbacks	Good Avg. Poor
200	Quality and workmanship of external cladding/ texture	Good Avg. Poor
	Remarks:	
0.00		