Quality Control Check Repot.
Stage: After Finishing Stage III (VIII

Flat No	51	Other		Sl. No.	27506
Company	xlilgani estati Project	Project	Niloni estate	Phase	F
Prepared by	P. Sa Kwar	Sign	Prody	Date	41418
Project Manager	Rosleshyon	Sign	Report	Date	カニカト
Previous stage report no.	no.	27512	Report filed and signed by PM	d by PM	☐Yes ☐No
Checked By MD on		MD Sign		For filling	☐Yes ☐No
Recommendation:  Stop further work. Subnessed with further work. Proceed with further work. Proceed with further works after the spection should be done after the specific specifi	Recommendation:  Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. ATR not required.  Proceed with further work. ATR not required.	port to QC team. Procer submitting ATR on ing corrections pointedired.	eed only after recheck be QC report to QC team. I out in the QC report. A	yy QC. ATR not required.	

- Completing stage II works.
- Complete works like windows, grills, electrical wiring, switches, french door glass, etc.
- In case of modular kitchen provide platform, granite and dado and modular kitchen in this stage.
- Provide video door phone in this stage.
- Possession for wood work cannot be given until QC check for stage III is completed and all corrections mentioned in the report are made.

- 1. Window grills must be fitted at the depth of 1/4" from the wall.
- Switchboards must be fitted to plum.
- Cover junction boxes with cement covers and not PVC covers. Usc pin head type sheet metal screws (not MS).

## Miscellaneous check:

	r-	т-		
	Video door phone to be provided		Modular kıtchen workman ship	Modular kitchen to be provided
0.000	∐ Yes	]	☐ Goo	Yes
	∐Yes ∐No —		d   Av	Yes \No
	-	}	g Poor	
	Video door phone provided	workman ship & finishing	Good Avg Poor Modular kitchen granite & dado	Modular kitchen provided
	☐ Yes ☐ No		Good Avg Poor	Tes Tyno

10

S No

Room

Junction box covers

painting

## Quality Control Check Repot. Stage: After Finishing Stage III (Villas)

Miscellaneous check - after finishing stage III	
Quality and workmanship of gate	Good: Avg. Poor
Quality and workmanship of railings	Good Avg. Poor
Painting of gates & railings	☐ Good ☑ Avg. ☐ Poor
Cleaning/painting of external cladding/texture	Good Avg. Poor
Quality and workmanship of lawn	Good Navg. Poor
Remarks:	