	uality
THE PERSON NAMED IN COLUMN TWO IS NOT THE OWNER, THE OW	Control
The state of the s	uality Control Check Repot. S
	Stage: After
The second secon	Stage: After Finishing Stage II (Villas)
	tage II (Villas

Flat No	48	Other		SI. No.	23783
Company	VOC(119)	Project	70C	Phase	(
Prepared by	2	Sign	Throof hund	Date	13/06/19
Project Manager		Sign	₹.	Date	13/06/19
Previous stage report no.	no.	33251	Report filed and signed by	d by PM	Yes No
Checked By MD on		MD Sign		For filling	Yes No
Recommendation: Stop further work. Stop further work. Proceed with furth	Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required. Proceed with further work. ATR not required.	port to QC team. Proceed ter submitting ATR on the corrections pointed ired.	eed only after recheck b QC report to QC team. d out in the QC report. 1	ATR not required.	

Inspection should be done after:

- Completion of flooring, bathroom /utility tiles, doors & beading, first coat of paint. Completion of windows, grills, electrical wiring, switches must be done in next stage

- False ceiling must be completed before flooring.

 Kitchen platform, granite and dado must be completed where modular kitchen is not provided.

 Provide granite soffit for main door in this stage.

		•		
	Main door granite soffit workmanship Good Avg Poor Main door granite soffit ec	Granite soffit for main door required Yes No	Main door fixed with lock & stopper ☐ Yes ☐ No	IVIISCEITATICOUS CITECA.
	☐ Good ☐ Avg ☐ Poor	☐ Yes ☑ No	✓ Yes □No	
polishing	Main door granite soffit edge	Granite soffit for main door provided		
1	Good Avg Poor	☐Yes ☐No		

Ren	9	∞	7	6		S	4	w	2	1	S No	
Remarks	Other	Portico	Utility	Kitchen	dining area	Wash basin in	Foilet 4	Toilet 3 G.T	Toilet 2 C.T	Toilet 1 M.T	Room	Tiling & granite work
			<	<	1			?	1	1	Workmanship of tiling	· ·
			<	7	1		ı	×	×	×	White cement filling around CPVC lines	
			<	<	١		1	<	7	1	Corners finishing	Rate th
			<	1	1		1	<	<	(Finishing near doors	Rate the quality of (Good , Avg. X, Poor – needs correction X X, NA)
			<	<	1		1	(5	5	Finishing on top of tiles	of (Goo
			1	<	1		1	7	<	<	Finishing near ventilators	d ~, A
			<	1	1		1	<	<	<	Step at bathroom entrance / utility	vg. X , F
			<	1	1		1	<	<	<	Step for shower / pot wash	00r – ne
			<	<	1		1	1	7	<	Tile joint grouting	eds corre
			1	<	1		1	1	1	1	Granite platform finishing and edge polishing	ction X
			1	<	1		1	1	1	1	Granite platform slope	X, NA)
			1	<			1	1	1	1	Granite platform height	
)	9	1		1	1	1	1	Finishing under granite platform	

H		Γ	Г		Γ			Г	Г		Г	1		T			
Remarks	15.	14.	13.	12.	17.	10.	9.	.∞	7.	6.	5.	4.	<u>.</u>	2.) :-	S No	
88	Other	Utility	Kitchen	Portico	Head room	Terrace/balcony2	Terrace/balcony 1	Lobby 2	Lobby 1	Dining	Drawing	Bedroom 4	Bedroom 3 Gr. Bed	Bedroom 2 C. god	Bedroom I M. Bao		Flooring & painting
			<	. (<	1	<	1	e C C C C C C C C C C C C C C C C C C C	<	<		<	<	<	Color variation of floor tiles	
			<	1	<	ess; re-	<	١	1	<	<	1	<	<	<	Flooring workman ship & grouting	
_			1	1	<	1	<	1	1	1	(1	1	<	3	Skirting size (3")	Rate
			<	1	<	1	<	1	1	7	<	1	<	<	5	Skirting workmanship	Rate the quality of (Good
			<	1	<	1	<	1	1	<	7	1	<	5	<	Plastering above skirting	ty of (Go
			<	1	<	-	<	-	1	<	<	7	(7	<	Plastering & finishing of walls	od v, Av
			<	1	<	1	<	1	1		<	1	1	1	5	Crack filling	×
			1	1	1	1	1	Comment	١	1	1	1	1	1)	Loft Finishing	or – need
		<		1	<	1		1	1	(<	1		<	7	General quality of painting & finishing	ds correcti
			<	1	<	1		1	1 4	1	(1		<		Door & frame painting quality	Poor – needs correction XX, NA)
			5	,	X	1	<		1		5	, >	< >	×	×	Door beading, luppam and painting quality.	NA)
				1		1		1	1	1				1	<	Edge building	

Quality Control Check Repot. Stage: After Finishing Stage II (Villas)

Quality and workmanship of portico tiles Quality and workmanship of flooring & setbacks Quality and workmanship of external cladding/ texture	Good Avg. Poor Good Avg. Poor Avg. Poor
Quality and workmanship of flooring & setbacks	Good Avg. Poor
Quality and workmanship of external cladding/ texture	Good Avg. Poor
Remarks:	