Flate No	という	Quality Control Check Repot.		Stage: After Finishing Stage II	Stage II (Villas)	
ing	Flat-No	الو	Other		Sl. No.	87990
ing	Company	SUP	Project	700	Phase	1
ing	Prepared by	SiSund Kuma	Sign	1.10	Date	15/9/17
ing required.	Project Manager	A. Sweet	Sign	4	Date	15/9/17
required.	Previous stage report	no.	26097	Report filed and signe	d by PM	Yes No
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	Checked By MD on		MD Sign		For filling	☐Yes ☐No
	Recommendation: Stop further work. Stop further work Proceed with furth Proceed with furth	Submit ATR on QC re. Proceed with work af her work only after mak her work. ATR not requ	eport to QC team. Proofer submitting ATR or ing corrections pointe ired.	ceed only after recheck land QC report to QC team and out in the QC report.	by QC. ATR not required.	

- Inspection should be done after:
 Completion of flooring, bathroom /utility tiles, doors & beading, first coat of paint.
 Completion of windows, grills, electrical wiring, switches must be done in next stage
- False ceiling must be completed before flooring.
- Kitchen platform, granite and dado must be completed where modular kitchen is not provided. Provide granite soffit for main door in this stage.

Miscellaneous check:

	Main door granite soffit workmanship Good Avg Poor Main door granite soffit edge	Granite soffit for main door required Yes No	Main door fixed with lock & stopper ☐ Yes ☐ No	
١	☐Good ☐Avg ☐Poor		☐Yes ☐No	
polishing	Main door granite soffit edge	Granite soffit for main door provided	Stoppen nat to	
)	Good Avg Poor	□Yes □No →	de.	

١

6

S 4 S

7

!2

S No

9 œ

10.

15. 14. 12.

13.

Quality Control Check Repot. Stage: After Finishing Stage II (Villas)

Miscellaneous check – after finishing stage II	
Quality and workmanship of portico tiles	Good Avg. Poor
Quality and workmanship of flooring & setbacks	☐Good ☐Avg. ☐Poor
Quality and workmanship of external cladding/ texture	☐Good ☐Avg. ☐Poor
Remarks:	