# ATR on Quality Control Check Repot. (Bungalows)

Bungalow No	10	QC report stage	Aplaly	Sl. No.	32726
Company	Voc up	Project	voc	Phase	
Prepared by	Sund	Sign	J'	Date	07/06/19
Project Manager	SURTIA	Sign	W.	Date	02/06/19
Receipt by QC date		Sign		Other	
Receipt at HO date	1	Sign		Other	
Checked By MD on		MD Sign		For filling	☐ Yes ☐ No
Recommendation that  Stop further work.	Submit ATR on QC	report to QC team. Pro	oceed only after reche	eck by QC.	

1 Stop further work. Proceed with work after submitting ATR on QC report to QC team.
Notes:  1. Attach a copy of the QC report to this sheet. 2. Circle each correction with a red pen – tick ( ) each circle for work completed and cross ( ) each circle where work has not been completed. 3. Give remarks for each case where work has not completed on this sheet. 4. Make 2 copied of the ATR – send one to MD and other to QC. 5. Enclose required photographs – hard copy.
Remarks: Pl Works Congleted

Page 1 of 1

Villa No.	10	Stage		Sl. No.	33728
Company	VOC(LLP)	Project	Voc	Phase	-
Prepared by	Tivinad Kunax	Sign	T. Vinod Kumal	Date	04/06/19
Project Manager	A. Suresh.	Sign	W.	Date	04/06/19
Previous stage report	no.	32412	Report filed and sign	ed by PM?	✓ Yes □ No
Checked By MD on		MD Sign		For filling	Yes No
Recommendation:					
Stop further work.	Submit ATR on QC r	eport to QC team.	Proceed only after recheck	by QC.	
Stop further work	. Proceed with work at	ter submitting AT	R on QC report to QC tean	1.	
			inted out in the QC report.		i.
Proceed with furth	ner work. ATR not requ	ired.		•	

## Inspection should be done after:

- brickwork & 2 coats plastering is completed
   after cleaning the Villa.
- water proofing, wreeding in bathrooms is completed,
   before starting painting, tiling & flooring.

# Plastering Check,

- Notes:

  1. Mark v for correct or minor mistake which does not require correction

  2. Mark X for minor mistake that requires minor correction.

  3. Mark XX for major mistake that requires correction by replacement or re-fixing.

  4. Mark XXX for major mistake that cannot be corrected.

  5. S'maplastered area from SFL should be left including in common areas and terraces.

  6. Windows must be checked with templates. Folorance ¼7.

  7. Provision of tiles in bathrooms, kitchen & wash areas (rough plastering).

  8. Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")

  9. All doors frames should have ½ grooves.

  10. Sill up must be of uniform thickness, correct height, at one level & without broken edges.

2.00	*					
Quality Contro	atrol Check Repot. Stage: After Plastering (Villas)					
loor	Substitute (Villas)					
Sedroom   M. Red   X   Y   Y   Y   Y   Y   Y   Y   Y   Y						
Eset backs are not	maintained as pos spacification					
Remarks Note: A Groves not provided.  Estimating provision is not maintained as pos specification.  Page 2 of 3						
	Page 2 of 3					

# Quality Control Check Repot. Stage: After Plastering (Villas)

Remarks:	Plastering quality of parapet walls ( v or x)  Plastering and finishing of chajjas ( v or x)	Is plastering of compound wall and villa external walls 6" below FFL of setbacks?	Miscellaneous check  Overall quality of plastering?
	<	□Yes ☑No	□ Good ☑ Avg. □ Bad