	Quality Control Check Repot.	
	t. Stage: After Plastering	
	r Plastering (Vi	
ĺ	<u> </u>	

Stop further work. Stop further work. Proceed with furthe Proceed with furthe	Recommendation:		Checked By MD on	1110dor ogme green	Previous stage report no	S. C.	Project Manager	June 10	Prenared by	,	Company		Y LLIG LYO.
Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. A Proceed with further work. ATR not required.				10.		damirali kwhy	→	J. Car Kiner		<u> </u>		+2	
port to QC team. Proce er submitting ATR on ng corrections pointed red.		MID Sign	AT C:	31784		Sign	2.	Sign		Froject	Designat	Stage	2+2
Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. The Proceed with further work only after making corrections pointed out in the QC report. ATR not required. Proceed with further work. ATR not required.			-	Report filed and signed by PM?	1200	`	11(dy		Diom dake	*			
y QC. .TR not required.		For filling		d by PM?		Date		Date	1 11430	Phace		Sl. No.	
		Yes No		NYes I No	8111No	7	05 11 118				4+1-15) -) i	

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the Villa.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

Plastering Check

- Mark ✓ for correct or minor mistake which does not require correction
- Mark \times for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces.
- Windows must be checked with templates. Tolerance 1/2".
- Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1") Provision of tiles in bathrooms, kitchen & wash areas (rough plastering)
- All doors frames should have 1/2 grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

Re	19	18	17	16	15	14	13	12	11	10	9	8	7	6	2	4	w	2	1	S No
Remarks $\checkmark \checkmark$	Other	Utility	Kitchen	Portico	Head room	Terrace/balcony 2	Terrace / balcony 1	Lobby 2	Lobby 1 F. box	Dining	Drawing	Toilet 4	Bedroom-4	Toilet 3 KT	Bedroom 3	Toilet 2 ペイ	n 2	Toilet 1 47	Bedroom 1 んら	Room
S CVER &			X	~	5	1	<	**PARIMETERS	<	<	<	\	-	<	<	<	<	<	く	Skirting Provision (✓ or 🗙)
N. S.			<		<		· <	4			<	\	Samuel and American	<	<	<	ζ.	<	<	Finishing around door frame (✓ or ×)
5			<	<	<		<	1	<	<	<		-	<	<	ζ	ζ,	<	<	Beams & columns finishing (• or ×)
\$ 10 m			<	\	1	\		t	1)	M I.			1)	`\	}	1		Finishing of lofts (✓ or 🗙)
5			7	<	<	-	<		<	<	7	L	,	<	<	<	<	<u> </u>	Ċ.	Electrical junctions finishing (• or ×)
J. W.			5	(<	\	1)	<	<	<	١	1	<	<	ζ	5	<	<	Window check (• or ×)
7		(X)	()	ļ	1	\	(\	\		Bayes and Art Art	<	,	5	7	<	\	Tiles provision (• or ×)
			\		1		-	\	(1		And the second s	\	<	1	5	1	5	1	Sink provision & size
			<	1	<	\	<			-	5	1		<	(ζ.	<	<	Grooves for door frames (• or ×)
			\	١	5		(((-	-			***************************************)	7)	(Balcony & terrace sill top finishing 10 (• or ×)
				\	\		1					-	***************************************	(7×7)	11	(X-X))	(×	21	Screeding in bathroom & utility (• or ×)
			l	١	1	1	1		1	1			1	(XX)		(XX)	1	(XX)		Screeding in 6" above FFL? (• or ×)

Quality Control Check Repot. Stage: After Plastering (Villas)

ı	Miscellaneous check	
	Overall quality of plastering?	☐ Good [√Avg. [] Bad
	Plastering of compound wall & gate pillars (v or x)	No.
	Is plastering of compound wall and villa external walls 6" below FFL of setbacks?	No No
	Plastering quality of parapet walls (vor x)	<
	Plastering and finishing of chajjas (vor X)	<
	Remarks:	
Γ		

ATR on Quality Control Check Repot. (Bungalows)

J			f I		AND THE RESERVE THE PROPERTY OF THE PROPERTY O
Bungalow No	72	QC report stage	5 = 100	Sl. No.	31974
Company	大さろ	Project	Bloomidale	Phase	The second secon
Prepared by	G. Rahad.	Sign	Rahad	Date	29/1/19
Project Manager	C. Bala Mural Kishn Sign	Sign	O Bosayo	Date	201112
Receipt by QC date		Sign		Other	
Receipt at HO date		Sign		Other	
Checked By MD on		MD Sign		For filling	☐ Yes ☐ No
Recommendation that was made by QC: Stop further work. Submit ATR on Q Stop further work. Proceed with work.	Recommendation that was made by QC: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC Stop further work. Proceed with work after submitting ATR on QC report to QC team.	port to QC team. Proceer submitting ATR on	ed only after recheck l QC report to QC team	by QC.	
Notes:					

- Attach a copy of the QC report to this sheet.

 Circle each correction with a red pen tick (✓) each circle for work completed and cross (X) each circle where work has not been completed. Give remarks for each case where work has not completed on this sheet.

 Make 2 copied of the ATR send one to MD and other to QC.

 Enclose required photographs hard copy.

					•	Remarks: All Works Completed
						ks Completed
			*			
	THE THE TAX ASSESSMENT OF TAX ASSESSMENT OF THE TAX ASSESSMENT OF THE TAX ASSESSMENT OF THE TAX ASSESSMENT OF TAX ASSESS					
~						