Quality Control Check Repot. Stage: After Plumbing & Electrical (Apartments)

Elat Nia					
Tat NO.	C-506	Other		Sl. No.	2 7 2 2 2 2
Company	Dric	Project	ろわ C	Phase	7) 65
Prepared by	P. Soh Kum	Sign	0.21	Date	,, ,,
Project Manager		Sign	> 		1314110
Drawingston	1. Subjec Kadey	ngi	halh	Date	4117 (3
r revious stage report no.	no.	14.597 440	Report filed and signed by	d by PM?	□Yes □No
Additions & alterations sheet date	ns sheet date	(215/14	All pages signed by engineer & customer? Yes No	gineer & customer?	Yes No
Checked By MD on		MD Sign		For filling	TVec TVi
Recommendation:				o	
Stop further work. Stop further work. Proceed with furth Proceed with furth	Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not proceed with further work. ATR not required.	port to QC team. Proce er submitting ATR on ing corrections pointed red.	sed only after recheck b QC report to QC team. out in the QC report. A	y QC. ATR not required.	
Inspection should be done after	Proceed with further work. ATR not required pection should be done after:	red.	one of toport, to	viv not reduned.	
 after cleaning the apartment. 	artment,				, , , , , , , , , , , , , , , , , , , ,

- before starting painting, tiling & flooring.
- electrical conduct, waterproofing & plumbing work is completed (for stage II only).
- additions & alterations is finalized and signed. In case there are no additions and alterations printout of email by PM to CR confirming the same must be
- additions & alterations sheets to be transferred to QC file. QC to check if A&A are made as per request.

After Plumbing & Electrical Check,

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- Location of CPVC & PVC fittings must be checked as per measurements given in circular. Tolerance 1".

 Location, height and spirit level of electrical points must be checked as per measurements given in circular & plan. Tolerance 1".
- Civil work near pipes in balcony & utility must be neat and mortar should be removed from the pipes.
- Water proofing must cover all pipes & check height above SFL.
- Fasteners must be used as specified in circular. Especially check fixing of PVC pipes. Height of DB box must be 6" below false ceiling level or 12" below slab level.
- 11. In case of many changes in civil work, electrical work and plumbing work, a new drawing must be prepared at HO and approved by MD.

Quality Control Check Repot. Stage: After Plumbing & Electrical (Apartments)

Remarks on additions & alteration sheet: Signed by engineer, Revised drawing required from HO	Remarks	15 Other	1	13 Kitchen	<u> </u>	-	╀	┾	1_	_		<u>↓</u> _	Ļ	_	1	1_	S No		
sheet:				1	1	<	<		ſ)	1	1)	/	/	}	utility (v or	Civil work near pipes in	
es No			<	,				i	1		-)	۲.		5		(or X)	CPVC & PVC Check	
Signed by customer, Approved revised dr			<	· · · · · · · · · · · · · · · · · · ·				<					1	, <		j	(• or X)	Electrical points check	
Signed by customer, Approved revised drawing attached			,		-	<					}	<]	5	1		check (v or	Water	
			1		-		-)	7	 •	•		1		check (v or	Proper use of	
Yes No			1	1	-				<		}		!			50 NO 100	DD (v or X)	-	
		5					}]	!					(or x)	Changeover	Placement of	