Quality Control Check Repot. Stage: After Plumbing & Electrical (Apartments)

01-03-419-6-00				
Flat No.	シャーン	Other	Sl. No.	79148
Company	BNC	Project	Mfh Phase	
Prepared by	M. Toga Svidhou	Sign	A Date	41/50/30
Project Manager	17 C	Sign	T Date	1 6.5.17
Previous stage report no	no.	27132	Report filed and signed by PM?	
Additions & alterations sheet date	ns sheet date	£1 8038	All pages signed by engineer & customer?	& customer? Yes No
Checked By MD on		MD Sign	For fill	filling Yes No
Recommendation: Stop further work. Sub Stop further work. Pro Proceed with further w	Recommendation: Stop further work. Submit ATR on QC report Stop further work. Proceed with work after s Proceed with further work only after making Proceed with further work. ATR not required transfer should be done after.	eport to QC team. Proc ter submitting ATR on sing corrections pointed ired.	Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR no proceed with further work. ATR not required.	C. not required.

- after cleaning the apartment.
- before starting painting, tiling & flooring.
- electrical conduct, waterproofing & plumbing work is completed (for stage II only).
- additions & alterations is finalized and signed. In case there are no additions and alterations printout of email by PM to CR confirming the same must be
- additions & alterations sheets to be transferred to QC file. QC to check if A&A are made as per request

After Plumbing & Electrical Check.

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.

 Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- Location of CPVC & PVC fittings must be checked as per measurements given in circular. Tolerance 1". Location, height and spirit level of electrical points must be checked as per measurements given in circular & plan. Tolerance 1".
- Civil work near pipes in balcony & utility must be neat and mortar should be removed from the pipes.
- Water proofing must cover all pipes & check height above SFL.
- Fasteners must be used as specified in circular. Especially check fixing of PVC pipes.
- Height of DB box must be 6" below false ceiling level or 12" below slab level.
- In case of many changes in civil work, electrical work and plumbing work, a new drawing must be prepared at HO and approved by MD.

Quality Control Check Repot. Stage: After Plumbing & Electrical (Apartments)

	Re	3.5	3	7		1	200	R	15	14	13	12	5/=	110		T.	∞	7	6	S	4	w		J		-			
	vise	gned		mari				Remarks	2	-	╀─	+	+-			+	4.	_	-			L.	_	-	-	No	o		
	Revised drawing required from HO	Signed by engineer,	The state of the s	Remarks on additions & alteration sheet:				rks	Other	Other	Kitchen	Uthlity-/-balcony-3	July / baleony 2	July / Dalcony 1	L000y-1	Culting 1	Dining	Drawing	Toilet-3	Bedroom-3	Toilet 2 (CT)	Bedroom 2 (Ko)	Toilet I (MT)	Bedroom I (MB)		Roo.	m		
		√ Yes	ration sheet.	ration cheet.							\		<	<	1	1	1			1	\	1	-	}	×	utility (> or	halcony &	Civil work	
	Yes No	čes □No									<		<	<		l	1) <		}	<	1		\(\frac{1}{2}\)	PVC Check	CPVC &	
Tes No	Approved	Signed by									<	{ }	<	<	1	\	<	1)	<	<			<		(or x)	points check	Electrical	
	revised drawing	Signed by customer, Yes No											1	\	,	1		•	1	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	,	}			ſ	>	check (vor	proofing	Water
											[1)	1	1	1	1]	l		3	}	TVO TO	×	check (v or	fasteners	Proper use of	
	7 1									1								!)	•	1	1				100	DB (v or x)	_	
															1	<]	1	1		,		(or X)	changeover	Generator	Diagonate	