Quality Control Check Repot. Stage: After Plastering (Apartments)

Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by Q Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR Proceed with further work. ATR not required.	Pacaman dation	Checked By MD on	rievious stage report no.	Dravious store and	2	Project Manager	richarca by		Company	Company	* Ide 140.	19t VO
Stop further work. Submit ATR on QC report Stop further work. Proceed with work after superceed with further work only after making or Proceed with further work. ATR not required.			,		Subba Reddy		M. Tepa Svidher		SAC.	7	れれた	>
port to QC team. Proceer submitting ATR on ing corrections pointedired.	MD Sign	2	26435		Sign	3	Sign	2	Project		Other	>
Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by Q Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR Proceed with further work. ATR not required.			Report filed and signed by	Rave	1.22		4	10101	がたか			
by QC. ATR not required.	For filling		ed by PM?		Date		Date		Phase		SI. No.	
	☐ Yes ☐ No	1	Yyes	125	38/06/12	+11 Lolex	90/1/15	<b> </b>		7	27121	

## Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the apartment.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

## Plastering Check.

## Notes:

- Mark v for correct or minor mistake which does not require correction Mark x for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces.
- Windows must be checked with templates. Plastering must be 3mm margin for luppum work. Tolerance 1/4".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2" grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

	0.	Ret	15	14	13	12	=	10	9	000	7	6	S	4	ر د	) N	)  -	S No
CE	Q PM	Remarks	Other	Other	Kitchen	Utility/baleony3	Utility / balcony 2	Utility / balcony 1	Lobby-1	Dining	Drawing	Toilet 3	Bedreem-3	Ioilet 2 (CT)	Bedroom 2 (KB)	户	n1 (	Room
1		स्र	_		<	ſ	<	<	1	く	<	1	)	<	<	<	. <	Skirting Provision ( • or ×)
	Property.	Electrical			{ 	1	<	<	1	1	<	1	ı	<	<	<	<	Finishing around door frame ( • or ×)
		cal			<	1	<	<	1	<	<	1	] ] 	<u> </u>	<	<	<	Beams & columns finishing (✓ or 🗙)
		function			<	[ ]	1	(	1	\	<b>,</b>	1	J	1	,	ı		Finishing of lofts ( • or ×)
	,	+		_	<	1	<	<	1	<	<	١	i	<b>&lt;</b>	<	<	X	Electrical junctions finishing ( v or x)
		nishine			<	1	1	ſ	1	*	3	1	J	<	<u>\</u>	<	<	Window check <sup>6</sup> (✓ or ×)
		<u>s</u>					1	1	1	1	1	1	J	く	١	<	ļ	Tiles provision (✓ or 🗙)
				'		1	١	1	1	1	<b>f</b>	[		<	1	<	1	Sink provision & size (✓ or 🗙)
		M. Bedyoon			(	1	<	}		(		١	1	<	<	<	<	Grooves for door frames ( v or x)
	3	A res		1			1		1	1	!	1	,	1	5	J	1	Balcony & terrace sill top finishing( v or x)
		s not			!		<			1	!	1	1	<	1	<	1	Screeding in bathroom & utility ( v or x)
_				}	_			}		1	1	,		<	1	<	1	Screeding in 6" above FFL? ( • or ×)