Quality Control Check Repot. Stage: After Plastering (Apartments)

Flat No.	C-80.4	Other	(SI. No.	27316
Company	BNC	Project	MFG	Phase 🥷	1
Prepared by M.	M. Tela Svidher	Sign	97	Date	P 30/05/17
Project Manager Sv.	SV-Subba Reddy	Sign	noch	Date	30/05/17.
Previous stage report no.	l.	28436	Report filed and signed by PM?	d by PM?	No □No
Checked By MD on		MD Sign		For filling	☐ Yes ☐ No
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	mit ATR on QC receed with work aftork only after mak	port to QC team. Proce ter submitting ATR on ing corrections pointed ired.	ed only after recheck l QC report to QC team out in the QC report.	yy QC. ATR not required.	

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the apartment.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

Plastering Check.

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.

 Mark XX for major mistake that requires correction by replacement or re-fixing.

 Mark XXX for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces.
- Windows must be checked with templates. Plastering must be 3mm margin for luppum work. Tolerance 1/4".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2 grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.