Quality Control Check Repot. Stage: After Plastering (Apartments)

Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team.	Recommendation;	Checked By MD on	rievious stage report no.	Drawing Subba	Project Manager	Prepared by	Company		141 TAC:
Stop further work. Submit ATR on QC report Stop further work. Proceed with work after support Proceed with further work only after making of the proceed with further work. ATP not required.			<u>ر</u> 	Subba Keddy vij	a soldher	エース	,	C-403	`
Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR Proceed with further work. ATR not required.	1110001811	MDSign	1)26940	Sign	a d	Sign	Project	Omer	25
ed only after recheck by QC report to QC team. out in the QC report.			Report filed and signed by	Z	4	1 100	文の文		
у QC. ATR not required.	For filling		d by PM?	Date	Date		Phase	SI. No.	
	☐Yes ☐No	E ros	N Ves INS	417048	FI Co HB	1	40×1×	97917	

chon should be done after;

- brickwork & 2 coats plastering is completed
- after cleaning the apartment.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

Plastering Check. Notes:

- Mark ✓ for correct or minor mistake which does not require correction Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark $\times \times \times$ for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces.
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1") Windows must be checked with templates. Plastering must be 3mm margin for happum work. Tolerance 1/4".
- All doors frames should have 1/2" grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

Rei	15	14	ມ	12	=	10	9	8	7	6	Ŋ	4	C.	2) -	-	S No
Remarks	Other	Other	Kitchen	Utility / balcony-3	Utility / balcony 2	Utility/balcony 1	Labby 1	Dining	Drawing	Teilet-3	Bedroom 3 (46)	<u>`</u>	, C	<u>`</u>	Tailet 1 CMT	Redroom 1 (MB)	Room
			<	1	~	<	1	~	<	1	<	. <	\			4	Skirting Provision (• or ×)
			1	1	<	١	1	١	<	1	1	_<	1	<		<	Finishing around door frame (v or x)
			<	1	<	<	١	K	4	1	2	<	k	\ <		<	Beams & columns finishing (v or x)
			<	ı	1	١	1	1	(1		()			,	}	Finishing of lofts (v or x)
			<	1	1	<	1	4	<	• 1		۷. ۷	,	<	<	<	Electrical junctions finishing (• or ×)
			<	1	1	1	1	ţ	<	, 1		4		<	<	<	Window check ⁶ (• or ×)
			<	1	(]	(1	j	1		, <		1	<	í	Tiles provision (✓ or ×)
			<	1	1	J	I	,	1		1	1	\	١	<	ı	Sink provision & size
			1	1	<	1	{		\	1		۷,	\	<	<	. <	Grooves for door frames (• or ×)
			1		4	1	1	1	, ,		1	(١	1	١	ß	Balcony & terrace sill top finishing(v or x)
			1		<	1		1	1 1		,	1	<	1	<	1	Screeding in bathroom & utility (• or ×)
				1	1 4	1	i	1	1	1	1	1	<	1	<	1	Screeding in 6" above FFL? (• or ×)