1	10
1	K
١	15
-	12
	1
1	Ì
	15
١	
1	Tarrey Country Check Mebut.
١	C
١	15
	6
1	17
	17
١	Ę
	Įĕ
	ŀ
	ı
	1
	2
1	1
	Stage: Alter Direkwork (Apart
	ľ
	12
	E
	ľ
	×
	E
	7
	3
	H
	7
1	7
į	۲
i	Α
	12

Flat No.	201	Others		SI. No.	32621
Company	SOV (UP)	Project	SOV	Phase	~)
Prepared by	S. Kauldeep	Sign	Standers	Date	18/1/9
Project Manager	E. Pusshottan	Sign	P	Date	1/1/1d/21
Previous stage report no.	no.	31574	Report filed and signed by PM?	ed by PM?	NYes □No
Apartment No		Other	,	Other	- Address
Checked By MD on		MD Sign		For filling	□Yes □No
Recommendation: Stop further work Stop further work Proceed with furt	Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. AT Proceed with further work. ATR not required.	port to QC team. Proces rer submitting ATR on ing corrections pointed ired.	eed only after recheck QC report to QC team d out in the QC report.	by QC. ATR not required.	

Inspection should be done after:

- brickwork is completed
- chicken mesh fixed
- after cleaning the apartment
- clectrical conducting work is completed

Brickwork Check.

Notes:

- Mark ✓ for correct or minor mistake which does not require correction
- 2. Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- 4. Mark XXX for major mistake that cannot be corrected.
- Wall thickness should be as per plan. Use of 4", 6" & 8" blocks must be checked.
- 6. All walls should have 2 bcds of about 2"to 3"thickmess with one no. 6 mm or 8 mm rod with M15 CC.
- 7. Chicken mcsh should be used in each and every joint between RCC & Brickwork.
- Joint between brickwork & beam on external side must be filled.
- . Check room dimensions with working plan. (Tolerance: 1")
- 0. Diagonals of each room shall be equal. (Tolerance: 2")
- 1. Balcony sill level should be 3'3"from SFL. (Tolcrance: 1")
- 12. Check room height with specified height. (Tolerance: 1")
- 3. Check plumb of walls where ever it appears to be out of plumb. (Tolerance: 1/2")
- 4. Specify the No. of beams which are not aligned by more than 1"in a room.
- . Door frames must have black Japan coating and wood primer / pellambar at cost of painter.

Page 2 o	
of 4	

	Rer	15	14	13	12	11	10	9	∞	7	9	5	4	w	2	_	S No
	Remarks	Other	Other	Kitchen	Utility/balcony3	Utility / baleony 2	Utility / balcony 1	Lobby-1	Dining	Drawing	Toilet 3	Bedroom 3	Toilet 2	Bedroom 2	Toilet 1	Bedroom 1	Room
					ony3	ony2	ony 1				4.7	90. T	C-T	r R	7.10	3,6	·
782	1			<	1	ζ.	<		Ţ	7	<	<	ς	<	<	ς.	Wall thickness (or x)
balcend	-			ς.	1	1	Ĺ	1	1	ζ	ζ.	<	7	ς.	`	ς	Beds in walls (v or x)
				ζ.	1	1	<	-	!	(۲	ς	ς .	ζ	(Chicken mesh (✓ or 🗙)
at mised				1	1	`	•	1	1	(<	١	۲	(۲	ς.	External brickwork & beam joint (> or ×)
d Rai				1	1	1	<	1	i	7	(<	(۲	ς	,	Room Dimensions
Lo a				1	1	1	Ţ	١	1	,	(1	1	١	١	1	Room Dimensions Difference in inche
d 1300	†			1	1	1	1	Î	1	•		\		۲	,	7	Diagonal (v or x)
لصلاطيط	,			\	1	1	1	1	1	1	1	J	ı	1	1	1	Diagonal Difference in inche
led.				1	1	¥	1	1 /		A	,	1	1	1	1	Ţ	Balcony sill level
			_		, ((1	!					,		`	Room Height
			=	Ava	10)	Ara	,	1	Q X X	=	= 0.5	からか	=	= 000	A Commo	Plumb of walls (Good/Avg./Bad)
	€				,		1	1	r	7		(;	,		Alignment of beam and walls - Nos.

Quality Control Check Repot.	Stage: After Brickwork (Apartments)
Quality of edges and corners in all rooms?	☐Good ☐ Avg. ☐ Bad
Specify rooms that need correction:	
Misc. Checks.	
Was 3.75 CFT proportion box provided?	✓ Yes ☐ No
Condition of proportion box?	☐ Good ☑ Avg. ☐ Bad
Was the Apartment cleaned before starting brick work?	☐ Yes ☐ No ☐ Cant' say
Is the Apartment cleaned for plastering?	□Yes □No
Wastage?	High Medium Low
Storage of building material like bricks sand and cement.	☐Good ☐ Avg. ☐ Bad
Drum (200 lts) provided for curing in each flat?	☑Ýes ☐No
Remarks:	

Door Frames & Windows check

Notes:

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing. Mark XXX for major mistake that cannot be corrected.
- Window template depth should be between 2 to 2 ½"after plastering. Lentil level should be 7'3"from SFL & 7'from FFL. (Tolerance 1")
- (Tolerance 1") Lofts should be at a height of 7'to 7'3" from FFL. Kitchen plat from should be at a height of 32" or 33" from FFL and 35" or 36" from SFL.
- Slopes of lofts and kitchen platforms to be checked by using 12"spirit level and check height from floor from 2 or 3 points. Thickness of platforms & lofts should be between 2 & 2.5".
- 10. Provide single layer table brick at bottom of each door frame without threshold.

70	0 5	4	13	12	11	10	9	∞	7	6	S	4	w	2	-	S No
NGHIAIKS.	Other	Other	Kitchen	Utility/baleony 3	Utility / balcony-2	Utility/balcony 1	Lobby 1	Dining	Drawing	Toilet 3 G.T	Bedroom 3 4. 8	Toilet 2 c・T	n 2	Toilet 1 9.7	Bedroom 1 , m. g	Room
			1	1	Κ	ĵ	1	1	(1	`	′	ζ	(Door size, face and position (v or X)
			ſ	1		ľ	1	1	(7	ς.	ζ	ζ		Brick at bottom of door frame (✓ or 🗙)
			ı	1	~		ı	1	7	/	1	ς	۲		ζ	Door lentil level (v or X)
		8	1	1	1	1	1	-	1	V	,	′	ς	1	ς	Door diagonal check (v or X)
			1	ı	8	1	ſ	1	1	7	1	ς,	7	7	<	Door Plumb - two sides
			ı	Ī	([1	ļ	1	<	<	7	7	ς.	′	Door frame black Japan/ wood primer/Peelambar check (v or X)
			5	1		Ī	1	1	1	<	ζ	(\	`	7	Windows lentil & sill leve
			ζ	1	•	1	ſ	!	7	1	<	7	7	ς.	<u> </u>	Windows size (✓ or 🗙)
			ζ	١	1	P	1	•	1	~	7	7	9	((Windows - template deptl & diagonal (✓ or 🗙)
			1	ľ		1	ſ	1	1	\	7	7	1	<	5	Windows - template powder coated (✓ or ×)
			1	1	1	1	1	ı	1	٦	١	1	1	ļ		Loft & Kitchen platform required? (Yes or No)
			1	1	1	1	1	1	ſ	1	-	1	1	ı	1	Loft & Kitchen platform provided (v or × or NA
			1)	1]	ı	}	1	1	1	ļ	1	1		Loft & Kitchen platform slope (vor X)

Quality Control Check Repot. Stage: After Brickwork (Apartments)