Quality Contr	Quality Control Check Repot.	Stage: After Brickwork (Apartments)	
Flat No. C-SIS	Others	SI. No.	29210
Company Poor - U	Project	Phase	+
Prepared by (V.S., Kimar	Sign	Date	2/2/18
Project Manager 12 ishimsh himey Sign	Sign	Date	2/2/18
Previous stage report no.	29060	Report filed and signed by PM?	XYes JNo
Apartment No	Other	Other	
Checked By MD on	MD Sign	For filling	Yes No
Recommendation:  Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	report to QC team. Profeer submitting ATR oking corrections pointured.	oceed only after recheck by QC. on QC report to QC team. ted out in thc QC report. ATR not require	Xd.

Inspection should be done after:

- brickwork is completed
- chicken mesh fixed
- after cleaning the apartment
- electrical conducting work is completed

## Brickwork Check.

## Notes:

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing
- Mark XXX for major mistake that cannot be corrected.
- Wall thickness should be as per plan. Use of 4", 6" & 8" blocks must be checked.
- All walls should have 2 beds of about 2"to 3"thickmess with one no. 6 mm or 8 mm rod with M15 CC.
- Chicken mesh should be used in each and every joint between RCC & Brickwork.
- Joint between brickwork & beam on external side must be filled.
- 10. Diagonals of each room shall be equal. (Tolerance: 2") Check room dimensions with working plan. (Tolerance: 1")
- 11.
- Balcony sill level should be 3'3" from SFL. (Tolerance: 1")
- 13. 12. Check plumb of walls where ever it appears to be out of plumb. (Tolerance: 1/2") Check room height with specified height. (Tolerance: 1")
- 14. Specify the No. of beams which are not aligned by more than 1"in a room.
- Door frames must have black Japan coating and wood primer / pellambar at cost of painter.

Ren	15	14	13	<u>.</u>	=	Ξ	S	$\infty$	7	6	Ŋ	17	S	10		S No
Remarks	Other	Other	Kitchen	Undity / balcony 3	1 Inhty / balcony 2	Unlity / bal	Lobby I	Dining	Drawing	Toilet-3	Bedroom 3	Toilet 2	Bedroom 2	Toilet 1	Bedroom 1	Room
				cony 3	cony 2	cony i					03	7	1000	7	أحسا	
					ď	۲	•	K.	<	1	<	<	ς,	ς.	ζ,	Wall thickness ( • or ×)
			*		۲	<	Ţ	<	<.	-	<	۲,	< .	< .	ς,	Beds in walls (✓ or 🗙)
			ζ.		-	· ·	1	<.	۲,	1	ς.	ς,	<,	< <sub>.</sub>	<	Chicken mesh (✓ or ×)
			ζ,	4	<	r.	1	<	<,	1	<	۲,	ς.,	(	<	External brickwork & beam joint ( or
			ζ.	1		۲ .	1	<	<,	*	<	5	ζ.	ς,	<,	Room Dimensions ( • or ×)
			1	!	I		,	1	1	j	1	i		I		Room Dimensions Difference in inches
			<	1	<	c	1	<	<	j	<	<	K	<,	<,	Diagonal (✓ or 🗙)
			1	1	,		`.		1	\		i v	]; 			Diagonal Difference in inches
			3		<	,		1	!	1	1	1	1	1		Balcony sill level
			5		<b>\</b>	<	1	(	<	1	<	<	<,	ζ.	2	Room Height
			V	5	ς	ć		<.	(	Marine.	K	۷.	ζ,	7	,	Plumb of walls (Good Avg./Bad)
			<		<	<	1	<		1	<	ς.	<	, ,		Alignment of beams and walls - Nos

Quality Control Check Repot.	Stage: After Brickwork (Apartments)	
Quality of edges and corners in all rooms?	Good Avg. Bad	
Specify rooms that need correction:		
Misc. Checks.		
Was 3.75 CFT proportion box provided?	Yes No	
Condition of proportion box?	Good Avg. Bad	
Was the Apartment cleaned before starting brick work?	Yes No Cant say	
Is the Apartment cleaned for plastering?	Yes No	
Wastage?	High Medium Low	
Storage of building material like bricks sand and cement.	☐ Good ☑ Avg. ☐ Bad	
Drum (200 lts) provided for curing in each flat?  Remarks:	☐ Yes ☑No	
Door Frames & Windows check		

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing. Mark XXX for major mistake that cannot be corrected.
- Window template depth should be between 2 to 2 ½"after plastering. Lentil level should be 7'3"from SFL & 7'from FFL. (Tolerance 1")
- Lofts should be at a height of 7'to 7'3" from FFL. Kitchen plat from should be at a height of 32"or 33"from FFL and 35" or 36"from SFL. (Tolerance 1")
- Slopes of lofts and kitchen platforms to be checked by using 12"spirit level and check height from floor from 2 or 3 points. Thickness of platforms & lofts should be between 2 & 2.5".
- 10. Provide single layer table brick at bottom of each door frame without threshold.

Ren	15	14	13	[]	Ξ	5	9	8	7	6	5	4	သ	2	1	S No
Remarks:	Other	Other	Kitchen	Utility / balcony 3	thility / balcony 2	Utility / balcony 1	Labby 1	Dining	Drawing	Toilet-3	Bedroom 3 んか		n 2	Toilet 1 MT	Bedroom 1 べら	Room
			ì			V		}	۷.	1	ζ.	۷,	ς,	۲,		Door size, face and position ( ✓ or ×)
			1	1		<	1	Ņ	۷	)	Κ,	۲,	< .	ς, '		Brick at bottom of door frame ( v or X)
				1	,	< .	١	\	۷.	)	<	C.	<,	ς,	ζ,	Door lentil level ( v or X)
			1	4	1	< .	1	,	۷,	1	<.	ς,	<.	<,,	<,	Door diagonal check
			•	١	,	<.	į	1	Κ,	1	ς.	4.	Ç.	ć.,	۲.	Door Plumb - two sides (✓ or 🗙)
				1	\	< .	١	Ż	<	\	`	N.	S.	ς.	<,	Door frame black Japan/ wood primer/Peelambar check ( or X)
			<	}		ţ	1	1	<	1	ν,	ζ.	ς.	ς.	ζ.	Windows lastil & sill lavel
			<	1	١,		3	Į,	<	ļ	<	<	ς,	۲	7	Windows size (✓ or 🗙)
			<	1	1		1	,	<,	1	ď,	ς,	ς,		ζ,	Windows - template depth & diagonal (✓ or ×)
			<.	1	X		1	1	<,	1	<.	<	, <	<	<	Windows - template powder coated (✓ or 🗙)
			1	1	,	1	١	i	1	1	1	1		1	1	Loft & Kitchen platform required ? (Yes or No)
			1	1	Ţ	,	١	,	1	1	1	į	,	1	3	Loft & Kitchen platform provided ( • or × or NA)
			1	j	٩	1	}	1	7	1	1		1.	1	3	Loft & Kitchen platform slope (✓ or 🗙)