Quality Control Check Repot. Stage: After Plumbing & Electrical (Apartments)

69 07 2018 C9 07 2018 □Yes □No □Yes □No	Report filed and signed by PM? All pages signed by engineer & customer? For filling For filling GC report to QC report. ATR not required.	revious stage report no. Subba Reday Sign 26825 Report filed and signed by Proceed with further work. ATR not required. Sign 26825 Report filed and signed by Proceed out in the QC report. ATR not required.	Sign 26825 23/54/18 MD Sign Proof to QC team. Proofing corrections pointe ired.	roject Manager roject Manager subba Ready Sign revious stage report no. 2 (dditions & alterations sheet date commendation: Stop further work. Submit ATR on QC report to Stop further work. Proceed with work after sub Proceed with further work. ATR not required. Proceed with further work. ATR not required.	Project Manager Project Manager Previous stage report no. Additions & alterations sheet date Checked By MD on Recommendation: Recommendation: Stop further work. Submit AT Stop further work. Proceed with further work only Proceed with further work. AT
	Phase	N POP	Project	BNC	Company
30782	Sl. No.		Other	D-103	Flat No.

Inspection should be done after:

- after cleaning the apartment.
- before starting painting, tiling & flooring.
- electrical conduct, waterproofing & plumbing work is completed (for stage II only).
- additions & alterations is finalized and signed. In case there are no additions and alterations printout of email by PM to CR confirming the same must be
- additions & alterations sheets to be transferred to QC file, QC to check if A&A are made as per request.

After Plumbing & Electrical Check.

Notes:

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing
- Mark XXX for major mistake that cannot be corrected.
- Location of CPVC & PVC fittings must be checked as per measurements given in circular. Tolerance 1".
- Location, height and spirit level of electrical points must be checked as per measurements given in circular & plan. Tolerance 1".
- Civil work near pipes in balcony & utility must be neat and mortar should be removed from the pipes.
- Water proofing must cover all pipes & check height above SFL.
- Pasteners must be used as specified in circular. Especially check fixing of PVC pipes
- 10. Height of DB box must be 6" below false ceiling level or 12" below slab level.
- In case of many changes in civil work, electrical work and plumbing work, a new drawing must be prepared at HO and approved by MD.

Quality Control Check Repot.

	Repot.
	Stag
A COLUMN STATE OF THE PERSON STATE OF THE PERS	e: After
	Stage: After Plumbing & Electrical (Apartments)
	ing & El
	lectrical
	l (Apart
	ments)

]Yes □No	ing attached	Approved revised drawing attached	— Approv]Yes □No	from HO	Revised drawing required from HO	Revis
	✓ Yes ☐ No		Signed by customer,	Signed	∠Yes □No	K	Signed by engineer,	Signe
						teration sheet:	Remarks on additions & alteration sheet:	Rema
			_				i de la constante de la consta	
		-	not littled.	Di-water	5 CL D	n n.T s	ン× ·	Remarks
							Other	15
				2 d 3			Other	14 (
*	ון	ţ	1	\	(ļ	Kitchen	13 1
1	-		I]	1	1	Utility/balcony3	12
f	Ţ	Ţ	ζ.	<	(\	Utility / b alcony 2-	11 1
1	ı	1	1	(1	1	Utility/balcony l	10
	ı	1	1	1	1	1	Lobby 1	9]
ı	ſ	1	ſ	1	1	1	Dining	8
(<	Ţ	((I	ŗ	Drawing	[
1	1	1	ļ	1	1		Toilet 3	6 '
1	1	١	1	(,		Bedroom 3 (G・B)	5
1	1	1	((X	ι	Toilet 2 (c न)	4
1]	1	7	ι	Ţ	Bedroom 2 (k·8)	3
1	1	1	(1	X	١	Toilet I (m.1)	2
1	١	1	1	ζ	ļ		Bedroom 1 (m·8)	
Generator changeover (or	DB (or x)	fasteners check (• or ×)	proofing check (• or ×)	points check (• or ×)	PVC Check	near pipes in balcony & utility (• or ×)	Room	S No
Dlacement of	Diacament of	Dramar nea of	Water	Dlantminnl	CD17C 0.	Civil month		-