ļ	
	1
	10 11117
	спеск керот.
	X XC
	001.
	S
	age:
	After
	Plasi
	tering
	y (An
1	2
Chiranter	tmonte)

171 3 7 7			2111 1000000	E (C) Par Unitellity)	
FIAL NO.	D-20)	Other		SINO	
Company	+	Project	0		20937
Prengred har	misia Homes	- voleer	moter Homes	Phase	1
rivpated by	SKLINGER	Sign	Chuchen	Date	
Project Manager		Sign	2		8102/20/12
Previous stage rener	- income	Q	mille	Date	24/20/20/20
ome suge report no.	HO.	30359	Report filed and signed by PM?	d by PM?	17 Vec No
Checked By MD on					F : 58
Recommendation:		uğıc mar		For filling	☐ Yes ☐ No
Accommission:					
Stop further work.	Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by Stop further work. Proceed with work after submitting ATP on QC	port to QC team. Proce	ed only after recheck b	у QC.	
Proceed with furth	Proceed with further work only after making corrections pointed out in the QC report. ATR not required. Proceed with further work. ATR not required	ng corrections pointed	out in the QC report. /	ATR not required.	

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the apartment.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

Plastering Check.

- Mark ✓ for correct or minor mistake which does not require correction
- Mark \times for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark **XXX** for major mistake that cannot be corrected.

 9"unplastered area from SFL should be left including in common areas and terraces.
- Windows must be checked with templates. <u>Plastering must be 3mm margin for luppum work</u>. Tolerance 1/2" Provision of tiles in bathrooms, kitchen & wash areas (rough plastering).
- Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2" grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.