Quality Control Check Repot. Stage: After Plastering (Apartments)

Flat No.	カーかのル	Other		Sl. No.	2000
					7
Company	Vista Hames	Project	Visito Homes	Phase	
Prepared by	S. Sund Xum	Sign		Date	13/2/19
Project Manager	1 mad hu	Sign	Y why	Date	13/8/19
Previous stage report no.	t no.	30879	Report filed and signed by PM?	d by PM?	Yes No
Checked By MD on		MD Sign		For filling	☐ Yes ☐ No
Recommendation: Stop further work. Stop further work Proceed with furt	Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	port to QC team. Procter submitting ATR on ing corrections pointedired.	ced only after recheck by QC report to QC team.	y QC. ATR not required.	

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the apartment.
- water proofing, screeding in bathrooms is completed
- before starting painting, tiling & flooring.

Plastering Check.

Notes:

- Mark of for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.

 Mark XX for major mistake that requires correction by replacement or re-fixing.

 Mark XXX for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces. Windows must be checked with templates. Plastering must be 3mm margin for happum work. Tolcrance 1/2".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2" grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges