Quality Control Check Repot. Stage: After Plastering (Apartments)

Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by (Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATI Proceed with further work. ATR not required.	Checked By MD on	Previous stage report no.	Project Manager	Prepared by	Company	Flat No.
commendation: Stop further work. Submit ATR on QC report Stop further work. Proceed with work after submit ATR on QC report Stop further work. Proceed with further work only after making a Proceed with further work. ATR not required.		0.	Kylynsh Kurry Sign	M. Teja Sindley	PWV-LI	D-425
port to QC team. Proceed the submitting ATR on ing corrections pointed ired.	MD Sign	4508%	Sign	Sign	Project	Other
Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required.		Report filed and signed by PM?	QU/	The state of the s	5-43	
by QC. ATR not required.	For filling	d by PM?	Date	Date	Phase	Sl. No.
	□Yes □No	WYes No	18/03/18.	15/03/18	[=]	29660

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the apartment.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

Plastering Check.

- Mark \vee for correct or minor mistake which does not require correction Mark \times for minor mistake that requires minor correction.

 Mark \times for major mistake that requires correction by replacement or re-fixing. Mark \times \times for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces.
- Windows must be checked with templates. Plastering must be 3mm margin for luppum work. Tolerance 1/4".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have "grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

Rer	7	5	14	13	12	11	10	9	8	7	9	2	4	w	2	1	S No
Remarks	Caron	Other	Other	Kitchen	Utility/balcony3	Utility / balcony 2	Utility√ balcony 1	Lobby-1—	Dining	Drawing	Toilet-3	Bedroom-3	Toilet 2 (CT)	Bedroom 2 (KB)	Toilet 1 (MT)	Bedroom I(KB)	Room
	200			Y	1	<	<		_	く		1	<u> </u>	<	<	<	Skirting Provision (• or ×)
				~	-	<	1	\	1	<	1	ļ	く	V	く	<	Finishing around door frame (• or ×)
				<	1	<	7		<u>\</u>	<		}		<	<	ζ	Beams & columns finishing (• or ×)
			- 40	<	1	1	1		1		-	1	(1	Finishing of lofts (• or ×)
				<	-	<	<	•	く	, <	-	1	<	外	~	メ	Electrical junctions finishing (• or ×)
				<	•	1	ţ		-	<		•		<u> </u>	Y	<	Window check ⁶ (✓ or X)
				<	1	〈		1	1	{	-	+	1		<u>\</u>		Tiles provision (• or ×)
				<	1	ſ	-		(•		1	4	-,	<	(Sink provision & size (• or ×)
						<			1	<	1	1	<u> </u>	<	<	<	Grooves for door frames (• or ×)
				1		()	1	\	1	1	1	1	-	1	1	Balcony & terrace sill top finishing(v or x)
						<)	1	1	j	•		<	1	<	5	Screeding in bathroom & utility (or x)
					1	<	1	1	1	1		1	<	ſ	<		Screeding in 6" above FFL? (v or x)