## Quality Control Check Repot. Stage: After Plumbing & Electrical (Apartments)

Prepared by   Project   Project   Project   Project Manager   Subso Roll   Sign   Date   30   05   18	Flat No.	4093	Other	1	SI. No.	30383
Sign  Date  Ont no.  All pages signed by engineer & customer?  MD Sign  MD Sign  All pages signed by engineer & customer?  ork. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  ork. Proceed with work after submitting ATR on QC report to QC team.  urther work only after making corrections pointed out in the QC report. ATR not required.  urther work. ATR not required.	Company	BNC	Project		Phase	
Sign  Sign  Ort no.  Subba Rady  Sign  Soous  Report filed and signed by PM?  All pages signed by engineer & customer?  All pages signed by engineer & customer?  For filling  ork. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  ork. Proceed with work after submitting ATR on QC report to QC team.  urther work only after making corrections pointed out in the QC report. ATR not required.  urther work. ATR not required.	Prepared by	M. Teja Svidhur	Sign		Date	30/05/18
ritions sheet date  Unsold Flat  MID Sign  MID Sign  MID Sign  All pages signed by engineer & customer?  For filling  For filling  wither work only after submitting ATR on QC report to QC team.  Wither work only after making corrections pointed out in the QC report. ATR not required.  When the proceed with work after submitting ATR on QC report to QC team.  Wither work. ATR not required.	Project Manager		Sign	284	Date	30/05/18
ations sheet date  Unsold Flot  MID Sign  MID Sign  MID Sign  MID Sign  For filling  For filling  ork. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  ork. Proceed with work after submitting ATR on QC report to QC team.  urther work only after making corrections pointed out in the QC report. ATR not required.  urther work. ATR not required.	Previous stage report	no.	30043	Report filed and signe	d by PM?	Yes No
MD Sign    For filling     For	Additions & alteration	is sheet date	Unsold Flat	All pages signed by er	eer & customer?	☐ Yes ☐ No
Recommendation:  Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	Checked By MD on		MD Sign		For filling	☐ Yes ☐ No
Increation should be done offer.	Recommendation:  Stop further work.  Stop further work.  Proceed with furth  Proceed with furth	Submit ATR on QC re Proceed with work aft er work only after maker work. ATR not requi	port to QC team. Proceer submitting ATR on ing corrections pointed ired.	eed only after recheck be QC report to QC team. I out in the QC report. 1	y QC. ATR not required.	

- after cleaning the apartment.
- before starting painting, tiling & flooring.
- electrical conduct, waterproofing & plumbing work is completed (for stage II only).
- additions & alterations is finalized and signed. In case there are no additions and alterations printout of email by PM to CR confirming the same must be
- additions & alterations sheets to be transferred to QC file. QC to check if A&A are made as per request.

## After Plumbing & Electrical Check

Notes:

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.

  Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- Location of CPVC & PVC fittings must be checked as per measurements given in circular. Tolerance 1".
- 755432 Location, height and spirit level of electrical points must be checked as per measurements given in circular & plan. Tolerance 1".
- Civil work near pipes in balcony & utility must be neat and mortar should be removed from the pipes.
- Water proofing must cover all pipes & check height above SFL.
- Fasteners must be used as specified in circular. Especially check fixing of PVC pipes. Height of DB box must be 6" below false ceiling level or 12" below slab level.
- In case of many changes in civil work, electrical work and plumbing work, a new drawing must be prepared at HO and approved by MD.

## Quality Control Check Repot. Stage: After Plumbing & Electrical (Apartments)

Res	Sig	Reı		Rei	15	14	13	12.	11	10	9.	8	7	6	S	4	w	2	Н	S No	
Revised drawing required from HO	Signed by engineer,	Remarks on additions & alteration sheet:		Remarks (1) Wall	Other	Other	Kitchen	-Utility-baleony3-	Utility / balcony-2	-Utility/ balcony I	-Lobby 1	Dining	Drawing	-Foilet 3	Bedroom 3 (4β)	Toilet 2 $((\tau))$	Bedroom 2 (KB)	Toilet 1 (MT)	Bedroom 1 (Mg)	Room	
from HO		teration sheet:	المراوات المراد	nietures			1	1	<	7					(	ſ	-	}	1	near pipes in balcony & utility ( ~ or ×)	Civil work
]Yes □No	]Yes □No	Unsold Frat		not for			X	1	<	5	<b>I</b>		•	1		<	}	<	5	PVC Check (✓ or ×)	CPVC &
Approv	Signed	(et		foreded in			<		~	7		. 🗸	<		<	<	<	<	<	points check	Electrical
Approved revised drawing attached	Signed by customer,			5(分				1	1	)	1	(	}	Ţ	1	ı	١	١	J	check (v or	Water
ing attached								[	\	1	]		}		1	1	1	1	1	rasteners check ( or x)	Proper use of
]Yes □No	]Yes □No						1		1	j		1	7	Ì	1	١	1	1	1	DB (v or X)	Placement of
1	)						l	1		}	1		7	-		1		1	1	changeover ( v or ×)	Placement of