Qua
lity (
Quality Control Check Repot. St.
) Che
ck R
epot.
Stage: Before Casting Slab
Befor
re Ca
isting S
Slab
11 ()

Recommendation: Stop further work. Stop further work. Proceed with furth	Checked By MD on	Previous stage report no.	Project Manager	Prepared by	Company	Block No
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. Proceed with further work. ATR not required.		no.	Countres hunds	くるがなか	Zingini Estato	74
o QC team. Pomitting ATR	MD Sign	31952	Sign	Sign	Project	Slab No.
AT		Report filed and signed by PM?	June J	7. 00. 10. 10. 10. 10. 10. 10. 10. 10. 10	Nilgini Estato	03
QC.	For filling	1?	Date	Date	Phase	SI. No.
	Yes No	MYes ∐No	20/11/18	20 11 18	H	32128

Slab Check. Notes:

- Inspection should be done before casting of slab at each stage i.e. when the slab is ready for casting.
 Prepare Slab Dimensions Check Plan as follows:

 a. Show outer dimensions of slab. (Tolerance 2")
 b. Show length and width of balconies (Tolerance 1")
 c. Show inner dimensions of ducts. (Tolerance 1")
 d. Show location of sunken slab.
 e. Print an A3 size plan.
- Mid landing height is no. of risers x riser height. Measure from SFL to SFL. Check staircase of lower floor that has been casted.

☐ Yes ☐ No	Within tolerance of 1/4"?		Actual:	1	Specified:	Staircase slab thickness
∐Yes ∐No	Within tolerance of ½"?		Actual wd:	į	Specified wd:	Staircase width
☐ Yes ☐ No	Within tolerance of ½"?	1	Actual ht:	1	Specified ht:	Staircase - mid landing 2
∐Yes ∐No	Within tolerance of 1/2"?	1	Actual ht:	1	Specified ht:	Staircase - mid landing1
		No	MYes ∐No		:d?	Slab Dimensions Check Plan enclosed?
II.	mention actual dimension next to	d colour and	limension with re	incorrect d	n colour. Circle each	4. Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension max or it.

Quality Control Check Repot. Stage: Before Casting Slab (Villas)

Quality of centering, rod bending and concreting. Quality of centering, rod bending and concreting?	Good Avg. Bad
18"extension to beam bottom runners on outer side provided?	Yes No
Quality of Bracing Provided?	Good Arg. Bad
Alignment of beams on outer side?	Good Avg. Bad
Shuttering leveling?	Good Avg. Bad
Column steel overlapping and cranking? (overlapping length should be 45 to 50 D)	Correct Needs correction
Remarks:	

Slab Steel check.

Notes:

- Mark V for correct or minor mistake which does not require correction
 Mark X for minor mistake that requires minor correction.
 Mark X for major mistake that requires correction by replacement or re-fixing.
 Mark X X for major mistake that cannot be corrected.
 Columns overlapping length should be 45 to 50 D.

Quality Control Check Repot. Stage: Before Casting Slab (Villas)

	Remarks:	16.	15.	14.	13.	12.	11.	10.	9.	8.	7.	6.	5.	4.	ယ	2.		S No
		Steel check - slab extensions/ joints	Steel check — floating columns	Electrical Conducting	Steel Check - Column steel overlapping length and cranking	Covering blocks for slab	Steel Check - Slab Extra Bars	Steel Check Slab cranking & chairs	Steel Check - Slab spacing of bars	Steel Check - Slab size of bars	Depth and width of beams	Covering blocks for beams	Steel Check - Beams Bearing	Steel Check - Beams Overlapping & Cranking	Steel Check - Bcams Extra Bars	Steel Check - Beam size of bars	Steel Check - Beam no of rods	ltein
		de comment	1	~	<	<u> </u>	~	✓	< ·		√	\	<	<	<i>\</i>	<u> </u>	ζ,	Quantitative Check (\(\cdot \(\times \(\times \))
	700-11	☐ Good ☐ Avg. ☐ Bad	☐ Good ☐ Avg. ☐ Bad	✓ Good ☐ Avg. ☐ Bad	☐ Good ☑ Avg. ☐ Bad	☐ Good 🗹 Avg. ☐ Bad	Good Avg. Bad	☐ Good ☑ Avg. ☐ Bad	✓ Good ☐ Avg. ☐ Bad	Good Avg. Bad	✓ Good Avg. Bad	Good Avg. Bad	☐ Good 🗹 Avg. ☐ Bad	✓ Good ☐ Avg. ☐ Bad	Good Avg. Bad	Good Avg. Bad	Good Avg. Bad	Qualitative Check (Good ' Avg. / Bad)