		CIND	3000
Block No. A Hack (2 & 3 Flats) Column No.	mn No.	SI. No.	33991
Company NAP Project	et VIII	Phase	
Prepared by \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	C. Starting !	Date	16/63/19
Project Manager Subba 366 Asign			15/07/19
	33961 Report filed and signed by PM?		Yes No
Checked By MD on MD Sign	Sign	For filling	Yes No
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required. Proceed with further work. ATR not required.	o QC team. Proceed only after recheck lbmitting ATR on QC report to QC team orrections pointed out in the QC report.	y QC. ATR not required.	

Columns Position Check.

Notes:

- 1. Inspection should be done after casting of columns at each stage and before starting centering works for each slab.
- Prepare Columns Position Check Plan as follows:
- Divide blocks into smaller sub-blocks.
- Show size and orientation of columns. (Tolerance 0.5")
- Show inner inner space between columns. (Tolerance 1")
- Show diagonals for 20% of bays. (Tolerance 1.5")
- Print an A3 size plan.
- Columns Position Check Plan enclosed? Circle each correct dimension with green colour. Circle each incorrect dimension, with red colour and mention actual dimension next to it. √ Yes S

Slab Dimensions Check.

- Prepare Slab (or plinth beams) Dimensions Check Plan as follows:
- Show outer dimensions of slab. (Tolerance 2")
- Show length and width of balconies (Tolerance 1")

 Show inner dimensions of ducts and lift well. (Tolerance 1")
- Show location of sunken slab.
- Print an A3 size plan.

Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention act	lension with red colour and mention actual	ictual dimension next to it.
2. Cilcle caell collect difficultions with 6. con colors control collections and collections are control collections.		
Slab Dimensions Check Plan enclosed?	Yes No N.O	
Specified thickness of slab?	Actual thickness of slab?	comm

Page 1 of 7

10
Quality
Quality Control Check Repot. Sta
Check
Repot.
Stage: After
r Column
Casting
Stage: After Column Casting (Apartments

Quality of centering, rod bending and concreting.		
Quality of centering, rod bending and concreting?		Good Myg. Bad
Quality of starters?		☐ Good ☑ Avg. ☐ Bad
Number and size of honey combs?		☐ High ☐ Medium. ☑ Low
Are the honey combs is slab and columns packed?		☐ Good ¶ Avg. ☐ Bad
Number of beams that are sagging, bulging, caved or deflected in the slab by more than 1"	than 1"	Look
Have 6 cubes each for columns and slab casted and numbered for testing?		√ Yes ☐ No
Remarks:		
Curing.		
Bunds for curing made on slab?	☐Yes ☐No	- 1. - 5
Bund size is less than 100 sft?	□Yes □No	
Drum (200 lts) provided for curing?	Yes No	
Gunny bags used for column curing?	✓ Yes	
Distance of tap from furthest distance that requires curing. (max permitted 100')	4-0-0"	
Frequency of curing in number of times a day (enquire from labourers)	2 times	
Is the pressure in the curing pipe more than 15' head?	√Yes □No	
Quality of infrastructure for curing.	☑ Good ☐ Avg. ☐	Bad
Remarks: (1) (sine of the colors colors	not costed.	à.

Stage: After Column Casting (Apartments)

Quality Control Check Repot.
Columns height, plumb, steel & level marking check.

Mark v for correct or minor mistake which does not require correction
 Mark X for minor mistake that requires minor correction.
 Mark XX for major mistake that requires correction by replacement or re-fixing.
 Mark XX for major mistake that cannot be corrected.
 Tolerance: Plumb 0.25".
 Circle actual height of columns if level differs from specified height by more than 1".

17.	16.	15.	14.	13.	12.	11.	10.	9.	.8	7.	6.	S.	4.	. ω	2.	1.			SNo
4	gui.	ĵ	an so	6.40	į	3	ì	Villaner	ì	i Come	1	or Jan	7.2	2	3	age III			Col No.
2	5	C	C	3	4)	C4-	5	C	(C)	5	Ca	()	5	C2.	C	CI			Col type
9.6"	Stevens	3/0"	9'6"	9-6 M	Stairs	614"	910"	979"	a 1 o u	844	8-9"	0 to "	9-0"	9-6"	6,0,	9-6"		Spec.	Heigh
8-116	Stairs	9-6"	9-1-1	9-1"	silais	8,74,	30.0	qc."	19.	6-9"	8-10"	8-="	9-0"	8-11	4-1"	a_c."		Actual	Height in ft
	<	<	<	<	<		6.	<	<		\	<	<	<_	<	<	rods	No of	Steel (
<	<	<	<	1	<	<.				<\	<		<	<	~	<	rods	Size of	Steel (v or x)
<	<	<	*	<	-		J*	٧/				4	<	<	<,	<			Honeycombs
	<	√,	<	<	, Daller	<	<	<	<	< ,		\ 	V ,	~	<	<		Side 1	Plumb
<	Y	~	<	<	Donates:	<	*	5	`\	<	<	\checkmark	K,	ζ.	<	/		Side 2	Plumb (or x)
Yes No	✓ Yes ☐ No	∐Yes □No	√ Yes □ No	✓ Yes □ No	∐Yes ∐No	☑ Yes □ No		√ Yes No	√ Yes □ No	✓ Yes \ \ \ No	∏Yes □No	☑Yes ☐No	✓ Yes □ No	☑Yes ☐No	✓ Yes □ No	✓ Yes ☐ No	column?	marked on	Reference level

Quality Control Check Repot. Stage: After Column Casting (Apartments)

39.	38.	37.	36.	35.	34.	33.	32.	31.	30.	29.	28.	27.	26.	25.	24.	23.	22.	21.	20.	19.	18.		S No
											وي م	Con	48n,	î: -	1		Î		Cont.	ì	Jitan		Col No.
									2		G	Cs	0 -	C3	C.	Ch	C2	(4)	C2	C	0		Col type
									-		8.4	3-5-8	970"	814"	8-9"	8-4"	9. U	8-9"	8-9	9'0"	9'-0"	Spec.	Heigl
											8/10"	64	12,0	8-10"	8-(0"	8:100	90"	20-0-	8,70,	950	970	Actual	Height in ft
											<	<u> </u>	<	<		<	<	\	~	<	Υ΄.	No of rods	Steel (
												<	V.	۷.	۲,	4	4.	<	K	<	Ve -	Size of rods	Steel (v or x)
								•		1		۲.	<	, i	V .	4	· .	<	<		<.		Honeycombs
				*							< \	<	<	۷	V.	<	<	~ ~	<	<	<	Side 1	Plumb
											<	<	<	<	<. \	V.	<	<	<	<,,	<	Side 2	Plumb (or X)
☐ Yes ☐ No	☐ Yes ☐ No	□Yes □No	☐Yes ☐No	☐ Yes ☐ No	∐Yes ∏No	∐Yes □No	∏ Yes ∏No	√ Yos □ No	Yes No	√ Yes □ No	Yes No	√ Yes □ No	[√Yes ∐No	Yes No	Yes No	√Yes □No	√ Yes □ No	√ Yes □ No	marked on column?	Reference level			