## Quality Control Check Repot. Stage: After Plumbing & Electrical (Apartments)

Flat No.	B-708 ·	Other	ſ	SI. No.	802tB
Company	PMR	Project	PMR	Phase	T
Prepared by	M. Tya Sindhar	Sign	T T	Date	C3/c3/c2
Project Manager	K-SHIRISH	Sign	A	Date	4)40/20
Previous stage report no.	no.	634469	Report filed and signed by PM?	d by PM?	⊠Yes □No
Additions & alterations sheet date	ns sheet date	26/12/16	All pages signed by engineer & customer?		Yes □No
Checked By MD on		MD Sign	1,31,100	For filling	☐ Yes ☐ No
Recommendation:  Stop further work. Sul Stop further work. Proceed with further w	Recommendation:  Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	port to QC team. Proce ter submitting ATR on ing corrections pointed ired.	eed only after recheck be QC report to QC team. I out in the QC report.	y QC. ATR not required.	

Inspection should be done after:

- after cleaning the apartment.
- before starting painting, tiling & flooring.
- electrical conduct, waterproofing & plumbing work is completed (for stage II only).
- additions & alterations is finalized and signed. In case there are no additions and alterations printout of email by PM to CR confirming the same must be
- additions & alterations sheets to be transferred to QC file. QC to check if A&A are made as per request.

## After Plumbing & Electrical Check.

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.

  Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- Location of CPVC & PVC fittings must be checked as per measurements given in circular. Tolcrance 1".
- Location, height and spirit level of electrical points must be checked as per measurements given in circular & plan. Tolerance 1".
- Civil work near pipes in balcony & utility must be neat and mortar should be removed from the pipes.
- Water proofing must cover all pipes & check height above SFL.
- Fasteners must be used as specified in circular. Especially check fixing of PVC pipcs.
- Height of DB box must be 6" below false ceiling level or 12" below slab level.
- In case of many changes in civil work, electrical work and plumbing work, a new drawing must be prepared at HO and approved by MD.

Quality Control Check Repot. Stage: After Plumbing & Electrical (Apartments)

тем тим подпират Втем и и и и и и и и и и и и и и и и и и и	Revised drawing re	Signed by engineer.	Kemarks on addition	Damada		WOTHING.	Romarks	15 Other	14 Other			17 The County of County 2		0000		8   Dining	╀-	_	-	Rodinom 3	Toilet 2	3   Bedroom 2	2 Toilet 1		-	S N Roo	<del></del>	
фитеа поп но			Kemarks on additions & alteration sheet:							•	ny 3	July 2 4		JIIV I		(	ļ	1	(ug)/				(KT)	(MB)	_	utility ( vor	near pipes in balcony &	Civil work
Yes YNo			;;							***************************************	,	<b>人</b>	<	\ !		1	ſ	1	(	<		\		(		) ( , , ,	——— E	
Approved	Signed by	2							<			<u> </u>	<			*	<	[	< \	<	<	\<		<		( v or x)	points check	Flantming
Approved revised drawing at	Signed by customer,								1				<u></u>	ļ			ļ t		1	ı	ı	1	1		>	check (✓ or	proofing	1117
tached							-		1				<b>†</b>		1	1		[	(	5	1	i	3		×	check (✓ or	Proper use of fasteners	
Yes No	Yes No													1		<		,		1	•	1	ſ		175	3	Placement of DB ( • or ×)	¥
														Livery .	1	<	1	1	,			1	ſ		( v or x)	changeover	Placement of Generator	