## Quality Control Check Repot. Stage: After Brickwork (Apartments)

Recommendation:  Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	Checked By MD on	Apartment No	Previous stage report no.	Project Manager K. CHIRISH	Prepared by M. Tyo Victor Sign	Company PMR - II	Flat No. 6-119
on QC re work aft fter mak not requi					dher	,	
port to QC team. Pro ter submitting ATR o ing corrections point ired.	MD Sign	Other	15848	Sign	Sign	Project	Others
ceed only after recheck I n QC report to QC team ed out in the QC report.			Report filed and signed by PM?	25	94°	DMR-II	•
by QC. ATR not required.	For filling	Other	d by PM?	Date	Date	Phase	Sl. No.
	☐Yes ☐No		Yes No ·	N/30MB	F1/80/46	7	998tB

Inspection should be done after:

- brickwork is completed
- chicken mesh fixed
- after cleaning the apartment
- electrical conducting work is completed

## Brickwork Check,

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing
- Mark XXX for major mistake that cannot be corrected.
- Wall thickness should be as per plan. Use of 4", 6" & 8" blocks must be checked.
- All walls should have 2 beds of about 2"to 3"thickness with one no. 6 mm or 8 mm rod with M15 CC
- Chicken mesh should be used in each and every joint between RCC & Brickwork.
- Joint between brickwork & beam on external side must be filled.
- Diagonals of each room shall be equal. (Tolerance: 2") Check room dimensions with working plan. (Tolerance: 1")
- 11. Balcony sill level should be 3'3" from SFL. (Tolcrance: 1")
- Check room height with specified height. (Tolerance: 1")
- 13. Check plumb of walls where ever it appears to be out of plumb. (Tolerance: 1/2")
- 14. Specify the No. of beams which are not aligned by more than 1"in a room.
  15. Door frames must have black Japan coating and wood primer / pellambar -
- Door frames must have black Japan coating and wood primer / pellambar at cost of painter.

Ren	15	14	13	12	=	=	9	∞	7	6	U	4		1	-	S No
Remarks	Other	Other	Kitchen	Utility/balcony 3	Utility / baleony 2	Litility / balcony 1	Lebby 1	Dining	Drawing	Teilet 3	Bedroom 3	Toilet 2 (Cr)	Bedroom 2, (KB)		n 1 (	
			<u> </u>	•	۲	4	1	<	<	ſ	1	4	<	<	<	Wall thickness ( v or x)
			<	[	۲	ζ.	-	<b>√</b>	く	1	ſ	<	<	<	4	Beds in walls (✓ or ×)
			<	ı	4	۷	1	4	<b>4</b>	1	ſ	<	<	<	<	Chicken mesh
			<b>\</b>	1	<	<b>ح</b>	1	~	<b>\</b>	ſ	١	4	<	<	<	External brickwork & beam joint ( • or ×)
			<	İ	<	5		<u>ر</u>	<	(	ſ	7	<	<	۷	Room Dimensions ( v or x)
		~	<b>\</b>	la e	1	j	1	1	J	1	_	١	,	١	(	Room Dimensions Difference in inches
		_	۲_	1	1	乀	1	<	<	1	١	۷,	<	۷.	۲	Diagonal ( • or ×)
			1	1	1	)	1	ľ	3	1	1	(			1	Diagonal Difference in inches
			1	[	1	<b>!</b>	1	( )		1	}	(	I	ſ	ſ	Balcony sill level ( v or x)
		<		1	4	<	1	4	<	1	1	<	<	<	<	Room Height ( v or x)
		7	Re	!	-	As a	1		A	1	)		7		**	Plumb of walls (Good/Avg./Bad)
2.		<		1		<	1	,		į	1	<	<	4	<	Alignment of beams and walls - Nos.

Quality Control Check Repot.	Stage: After Brickwork (Apartments)
Quality of edges and corners in all rooms?	☐ Good ☑ Avg. ☐ Bad
Specify rooms that need correction:	
Misc. Checks.	
Was 3.75 CFT proportion box provided?	√Yes
Condition of proportion box?	Good Avg. Bad
Was the Apartment cleaned before starting brick work?	Yes No Cant' say
Is the Apartment cleaned for plastering?	Yes No
Wastage?	High Medium Low
Storage of building material like bricks sand and cement.	Good Avg. Bad
Drum (200 lts) provided for curing in each flat?	√Yes □No
Remarks:	
Door Frames & Windows check	

Notes:

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.

  Mark XX for major mistake that requires correction by replacement or re-fixing.

  Mark XXX for major mistake that cannot be corrected.
- Window template depth should be between 2 to 2 ½"after plastering. Lcntil level should be 7'3"from SFL & 7'from FFL. (Tolerance 1")
- Losts should be at a height of 7'to 7'3" from FFL. Kitchen plat from should be at a height of 32"or 33"from FFL and 35" or 36"from SFL. (Tolerance 1")
- Slopes of lofts and kitchen platforms to be checked by using 12"spirit level and check height from floor from 2 or 3 points. Thickness of platforms & lofts should be between 2 & 2.5".
- Provide single layer table brick at bottom of each door frame without threshold.

Ren	15	14	13	12-	11	10	9	×	> -	1 0	2/	5	4	w	/	) -	S No
Remarks:	Other	Other	Kitchen	-Utility-baleony-3-	Utility / baleony 2	Utility/ balcony 1	Lebby-1	Dining	Drawing	Tonot o	Taileta	لماً إ	Toilet 2 (CT)	Bedroom 2 (Kb)		Bedroom I (M8)	
			1		<	ſ	1	1	<	1	1		4	4	3	<	Door size, face and position ( v or x)
			1		1	-	-	1	1		1		\	۷	١	<	Prosition ( v or x)  Brick at bottom of door frame ( v or x)  Door lentil level ( v or x)  Door diagonal check ( v or x)
		1	(			\		(	4	1	j	-	` (		<	<	Door lentil level
		ļ	Í	<		j	1	İ	4	1	3	2			<	<	Door diagonal check
		1	,	•		1	1	1	4	1	1	1		<	4	<	Door Plumb - two sides
		(	1			l	(	\	<	{	j	4		<	<	<	Door frame black Japan/ wood primer/Peelambar check ( v or X)  Windows lentil & sill level   ( v or X)  Windows size ( v or X)  Windows - template depth & diagonal ( v or X)  Windows - template
		<	1				,	•	5	[		K		<	<		Windows lentil & sill level ( v or x)
		K	, [	1	1			\	4	-	1	<	<	,	<	<	Windows size ( v or x)
		4		1	]		1	1	4	1	ļ	4	<			\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	Windows - template depth & diagonal ( v or X)
		<	1	١	.		1	1	4	1	1	4	K	. <		< \	Windows - template
		Zo		1	}	1		1 )			)	(	3	I	1	L	oft & Kitchen platform equired ? (Yes or No)
		1	]	1	ſ		1 1	)		1	1	1	1	]		l p	Loft & Kitchen platform rovided ( > or × or NA)
		Series and the series	1		1			,		1	1	1	1	1		L	oft & Kitchen platform ope (* or *)