Quality Control Check Repot. Stage: After Plastering (Apartments)

Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required. Proceed with further work. ATR not required.	Checked By MD on	Previous stage report no.	Project Manager	Prepared by	Company	Flat No.
ubmit ATR on QC re roceed with work af work only after mak work. ATR not requ			SHIRBH	M. Tela Soldher	PMR	C-119 .
Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR n Proceed with further work. ATR not required.	MD Sign	998 ER	Sign	Sign	Project	Other
eed only after recheck l QC report to QC team l out in the QC report.		Report filed and signed by PM?	T. Th	XX	PMR	1
by QC. ATR not required.	For filling	ed by PM?	Date	Date	Phase	SI. No.
	□Yes □No	Yes No	81/10/20	81/10/40	2	28864

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the apartment.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

Plastering Check.

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces.
- Windows must be checked with templates. Plastering must be 3mm margin for luppum work. Tolerance 1/2".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2" grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

		Ren	15	14	13	12	11	10	6	8	7	6	5	4	3	2		S No
	<u>S</u>	Remarks Wite.	Other	Other	Kitchen	-Utility/ba	Utility / balcony-2:	-Utility-/ balcony 1	-1-yddo-1	Dining	Drawing	Toilet-3	Bedroom 3	Toilet 2	Bedroom 2	Toilet 1	Bedroom 1	Room
1 2000	Dado	_				dcony 3-	dcon y 2	dcony 1					}- 	$(c\tau)$	2 (KB)	()	1 (MB)	
	the	Skirling			<		く	<		(<			4	<	<	<	Skirting Provision (• or ×)
	Nov.	ZT)			1	1	<	1	(1	<	1	1	乀	<	<	<	Finishing around door frame (• or ×)
	andra	Provision			<	-	<	<	1	<	5	1)	<	<	<	<	Beams & columns finishing (v or x)
	2				<		1	1	1	-	J	1	1	(ſ	1		Finishing of lofts (v or x)
	net au	is not	7		<	1	<	1	•	١	<	1	1	<	<	<	<	Electrical junctions finishing (> or ×)
	Con 1	tas			<	1	1	J		١	<)	4	<	<	<	Window check ⁶ (✓ or ×)
	Specifical	Ku			×	1	<	j	-)	1)	~	1	<	-	Tiles provision (✓ or 🗙)
	fication	Spe			<	1	<	١	f	1	1	l	١	<	1	<	1	Sink provision & size (✓ or 🗙)
	•	ufications			ļ	1	<	1	-	1	<	1)	1	<	<	<	Grooves for door frames (• or ×)
		ON			1	1	<	1		١	1	Ţ	j	1	١	94-	J	Balcony & terrace sill top finishing(v or x)
					1		<			1	1	1	}	<	1	K)	Screeding in bathroom & utility (or x)
					1		<		ļ		J]	<		<	J	Screeding in 6" above FFL? (• or ×)